

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/GRB21005844/R1TF3E2-1
Date: 21/07/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : FBR9774Y **Insured Vehicle No :** SLM6013M
Date of Loss: 11/05/2021 Nature of Claim: TP Claim No: MFL2021D0002143

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR9774Y**
Make & Model: YAMAHA NMAX155, 155cc ABS CVT Engine No: G3L8E0310085
Reg. Date: 14/12/2020 (Man. Year: 2020) Chassis No: MH3SG5680LK054510
Colour: Black Odometer: 14624 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-13 Rear Tyre Size: 130/70-13
Front Left Side: IRC 4 mm Rear Left Side: IRC 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,013.70	2,223.70	3,790.00	63.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	610.00	370.00	240.00	39.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,623.70	2,593.70	4,030.00	60.84
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	6,623.70	2,050.00	4,573.70	69.05
+ GST 7.00/7.00% (S\$)	463.66	143.50	320.16	69.05
Nett Amount (S\$)	7,087.36	2,193.50	4,893.86	69.05

INSPECTION

Date of Assignment: 28/06/2021
Date Inspected: 17/05/2021 Inspected At: 61 Woodland Industrial Park E9 #01-14 E9
Estimated Period of Repair: 4.0 days
Premium
Repairer: GP Motoring Pte Ltd (HQ)

Adjuster: MOHD RASUL**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jul 2021)	
Parts:	N/A	YAMAHA NMAX155 155cc ABS CVT (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR9774Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Serviceable	650.00 FL	*- FL
2	1		*O/S SIDE MIRROR	Damaged	120.00 FL	*120.00 FL
3	1		*HANDLE-BAR	Serviceable	135.00 FL	*- FL
4	1		*SET HAND GRIP	Serviceable	95.00 FL	*- FL
5	1		*SET BRAKE LEVER	Damaged	80.00 FL	*80.00 FL
6	1		*FRONT O/S SIGNAL	Intact	95.00 FL	*- FL
7	1		*SET FOOTSTEP PANEL	Damaged	280.00 FL	*280.00 FL
8	1		*EXHAUST ASSY	Repair	780.00 FL	*- FL
9	1		*EXHAUST PROTECTOR	Damaged	68.00 FL	*68.00 FL
10	1		*REAR TAILLAMP	Damaged	285.00 FL	*285.00 FL
11	1		*REAR O/S FOOTREST	Damaged	70.00 FL	*70.00 FL
12	1		*AIR FILTER BOX COVER	Damaged	220.00 FL	*220.00 FL
13	1		*MAIN STAND	Intact	145.00 FL	*- FL
14	1		*REAR FENDER	Not Necessary	248.00 FL	*- FL
15	1		*REAR SPORT RIM	Repair	650.00 FL	*- FL
16	1		*REAR RIM BRACKET	Serviceable	322.00 FL	*- FL
17	1		*SET FAIRING COVER	Damaged	1,350.00 FL	*950.00 FL
18	1		*SET CRASH BAR	Damaged	380.00 FL	*220.00 FL
19	1		*SET NUMBER PLATE	Not Necessary	28.00 FS	*- FS
20	1		*REAR BOX BRACKET	Damaged	150.00 FS	*100.00 FS
21	1		*NMAX EMBLEM	Necessary	60.00 FS	*60.00 FS
22	1		*DELIVERY BAG	Serviceable	400.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,611.00	2,453.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	597.30	229.30
Total Parts (\$\$)	6,013.70	2,223.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE	New	50.00	40.00
2	TO CHECK ELECTRICAL SYSTEM,WIRE HARNESS AND FOCUS HEADLAMP	New	80.00	30.00
3	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS;RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT	New	480.00	300.00
Gross Labour Cost (\$\$)			610.00	370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >