

C L APPRAISER PTE LTD

24 Peshurst Place, Singapore 556440
Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783
Reg No: 201000228E

INVOICE

Mohamad Yusoff Bin Othman
C/o: GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Invoice No. : CL/210334

Ref No. : GP/05/2101/TP

Date : 17 June 2021

DESCRIPTION	AMOUNT
OUR SERVICE FEE CHARGES:	
<ul style="list-style-type: none">SURVEY INSPECTION FOR VEHICLE NO. <u>FBR 9774 Y</u>RESURVEY INSPECTIONDIGITAL PHOTOGRAPHS SERVICES (INCLUSIVE OF STORAGE AND SUBMISSION OF DIGITAL PHOTOGRAPHS)TRANSPORTATION	
GRAND TOTAL	S\$ 585.00

E & O. E

All cheque payment should be "Crossed" and made payable to " C L APPRAISER PTE LTD "

We shall be grateful if you could forward our payment at your early convenience.



CL Appraiser Pte Ltd



24 Peshurst Place, Singapore 556440

Email: clappraiser@yahoo.com Hp: 9068 8689 Fax: 6452 9783

Reg No: 201000228E

VEHICLE INSPECTION REPORT

To: Mohamad Yusoff Bin Othman
C/o: GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Date : 17 June 2021
Our ref : GP/05/2101/TP

Accident Date : 11 May 2021
Inspection Date : 18 May 2021
Repairer Name : GP Service Pte Ltd
284 Macpherson Road,
Singapore 348608

Type of Survey : Third Party

PARTICULARS OF VEHICLE

Registration No	: FBR 9774 Y	Year / Capacity	: 2020 / 155 cc
Make / Model	: Yamaha Nmax 155	Colour	: Black
Chassis No	: MH3SG5680LK054510	Mileage	: 14624
Engine No	: G3L8E0310085		

CONDITION OF TYRES

	Make	Size	Thread Balance	Rim
Front	: IRC	110/70 -13	5 mm	Sport
Rear	: IRC	130/70 -13	5 mm	Sport

GENERAL DESCRIPTION OF DAMAGE VEHICLE

The impact damages sustained on the vehicle at the time of inspection is on the n/s rear and o/s portion.
(Details refer to the photographs attached)

Enclosed number of photographs: **125** copies

REMARKS

This inspection was conducted entirely on a "**WITHOUT PREJUDICE**" basis and we have not given authorization and instruction to the repairer to proceed with the repair.

RECOMMENDATIONS

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a **Lump Sum of \$5,000.00** on a contractual basis.

Under normal circumstances, the repair period would be about 20 (Twenty) working days.

Vehicle Registration No.: FBR 9774 Y

Our Ref No.:

GP/05/2101/TP

Qty	Description	Conditions	Repairer's Estimate	Revised Amount
-----	-------------	------------	---------------------	----------------

SPARE PARTS - LIST ITEMS

1	Headlamp	Damage	\$ 650.00	\$ 650.00
1	O/s side mirror	Damage	\$ 120.00	\$ 120.00
1	Handle-bar	Damage	\$ 135.00	\$ 135.00
1	Hand grip (1 set)	Necessary	\$ 95.00	\$ 95.00
1	Brake lever (1 set)	Damage	\$ 80.00	\$ 80.00
1	Front o/s signal	Intact	\$ 95.00	
1	Footstep panel (1 set)	Damage	\$ 280.00	\$ 280.00
1	Exhaust assy	Damage	\$ 780.00	\$ 780.00
1	Exhaust protector	Damage	\$ 68.00	\$ 68.00
1	Rear taillamp	Damage	\$ 285.00	\$ 285.00
1	Rear o/s footrest	Damage	\$ 70.00	\$ 70.00
1	Air filter box cover	Damage	\$ 220.00	\$ 220.00
1	Main stand	Intact	\$ 145.00	
1	Rear fender	Damage	\$ 248.00	\$ 248.00
1	Rear sport rim	Damage	\$ 650.00	\$ 650.00
1	Rear rim bracket	Damage	\$ 322.00	\$ 322.00
1	Fairing cover (1 set)	Damage	\$ 1,350.00	\$ 1,350.00
1	Crash bar (1 set)	Damage	\$ 380.00	\$ 380.00
			\$ 5,973.00	\$ 5,733.00
			<i>Less 10%</i>	<i>\$ 597.30</i>
Total Cost - List Items			\$ 5,375.70	\$ 5,159.70

SPECIAL NETT ITEMS

1	Number plate (1 set)	Damage	\$ 28.00	\$ 28.00
1	Rear box bracket	Damage	\$ 150.00	\$ 150.00
1	"NMAX" emblem	Necessary	\$ 60.00	\$ 60.00
1	Delivery bag	Damage	\$ 400.00	\$ 400.00
Total Cost - Special Nett items			\$ 638.00	\$ 638.00

Total cost of parts
\$ 6,013.70 \$ 5,797.70

Vehicle Registration No.: FBR 9774 Y

Our Ref No.:

GP/05/2101/TP

S/No	Description	Repairer's Estimate	Revised Amount
	Total cost of parts c/f	\$ 6,013.70	\$ 5,797.70
	<u>LABOUR</u>		
1	To provide towing service.	\$ 50.00	\$ 50.00
2	To check electrical system, wire harness and focus headlamp.	\$ 80.00	\$ 50.00
3	To provide labour charges, workmanship to dismantle above damaged parts ; re-align body structure and damaged consistent to the accident.	\$ 480.00	\$ 400.00
	GRAND TOTAL	\$ 6,623.70	\$ 6,297.70

Vehicle Registration No.: FBR 9774 Y

Our Ref No.:

GP/05/2101/TP

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a **Lump Sum Repair Contract of : \$ 5,000.00**


By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged parts with used, reconditioned or new parts, or to repair it to a roadworthy condition.

Note: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage / item in this survey, kindly notified the company within seven (7) from the date hereof. Otherwise, the revised amount shall be deemed to be valid.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in other legal proceedings.

C L APPRAISER PTE LTD



Cheong K. H.
Automotive Appraiser

