

CV31 A/c 21007098 (Ag)

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMY2022M. Yr Regn: 2020 / Dec.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi Q3 C.C. 1395
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 10215 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZF38M1042416
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/65R17.
 R: 215/65R17.
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 01/07/21
 Survey held at Premian.
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TPAIG.

MV:

PV:

Nett:

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.P.C

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Insp (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0539/2021/TF
DATE : 29-Jun-21
WIP : 33072

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 01/07/2021
YOUR INSURED VEH NO : GBD 1979 D

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS. SEAH PEI LING, SINDEE
ADDRESS : 25 CANBERRA DRIVE
#06-52
SINGAPORE 768078
TELEPHONE : HP +65 90175662
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070175250
VEHICLE NO : **SMY 2022 M**
MODEL CODE : Q3 SPORTBACK 1.4 TFSI S
MODEL YEAR : 16/12/2020
ENGINE NO : CZD C18584
CHASSIS NO : WAUZZZF38M1042416
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jun-21
PLACE OF ACCIDENT : CTE BEFORE PIE CHANGI EXIT

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 2022 M (FRONTAL)

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY & FRONT PARKING AID	S/N \$ 480.00 ✓	
2	TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 2,400.00 500	
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS	\$ 3,900.00 1500	1100 Bonnet Bumper 400 Wheel Trim
SUB TOTAL LABOUR CHARGES		: \$ 6,780.00	<u>1500</u>

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 2022 M (REAR)

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	✓
3	TO RENEW REAR WINDSCREEN TO FACILLITATE REAR LID RENEWAL.	S/N \$	480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN. (BY OWNER)	S/N \$	190.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST ON REAR WINDSCREEN.	S/N \$	200.00 150.	
SUB TOTAL LABOUR CHARGES		:	\$ 1,710.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 2022 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DIMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,800.00	1000
7	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 4,100.00	1500 5500 1100 Lid Bumper 400 Arc Trim
8	TO REAPPLY PAINT COATING ON AFFECTED AREA. (BY S/N \$ OWNER)	\$ 180.00	✓ 1500
10	TO CARRY OUT DIAGNOSTIC CHECK.	\$ 192.00	✓
TOTAL LABOUR CHARGES (FRONT + REAR)		\$ 15,762.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2022 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FORNT BUMBER <i>Repair</i>	1	\$ 2,815.00	+	
2	FRONT BUMBER FIXING PARTS	1	\$ 414.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>3 new</i>	2	\$ 177.00	+	
4	FRONT BUMPER TRIM <i>Rehnd</i>	1	\$ 356.00	✓	
5	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	1	\$ 217.00	+	
6	FRONT MOUNTING SENSOR - LH / RH <i>new</i>	2	\$ 317.00	+	
7	FRONT BUMPER GRILLE COVER - LOWER CENTRE <i>new</i>	1	\$ 51.00	+	
8	FRONT BUMPER LOWER CLOSING ELEMENT <i>new</i>	1	\$ 190.00	+	
9	FRONT BUMPER SPOILER <i>new</i>	1	\$ 763.00	+	
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>3 new</i>	2	\$ 306.00	✓	
11	FRONT BUMPER AIR GUIDE TRIM - LH / RH <i>3 new</i>	2	\$ 328.00	+	
12	RADIATOR GRILLE <i>at</i>	1	\$ 1,928.00	✓	
13	RADIATOR GRILLE BRACKET <i>3 new</i>	1	\$ 41.00	+	
14	RADIATOR SECURING PLATE	1	\$ 33.00	+	
15	FRONT BUMPER CAMERA <i>3 new</i>	1	\$ 1,141.00	+	
16	RADIATOR GRILLE COVER	1	\$ 244.00	+	
17	FRONT STRIKER PLATE	1	\$ 244.00	✓	
18	FRONT PARKING AID SENSOR <i>3 new</i>	2	TBC	+	
19	FRONT PARKING AID SEAL SENSOR	4	\$ 14.00	+	
20	BONNET <i>Repair</i>	1	\$ 3,508.00	+	
SUB TOTAL SPARE PARTS		:	\$ 13,087.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2022 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	BONNET IMPACT PROTECTION - CENTER <i>Neu</i>	1	\$ 28.00	X
22	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	X
23	REAR BUMPER <i>Dented</i>	1	\$ 1,634.00	✓
24	REAR BUMPER SPOILER	1	\$ 459.00	✓
25	REAR BUMPER GRILLE - LH/RH <i>Neu</i>	2	\$ 304.00	X
26	REAR BUMPER PARKING AID SENSOR SUPPORT - RH <i>Neu</i>	1	\$ 25.00	X
27	REAR BUMPER ADAPTER - LH / RH	2	\$ 170.00	?
28	REAR BUMPER REINFORCEMENT BEAM	1	\$ 97.00	?
29	REAR BUMPER BRACKET	1	\$ 48.00	?
30	REAR BUMPER REFLECTOR - LH / RH <i>Neu</i>	2	\$ 82.00	X
31	REAR BOOT LID CONTROL UNIT <i>Neu</i>	1	\$ 411.00	X
32	REAR BUMPER AERIAL	1	\$ 71.00	?
33	REAR SHOCK ABSORBER	1	\$ 85.00	?
34	REAR BUMPER CARRIER	1	\$ 651.00	?
35	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 58.00	?
36	REAR BUMPER GUIDE SECTION - LH / RH <i>Neu</i>	2	\$ 126.00	X
37	REAR BUMPER PARKING AID <i>Neu</i>	2	TBC	X
38	REAR BUMPER PARKING AID SEAL RING <i>Ne Neu</i>	4	\$ 14.00	X
39	REAR BOOT LID <i>Dented</i>	1	\$ 3,470.00	✓
40	REAR BOOT LID ADHESIVE <i>Neu</i>	1	\$ 19.00	✓
SUB TOTAL SPARE PARTS		:	\$ 7,960.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2022 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	SELF LOCKING NUT - M6 ?	4 \$	16.00	✓
42	REAR BOOTLID HINGE - LH / RH	2 \$	295.00	+
43	REAR BOOTLID LOCK	1 \$	241.00	+
44	REAR BOOTLID LOCK COVER	1 \$	13.00	+
45	REAR LID STRIKER PLATE	1 \$	66.00	+
46	REAR LID GASKET ?	1 \$	205.00	✓
47	REAR LID LOCK ACTUATOR	1 \$	1,389.00	+
48	AUDI EMBLEM	1 \$	138.00	✓
49	Q3 EMBLEM	1 \$	99.00	✓
50	REAR WINDOW	1 \$	958.00	✓
51	PRIMER	1 \$	20.00	✓
52	REAR WINDSCREEN SPOILER - LH/ RH	2 \$	422.00	✓
53	INNER REAR TAIL LIGHT - LH / RH	2 \$	1,852.00	926 .
54	REAR TAIL LIGHT TRIM - LH / RH	2 \$	60.00	+
55	REAR LICENCE PLATE LIGHT	2 \$	101.00	+
56	REAR WHEEL ARCH TRIM - LH / RH	2 \$	1,072.00	✓
57	FRONT WHEEL ARCH TRIM - LH / RH	2 \$	1,072.00	✓
58	FRONT NO PLATE	S/N \$	60.00	✓
59	RAER NO PLATE	S/N \$	60.00	✓
60	REAR WINDSCREEN SEALANT	S/N \$	200.00	✓
61	SUNDRIES ?	3 \$	350.00	✓
TOTAL SPARE PARTS			\$ 29,736.00	
TOTAL LABOUR CHARGES			\$ 15,762.00	
GRAND TOTAL			\$ 45,498.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Li*
SURVEYED DATE : *21/07/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 00 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

JERGA DETAILS

61 Woodlands Industrial Park E9, E9 Premium, #01-02 Singapore 757047

Customer Details

Name:	
Mobile Number:	9657 4320
Car Brand and Model:	Audi Q3 Sportback
Car Plate Number:	SMY 2022M
Car Colour:	Black

OFFICIAL USE ONLY

Date of Application:	Quotation
----------------------	-----------

Package:

1. Paint Protection Coating ☐ a. CAMUI CC4 ☐ b. CAMUI Golden Expresser ☐ c. ULTIMEA Self Heal Coating	2. Solar Film (ULTIMEA) ☐ Platinum99 ☐ Transitional ☐ a. Full Car ☐ b. Half Car ☐ c. Others Remarks: _____
3. Paint Protection Film (ULTIMEA) ☐ a. Full Car ☐ b. Full Front ☐ c. 4 Doors ☐ d. Others Remarks: _____	4. Others ☒ a. Remarks: <u>Rear bumper</u> <u>Boot lid</u> <u>Front bumper</u> <u>Bonnet</u>

Amount Paid (Nets / Cash / Credit Card / Bank Transfer)

\$180/-

JERGA PTE. LTD.
UEN REG NO.
201736810K

JERGA DETAILS

61 Woodlands Industrial Park E9, E9 Premium, #01-02 Singapore 757047

Customer Details

Name:

Lim Eugene

Mobile Number:

9657 43 20

Car Brand and Model:

Audi Q3 Sportback

Car Plate Number:

SMY 2022 M

Car Colour:

Black

OFFICIAL USE ONLY

Date of Application:

05/01/2021

Package:

1. Paint Protection Coating

- ☐ a. CAMUI CC4
☐ b. CAMUI Golden Expresser
☒ c. ULTIMEA Self Heal Coating

2. Solar Film (ULTIMEA)

- ☐ Platinum99 ☐ Transitional
☐ a. Full Car
☐ b. Half Car
☐ c. Others

Remarks: _____

3. Paint Protection Film (ULTIMEA)

- ☐ a. Full Car
☐ b. Full Front
☐ c. 4 Doors
☐ d. Others

Remarks: _____

4. Others

- ☐ a. Remarks: _____

Amount Paid (Net) / Cash / Credit Card / Bank Transfer)

\$4951



Quotation No: AT2743

Customer: Eugene

Mobile: 96574320

Vehicle Model: Audi Q3 Sportback

Vehicle No Plate: SMW 8954 U

Film Installed: Titanium Series (AT TI)

Type of Installation: Rear Windscreen

LTA Regulation Type: Approved

Price: \$190

Contact Person: Eugene Saw

Mobile: 97488788

Office: 67425137

Workshop: 39 Ubi Rd 1 #01-05, World Publication Building Spore 408695

Email: eugene@absolutetint.com.sg

Website: www.absolutetint.com.sg

ROC: 200911198C

Facebook Page: www.facebook.com/absolutetintworkz

Pls Like and Share us on Facebook@our Absolute Tint Facebook Page!!



Terms and Conditions:

.All Goods and Services once Sold or Installed are Non Refundable

.Full Payment Must be made upon completion of all Jobs

.Please make out all cheques payable to (Absolute Tint Workz Pte Ltd)



Invoice No: AT2269

Customer:

Mobile: 96574320

Vehicle Model: Audi Q3 Sportback

Vehicle No Plate: SMW 8954 U

Film Installed: Titanium Series (AT TI)

Type of Installation: Full Car

LTA Regulation Type: Approved

Date of Installation: 21/12/2020

Warranty Period from Date of Issue: 10yrs

Warranty Card No: 1642

Price: \$450

Contact Person: Eugene Saw

Mobile: 97488788

Office: 67425137

Workshop: 39 Ubi Rd 1 #01-05, World Publication Building Spore 408695

Email: eugene@absolutetint.com.sg

Website: www.absolutetint.com.sg

ROC: 200911198C

Facebook Page: www.facebook.com/absolutetintworkz

Pls Like and Share us on Facebook@our Absolute Tint Facebook Page!!



Terms and Conditions:

.All Goods and Services once Sold or Installed are Non Refundable

.Full Payment Must be made upon completion of all Jobs

.Please make out all cheques payable to (Absolute Tint Workz Pte Ltd)