



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0539/2021/TF
DATE : 29-Jun-21
WIP : 33072

Estimate
\$22777.04 12 Days

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 01/07/2021
YOUR INSURED VEH NO : GBD 1979 D

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS. SEAH PEI LING, SINDEE
ADDRESS : 25 CANBERRA DRIVE
#06-52
SINGAPORE 768078
TELEPHONE : HP +65 90175662
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070175250
VEHICLE NO : SMY 2022 M
MODEL CODE : Q3 SPORTBACK 1.4 TFSI S
MODEL YEAR : 16/12/2020
ENGINE NO : CZD C18584
CHASSIS NO : WAUZZZF38M1042416
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Jun-21
PLACE OF ACCIDENT : CTE BEFORE PIE CHANGI EXIT



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 2022 M (FRONTAL)

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY & FRONT PARKING AID	S/N \$ 480.00 ✓	
2	TO DISMANTLE AND RENEW FRONT BUMPER AND BONNET. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 2,400.00 500	
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BONNET AND BOTH FRONT WHEEL ARCH TRIMS	\$ 3,900.00 1500	1100 Bonnet Bumper 400 Wheel Trim
SUB TOTAL LABOUR CHARGES		: \$ <u>6,780.00</u>	<u>1500</u>

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 2022 M (REAR)

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHTS AND REAR WIPER ASSY.	S/N \$	480.00	✓
3	TO RENEW REAR WINDSCREEN TO FACILLITATE REAR LID RENEWAL.	S/N \$	480.00	✓
4	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN. (BY OWNER)	S/N \$	190.00	✓
5	TO CARRY OUT WATER SEEPAGE TEST ON REAR WINDSCREEN.	S/N \$	200.00 * 150	
SUB TOTAL LABOUR CHARGES		:	\$ 1,710.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED REAR LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 2022 M

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DIMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 2,800.00	1000
7	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 4,100.00	Lid Bumper 400 Arc Trim
8	TO REAPPLY PAINT COATING ON AFFECTED AREA. (BY S/N OWNER)	\$ 180.00	1500
10	TO CARRY OUT DIAGNOSTIC CHECK.	\$ 192.00	
TOTAL LABOUR CHARGES (FRONT + REAR)		\$ 15,762.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2022 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FORNT BUMBER <i>Repair</i>	1	\$ 2,815.00	*
2	FRONT BUMBER FIXING PARTS	1	\$ 414.00	*
3	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>3 new</i>	2	\$ 177.00	*
4	FRONT BUMPER TRIM <i>Rehnd</i>	1	\$ 356.00	✓ 284.40
5	FRONT BUMPER GRILLE - LOWER CENTRE <i>new</i>	1	\$ 217.00	*
6	FRONT MOUNTING SENSOR - LH / RH <i>new</i>	2	\$ 317.00	*
7	FRONT BUMPER GRILLE COVER - LOWER CENTRE <i>new</i>	1	\$ 51.00	*
8	FRONT BUMPER LOWER CLOSING ELEMENT <i>new</i>	1	\$ 190.00	*
9	FRONT BUMPER SPOILER <i>new</i>	1	\$ 763.00	*
10	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>3 new</i>	2	\$ 306.00	*
11	FRONT BUMPER AIR GUIDE TRIM - LH / RH <i>3 new</i>	2	\$ 328.00	*
12	RADIATOR GRILLE <i>cut</i>	1	\$ 1,928.00	✓ 1542.40
13	RADIATOR GRILLE BRACKET <i>3 new</i>	1	\$ 41.00	+
14	RADIATOR SECURING PLATE	1	\$ 33.00	+
15	FRONT BUMPER CAMERA <i>new</i>	1	\$ 1,141.00	*
16	RADIATOR GRILLE COVER <i>cut</i>	1	\$ 244.00	✓ 194.80
17	FRONT STRIKER PLATE <i>cracked</i>	1	\$ 244.00	✓ 194.80
18	FRONT PARKING AID SENSOR <i>3 new</i>	2	TBC	+
19	FRONT PARKING AID SEAL SENSOR	4	\$ 14.00	+
20	BONNET <i>Repair</i>	1	\$ 3,508.00	*
SUB TOTAL SPARE PARTS		:	\$ 13,087.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2022 M

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	BONNET IMPACT PROTECTION - CENTER <i>3 items</i>	1	\$ 28.00	X	
22	HEADLIGHT MOUNTING - LH / RH	2	\$ 236.00	X	
23	REAR BUMPER <i>3 items</i>	1	\$ 1,634.00	✓	1307.20
24	REAR BUMPER SPOILER	1	\$ 459.00	✓	367.20
25	REAR BUMPER GRILLE - LH/RH <i>2 items</i>	2	\$ 304.00	X	
26	REAR BUMPER PARKING AID SENSOR SUPPORT - RH <i>1 item</i>	1	\$ 25.00	X	
27	REAR BUMPER ADAPTER - LH / RH <i>2 items</i>	2	\$ 170.00	X	
28	REAR BUMPER REINFORCEMENT BEAM	1	\$ 97.00	X	
29	REAR BUMPER BRACKET <i>1 item</i>	1	\$ 48.00	X	
30	REAR BUMPER REFLECTOR - LH / RH <i>2 items</i>	2	\$ 82.00	X	
31	REAR BOOT LID CONTROL UNIT <i>1 item</i>	1	\$ 411.00	X	
32	REAR BUMPER AERIAL <i>1 item</i>	1	\$ 71.00	X	
33	REAR SHOCK ABSORBER <i>2 items</i>	1	\$ 85.00	✓	67.92
34	REAR BUMPER CARRIER <i>2 items</i>	1	\$ 651.00	✓	520.40
35	REAR BUMPER HOLDING STRAP - LH / RH <i>2 items</i>	2	\$ 58.00	X	
36	REAR BUMPER GUIDE SECTION - LH / RH <i>2 items</i>	2	\$ 126.00	X	
37	REAR BUMPER PARKING AID <i>2 items</i>	2	TBC	X	
38	REAR BUMPER PARKING AID SEAL RING <i>4 items</i>	4	\$ 14.00	X	
39	REAR BOOT LID <i>Dented</i>	1	\$ 3,470.00	✓	2776.00
40	REAR BOOT LID ADHESIVE <i>1 item</i>	1	\$ 19.00	✓	14.88
SUB TOTAL SPARE PARTS		:	\$ 7,960.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 2022 M

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	SELF LOCKING NUT - M6 <i>Not rec</i>	4	\$ 16.00	<i>+</i>
42	REAR BOOTLID HINGE - LH / RH	2	\$ 295.00	<i>+</i>
43	REAR BOOTLID LOCK	1	\$ 241.00	<i>+</i>
44	REAR BOOTLID LOCK COVER	1	\$ 13.00	<i>+</i>
45	REAR LID STRIKER PLATE	1	\$ 66.00	<i>+</i>
46	REAR LID GASKET <i>Not rec</i>	1	\$ 205.00	<i>+</i>
47	REAR LID LOCK ACTUATOR <i>Damaged.</i>	1	\$ 1,389.00	<i>+</i> 1111.20
48	AUDI EMBLEM <i>Not rec</i>	1	\$ 138.00	<i>✓</i> 110.00
49	Q3 EMBLEM <i>Not rec</i>	1	\$ 99.00	<i>✓</i> 79.04
50	REAR WINDOW <i>Not rec</i>	1	\$ 958.00	<i>✓</i> 766.00
51	PRIMER <i>Not rec</i>	1	\$ 20.00	<i>✓</i> 15.76
52	REAR WINDSCREEN SPOILER - LH/ RH <i>Not rec</i>	2	\$ 422.00	<i>✓</i> 337.60
53	INNER REAR TAIL LIGHT - LH / RH <i>LH at</i>	2	\$ 1,852.00	<i>✓</i> 926 740.40
54	REAR TAIL LIGHT TRIM - LH / RH <i>Not rec</i>	2	\$ 60.00	<i>+</i>
55	REAR LICENCE PLATE LIGHT <i>1 piece damaged.</i>	2	\$ 101.00	<i>+</i> 50.50 40.16
56	REAR WHEEL ARCH TRIM - LH / RH <i>Not rec</i>	2	\$ 1,072.00	<i>✓</i> 857.60
57	FRONT WHEEL ARCH TRIM - LH / RH <i>Not rec</i>	2	\$ 1,072.00	<i>✓</i> 857.60
58	FRONT NO PLATE <i>Not rec</i>	S/N	\$ 60.00	<i>✓</i>
59	REAR NO PLATE <i>Not rec Dented</i>	S/N	\$ 60.00	<i>✓</i>
60	REAR WINDSCREEN SEALANT <i>Not rec</i>	S/N	\$ 200.00	<i>✓</i>
61	SUNDRIES <i>Not rec</i>	3	\$ 350.00	<i>✓</i> 18.64
TOTAL SPARE PARTS		:	\$ 29,736.00	
TOTAL LABOUR CHARGES		:	\$ 15,762.00	
GRAND TOTAL		:	\$ 45,498.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian L*
 SURVEYED DATE : *21/07/21*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *not Authorised , 00 Pays 12 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT