

12/12/2020

REF: CS3/MSG20014293/R1vf3-1

Special Instruction:

ASS. REC. BY:

SURVY BY: RASUL

ASSIGNMENT (Office)

Merimen

From (Person): FIEVEL FOO WEN YAO of MSIG

Date/Time: 28/6/2021 5:12 PM

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMP 3879Z

Insured: SJF 7599T

at Workshop m/s KOK WANG CAR GROOMING

Tel: 9183 9633

of NO. 1 SOON LEE STREET# 06-40

Policy No: 29083623QMX

Claim No: 632277

Sum Insured:

Excess:

D.O.A. 19/12/2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 3.54PM@22/12/20

Person Contacted: AH LIANG

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (X) Estimate
	Repairer agreed to survey on 23/12/2020
	SMP 3879Z-X
	SJF 7599T-NA/INC09004995/w1 DOA :05/03/2009
24/12/20	Submit PRS, repair range \$3,000-\$4,000 (7 days)