

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9970A**AAD2106-***Not Authorised**Recovery B4 painting*

8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 JUN 2021**SHD9970A**

JTDKB3FU003091526

TOYOTA

PRIUS GEN 4

24/06/2021

CHINA

24/09/2020

PART

- 1 COVER, FRONT BUMPER
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 LINER, FRONT FENDER, LH

| LIST | |
|------|--------------|
| \$ | Bn/um 521.00 |
| \$ | R 716.60 |
| \$ | R 246.10 |
| \$ | SL 132.70 |
| \$ | SL 80.20 |
| \$ | SL 82.30 |
| \$ | SL 47.50 |
| \$ | SL 59.30 |
| \$ | SL 59.30 |
| \$ | SL 422.50 |
| \$ | SL 178.60 |
| \$ | um 210.30 |

TOTAL \$ 2,756.40**25% \$ 689.10****\$ 2,067.30****Special Nett**

- 1 BUMPER CLIP FRT
- 1SET FENDER LINER CLIP
- 1SET FRNT BUMPER RETAINER CLIP

| | |
|----|----------|
| \$ | nn 95.00 |
| \$ | nn 60.00 |
| \$ | nn 85.00 |

TOTAL \$ 240.00**TOTAL PARTS \$ 2,307.30****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00

Trans-cab Auto Services Pte Ltd

AAD2106-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9970A

| | | | |
|---|----|-----------|------|
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$ | nn 380.00 | X |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 2,200.00 | 400/ |
| To transfer of rear end panel fittings, attachment and perform water seepage test. | \$ | nn 380.00 | X |
| To transfer of Tailgate fittings, attachments and perform water seepage test. | \$ | 4 180.00 | X |
| To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair. | \$ | 4 480.00 | X |
| TOTAL \$ 10,210.00 | | | |
| To transfer of Fender fittings, attachments and perform water seepage test. | \$ | 4 480.00 | X |
| To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas. | \$ | 4 380.00 | X |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair. | \$ | 4 380.00 | X |
| To check steering geometry and computer wheel alignment | \$ | 4 220.00 | X |
| To Rust-Proofing and apply undercoat Of The Affected Areas. | \$ | 250.00 | 30/ |
| Towing Fees | \$ | 4 150.00 | X |
| Putty And Spray Painting Of The Affected Portion. | \$ | 2,200.00 | 440/ |
| To reinstall rear bumper parking sensor. | \$ | 4 170.00 | X |
| To Check Electrical Lighting Concerned. | \$ | 170.00 | 10/ |

Trans-cab Auto Services Pte Ltd

AAD2106-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9970A

To transfer of luggage floor panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of tire, rim and on wheel balancing.

\$ 220.00 X

To replace, refix and top up coolant for radiator

\$ 170.00 X

To lift-up / out engine with gear box and refit.

\$ 440.00 X

To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.

\$ 380.00 X

To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.

\$ 380.00 X

TOTAL \$ 10,290.00

Over All Total \$ 12,597.30

(PART-BY-PART) Repair Days

25 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: