

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9970A**AAD2106-***Not Authored**Recovery B4 painting*

8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 JUN 2021

SHD9970A

JTDKB3FU003091526

TOYOTA

PRIUS GEN 4

24/06/2021

CHINA

24/09/2020

PART

- 1 COVER, FRONT BUMPER
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, RH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 LINER, FRONT FENDER, LH

*For LIT fender**1st bumper side furnish**CRT 93.60***LIST**

\$	<i>Bn/um</i>	521.00	✓
\$	<i>R</i>	716.60	}
\$	<i>R</i>	246.10	
\$	<i>Sh</i>	132.70	
\$	<i>Sh</i>	80.20	
\$	<i>Sh</i>	82.30	
\$	<i>Sh</i>	47.50	
\$	<i>Sh</i>	59.30	
\$	<i>Sh</i>	59.30	}
\$	<i>Sh</i>	422.50	
\$	<i>Sh</i>	178.60	}
\$	<i>um</i>	210.30	

TOTAL \$ 2,756.40**25% \$ 689.10****\$ 2,067.30****Special Nett**

- 1 BUMPER CLIP FRT
- 1SET FENDER LINER CLIP
- 1SET FRNT BUMPER RETAINER CLIP

\$	<i>um</i>	95.00	<i>505m</i>
\$	<i>um</i>	60.00	✓
\$	<i>um</i>	85.00	X

TOTAL \$ 240.00**TOTAL PARTS \$ 2,307.30****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To
Facilitate Bodywork Repair.

\$ *um* 300.00 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2106-**SHD9970A**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 *400%*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *X*

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *h* 180.00 *X*

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.

\$ *h* 480.00 *X*

To transfer of Fender fittings, attachments and perform water seepage test.

\$ *h* 480.00 *X*

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ *h* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *h* 380.00 *X*

To check steering geometry and computer wheel alignment

\$ *h* 220.00 *X*

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 *30%*

Towing Fees

\$ *h* 150.00 *X*

Putty And Spray Painting Of The Affected Portion.

\$ 2,200.00 *440%*

To reinstall rear bumper parking sensor.

\$ *h* 170.00 *X*

To Check Electrical Lighting Concerned.

\$ 170.00 *10%*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9970A**AAD2106-**

To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i>	220.00	X
To replace, refix and top up coolant for radiator	\$	<i>4</i>	170.00	X
To lift-up / out engine with gear box and refit.	\$	<i>4</i>	440.00	X
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	<i>4</i>	380.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>4</i>	380.00	X
TOTAL	\$		10,290.00	
Over All Total	\$		12,597.30	

(PART-BY-PART) Repair Days***25 DAYS******2 days*****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: