

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0534/2021/KS
DATE : 28-Jun-21
WIP : 32951

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

5 days - ok - Johnny Boo

23-Jul-21

OWNER'S NAME : MS MAH SOOK FUN RUTH AILEEN
ADDRESS : 167 LOYANG RISE
SINGAPORE 507434
TELEPHONE : HP +65 98629363
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800089458-02
VEHICLE NO : **SBV 4188 B**
MODEL CODE : A5 SPORTBACK 2.0 TFSI S TRONIC
MODEL YEAR : 27/7/2018
ENGINE NO : CVK 064960
CHASSIS NO : WAUZZZF5XJA116500
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Jun-21
PLACE OF ACCIDENT : TAMPINES AVENUE 7 TOWARDS AVENUE 2

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SBV 4188 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS , HORNS , OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER , RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00	\$ 1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,500.00	\$ 1,100.00
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$ 280.00
6	ADDED LABOUR - SEE ATTACHED	\$	1,480.00	\$ 830.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 7,732.00	\$ 4,132.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 4188 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,251.00	\$	1,800.80
2	FRONT BUMPER FIXING PARTS	1	\$ 407.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 228.00		
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 63.00		
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 474.00		
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 36.00	\$	28.72
8	FRONT BUMPER TOP COVER	1	\$ 127.00		
9	CAUTION STICKER	1	\$ 14.00		
10	AIR-CONDITIONER STICKER	1	\$ 8.00		
11	FRONT FENDER - RH	1	\$ 1,060.00	\$	848.00
12	FRONT FENDER ATTACHMENT PARTS	1	\$ 53.00		
13	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 74.00	\$	59.04
14	FRONT FENDER BRACKET - RH	1	\$ 35.00	\$	27.92
15	POP RIVERT	5	\$ 17.00	\$	15.84
16	FRONT FENDER BRACE- RH	1	\$ 118.00	\$	94.40
17	FRONT FENDER BRACKET - RH	1	\$ 49.00		
18	FRONT FENDER BRACKET - RH	1	\$ 35.00		
19	FRONT FENDER TRIM - RH	1	\$ 164.00	\$	130.80
20	FRONT WHEEL HOUSING LINER - RH	1	\$ 275.00	\$	219.60
SUB TOTAL SPARE PARTS		:	\$ 5,559.00	\$	3,225.12

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 4188 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 3,225.12
21	FRONT WHEEL SPOILER - RH	1	\$ 73.00	\$ 58.40
22	FRONT WHEEL SPOILER TRIM - RH	1	\$ 36.00	
23	FRONT FENDER FLEDGE COVER - RH	1	\$ 16.00	
24	LED HEADLIGHT - RH	1	\$ 7,902.00	\$ 6,321.60
25	LIFT CYLINDER - RH	1	\$ 198.00	
26	FRONT ALUMINIUM RIM - RH	1	\$ 1,690.00	
27	dded parts - see attached		\$ 164.00	\$ 130.80
28	SUNDRIES		\$ 300.00	\$ 2.64
TOTAL SPARE PARTS			\$ 15,938.00	\$ 9,738.56
TOTAL LABOUR CHARGES			\$ 7,732.00	\$ 4,132.00
GRAND TOTAL			\$ 23,670.00	\$ 13,870.56

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL/22/07/21



Supplementary Estimate

GST Reg No. 19-9902271-W

Get Reg No: 15 000271 W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0534/2021/KS 1-Jul-21 KEE SIANG 1 OF 1 SBV 4188 B A5 SPORTBACK 2.0 TFSI S TRONIC	
Quantity	Description	Unit Price	Amount	
<u>Labours</u>				
1	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM TO REMOVE AND REISNTALL RHS WING MIRROR ASSY TO FACILATE RESPRAY OF RHS FRONT DOOR. S/N	\$ 280.00	\$	280.00
2	TO RESPRAY RHS FRONT DOOR	\$ 1,200.00	\$	550.00
<u>Parts</u>				
1	FRONT RHS DOOR CHROME TRIM	\$ 164.00	\$	130.80
	GRAND TOTAL	\$ 1,644.00	\$	960.80

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT