



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0534/2021/KS
DATE : 28-Jun-21
WIP : 32951

Veron
\$15,222.56
5Days

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/6/2021

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS MAH SOOK FUN RUTH AILEEN
ADDRESS : 167 LOYANG RISE
SINGAPORE 507434
TELEPHONE : HP +65 98629363
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800089458-02
VEHICLE NO : SBV 4188 B
MODEL CODE : AS SPORTBACK 2.0 TFSI S TRONIC
MODEL YEAR : 27/7/2018
ENGINE NO : CVK 064960
CHASSIS NO : WAUZZZF5XJA116500
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Jun-21
PLACE OF ACCIDENT : TAMPINES AVENUE 7 TOWARDS AVENUE 2



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE 5BV 4188 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00 250	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,400.00 1000	✓
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,500.00 1100	✓
5	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	✓ ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓ ✓
TOTAL LABOUR CHARGES		:	\$	<u>6,252.00</u>



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6266 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 4188 B

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS		
1	FRONT BUMPER <i>Distorted</i>	1	\$	2,251.00	✓	1800.80
2	FRONT BUMPER FIXING PARTS <i>face</i>	1	\$	407.00	X	
3	FRONT BUMPER SECURING STRIP <i>face</i>	2	\$	71.00	X	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>face</i>	1	\$	228.00	X	
5	FRONT BUMPER AIR GUIDE - RH	1	\$	63.00	X	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$	474.00	X	
7	FRONT BUMPER GUIDE SECTION - RH <i>damaged</i>	1	\$	36.00	✓	28.72
8	FRONT BUMPER TOP COVER <i>face</i>	1	\$	127.00	X	
9	CAUTION STICKER	1	\$	14.00	+	
10	AIR-CONDITIONER STICKER	1	\$	8.00	X	
11	FRONT FENDER - RH <i>Distorted</i>	1	\$	1,060.00	✓	848
12	FRONT FENDER ATTACHMENT PARTS <i>face</i>	1	\$	53.00	X	
13	FRONT FENDER CLOSING ELEMENT - RH <i>? damaged</i>	1	\$	74.00	✓	59.04
14	FRONT FENDER BRACKET - RH <i>Damaged</i>	1	\$	35.00	✓	27.92
15	POP RIVET <i>face</i>	5	\$	17.00	✓	15.84
16	FRONT FENDER BRACE - RH <i>? bent</i>	1	\$	118.00	✓	94.40
17	FRONT FENDER BRACKET - RH <i>face</i>	1	\$	49.00	X	
18	FRONT FENDER BRACKET - RH	1	\$	35.00	X	
19	FRONT FENDER TRIM - RH <i>face</i>	1	\$	164.00	✓	130.80
20	FRONT WHEEL HOUSING LINER - RH <i>torn</i>	1	\$	275.00	✓	219.60
SUB TOTAL SPARE PARTS			:	\$	5,559.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6356 2323 FAX: 6843 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SBV 4188 B

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT WHEEL SPOILER - RH <i>could</i>	1	\$ 73.00	✓ 58.40
22	FRONT WHEEL SPOILER TRIM - RH <i>NE new</i>	1	\$ 36.00	? X
23	FRONT FENDER FLEDGE COVER - RH <i>NE new</i>	1	\$ 16.00	? X
24	LED HEADLIGHT - RH <i>could</i>	1	\$ 7,902.00	✓ 6321.60
25	LIFT CYLINDER - RH <i>new</i>	1	\$ 198.00	✓
26	FRONT ALUMINIUM RIM - RH <i>W X R</i>	1	\$ 1,690.00	✓ 1352.00
27	SUNDRIES <i>NE new</i> nec		\$ 300.00	? X 2.64
TOTAL SPARE PARTS		:	\$ 15,774.00	
TOTAL LABOUR CHARGES		:	\$ 6,252.00	
GRAND TOTAL		:	\$ 22,026.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

Adrian Lj

SURVEYED DATE :

28/06/21.

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

x1e Authorised, 05 days
H.S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT