

(08/11/13) wef
ASS. REC. BY: Marcus

REF: CS/AG121007126/Urf3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SMA8148X
at Workshop m/s: 200m
of: _____
Insured: SMF 4640R
Policy No.: _____
Claims No.: C10010663/KY
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.
Bal. or Market Value: 140k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____
Vehicle: IN / OUT
839D

Veh No: SMA8148X Yr Regn: 11/11/14
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA/
Make: Porsche Macan S c.c 2997
Colour: Black / Blue A/C: Insured / Std / NI / NA
Sp. Reading 136020 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WP1222957FLB60694
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 265/45R20 P.R
R: 295/40R20 MIC
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front: _____ Rear: _____
R/Bal. 3 mm R/Bal. 7 mm
L/Bal. 3 mm L/Bal. 7 mm
D.O.A. 26/6/21 D.O.I. 29/6/21
Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
The U/C / Chassis frame / Body Structure affected due to collision.

30/7/21 wrap sticker LTA \$90187
Dep 28
cont. met d/s \$9000 with E.I. (Red 19,488.47,68%)

Date/Time, File Pass to? : Preli. Report
1) : Final Report
Date/Time, File Return to?
2) 30/7/21-Typist
Report Format : TP
Lump Sum / ~~IBL~~ : (\$ 9000)
Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)
Days Of Repair: 5
Resurvey No. of Trip: 2
Survey Fee: _____
Transportation: _____
_____) S + RS, SI
) Photos
) Others
) _____
TOTAL

Not Authorized
 29/6/21
 4/5 \$9000
 5 days

* submit to insurance.



ZOOM AUTOWERKS PTE LTD
 130 Bedok Reservoir Road, Eunos Spring
 #08-1339 Singapore 470130
 Tel: 9450 7920
 zoomautowerks@gmail.com

4/5 \$9000

Car Number: SMA8148X
 Model : Porsche Macan
 Damaged Area: (Rear Portion)
 Repairer Estimation Cost of Repair :
 Supplementary may be included during the cost of repair :

Parts / Material :

1	Rear Bumper <i>assy</i>	<i>DD/De</i>	\$	1,786.50	/
2	Rear Bumper Centre <i>retainer</i>	<i>ena</i>	\$	265.00	/
3	Rear Bumper Side Mount @ SGD 154.00	<i>na</i>	\$	308.00	X
4	Rear Bumper Bracket @ SGD 32.00	<i>na</i>	\$	64.00	X
5	Rear Bumper <i>lower garnish</i>	<i>de</i>	\$	145.80	/
6	Rear Bumper Damping Parts @ SGD 53.00	<i>na</i>	\$	106.00	X
7	Rear Bumper Reinforcement	<i>berf</i>	\$	586.00	/
8	Rear Bumper Retaining Clip	<i>na</i>	\$	10.80	/
9	Expansion Rivet	<i>na</i>	\$	9.80	/
10	Expansion Nut	<i>na</i>	\$	11.60	/
11	Reverse Sensor @ SGD 245.00	<i>sc</i>	\$	980.00	X
12	Reverse Sensor Bracket (Set)	<i>na</i>	\$	96.00	X
13	Rear Bumper Clips	<i>na</i>	\$	60.00	/
14	Rear Lid	<i>DD/Berf</i>	\$	3,762.40	/
15	Rear Lid <i>moulding</i>	<i>na</i>	\$	397.10	/
16	Rear Lid Emblem (PORSCHE)	<i>na</i>	\$	226.80	/
17	Rear Lid Emblem (MACAN)	<i>na</i>	\$	156.30	/
18	Rear Lid Lock	<i>sc</i>	\$	737.30	X
19	Rear Taillamps @ SGD 964.50	<i>na</i>	\$	1,929.00	X
20	Rear End Panel	<i>na</i>	\$	1,181.30	X
21	Rear End Panel Top Garnish	<i>na</i>	\$	538.70	X
22	Rear End Panel Top Garnish Clips	<i>na</i>	\$	60.00	X
23	Centre Muffler	<i>na</i>	\$	2,504.80	X
24	Rear Muffler RH	<i>na</i>	\$	2,781.50	X
25	Rear Muffler LH	<i>na</i>	\$	2,781.50	X
26	Rear Tailpipe End	<i>sc</i>	\$	502.40	X
27	Rear Exhaust Heat Shield	<i>na</i>	\$	1,193.70	X
28	Rear Exhaust Mounting @ SGD 98.00	<i>na</i>	\$	196.00	X
			Parts :	\$ 23,378.30	
			Less Parts 10% :	\$ 2,337.83	
			Total Parts :	\$ 21,040.47	

Special Net Items :

Rear End Panel Sealant	<i>na</i>	\$	80.00	<i>50</i>
Rear Exhaust Sealant	<i>na</i>	\$	80.00	X
Rear <i>licence plate</i>	<i>sc</i>	\$	48.00	<i>40</i>
Rear Bumper Lower Diffuser (Accessories)	<i>na</i>	\$	1,850.00	<i>1400</i>
Rear Bumper Lower Difusser Lamp Set (Accessories)	<i>na</i>	\$	520.00	X
<i>1 set Rear wrap sticker</i>	<i>800 s/n</i>	\$	2,578.00	<i>na 600 s/n</i>
			Total S/N Parts :	\$ 2,578.00

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$	1,400.00	<i>800</i>
To Putty, Spray Paint on Affected Accident Areas	\$	1,400.00	<i>850</i>
To Check & Re-Connect all electrical wiring	\$	50.00	<i>20</i>
To Remove & Install Rear Bootlid Components Trim & Garnish	\$	150.00	<i>80</i>
To Remove & Install Rear Fenders Trim, Garnish, Spare Tyre Compartment	\$	150.00	<i>100</i>
To Re-position & Align Reverse Sensor	\$	120.00	<i>50</i>
To Re-programme & Re-set Diagnostics	\$	450.00	<i>100</i>

To Conduct Water Leakage Test
To Rust Proof Affected Areas

na
neu

	\$	150.00	X
	\$	200.00	60
Total Labour :	\$	<u>4,070.00</u>	

TOTAL PARTS :	\$	21,040.47	
TOTAL SPECIAL NET ITEM :	\$	2,578.00	
TOTAL LABOUR :	\$	<u>4,070.00</u>	
TOTAL REPAIR COST :	\$	<u>27,688.47</u>	28,488.47

DATE OF SURVEY / INSPECTED:
RECOMMENDED PART BY PART / LUMP SUM :
RECOMMENDED NUMBER OF DAYS :
SURVEY BY / SURVEYOR FIRM :
RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :
FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1- 7933.80
10%
P- 7140.42
S.N- 2090
L- 2060
11290.42

Post an Advertisement
 Sell it yourself! Advertise it at just
\$68 until it's SOLD!

Approval Case Up To 99%, High Trade In Price



Bank Loan @ 1.88% And 100%
 In House Financing @ 3.28%.
 5G Motors StarAd



Post an Ad Advertiser Login Ways of Selling

Browse by Category

7 vehicles

Porsche Macan

Sort by Date Posted 20 results/page

Advanced Search

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	Porsche	Macan	Any	Any	2014	Any	Any	Any	Available



Porsche Macan Diesel S 3.0A PDK **\$157,800** \$31,340 /yr 19-Dec-2014 2,967 cc 65,000 km SUV **Available**
Fuel Type: Diesel (Euro 5 Engine and Above)
 Sports Choono Package. Agent Unit. Cheaper Than A Standard Macan! Taken Care Of By Current Owner. High Loan And Trade In Available. Call Us Now To Make An Appointment To View This Beauty!
 Euro Performance Asia Pte Ltd
 Posted: 08-Jul-2021 Tags: 2014 Porsche Macan, Porsche Macan, Porsche, Macan

PREMIUM AD



Porsche Macan S 3.0A PDK **\$142,999** \$31,660 /yr 08-Jul-2014 2,997 cc 56,000 km SUV **Available**
 Hurry Buy Now Before COE Goes Up Again! 21" Porsche Rims! Super Low Mileage! 100% Accident Free! Immaculate Condition! Just Drive Off With Peace Of Mind! Excellent Driving Feel! Family 3rd Car Seldom Drive And Always Parked Under Shelter! Low-Interest Rates Avail...
 Posted: 05-Jul-2021 Tags: 2014 Porsche Macan, Porsche Macan, Porsche, Macan

PREMIUM AD



Porsche Macan S 3.0A PDK **\$170,800** \$34,120 /yr 09-Dec-2014 2,997 cc 81,000 km SUV **Available**
 Extended Warranty Till December 2021. Owner To Retain Carplate Consign Unit, Car Well Maintained By Female Owner, Servicing Done On Time. Call Us Now To Avoid Disappointment, Low Interest Bank Rate, In-house Loan And Competitive Insurance Quote Available!
 Posted: 04-Jul-2021 Tags: 2014 Porsche Macan, Porsche Macan, Porsche, Macan



Porsche Macan Diesel S 3.0A PDK **\$148,800** \$29,230 /yr 12-Dec-2014 2,967 cc 65,000 km SUV **Available**
Fuel Type: Diesel (Euro 5 Engine and Above)
 Consignment Unit! Agent Unit! After Warranty, Fully Serviced By Optima Werkz. Most Sought After Combinations - Black On Beige Leathers. Loan/Trade In Avail. No Consignment Agent!
 Posted: 01-Jul-2021 Tags: 2014 Porsche Macan, Porsche Macan, Porsche, Macan

DIRECT OWNER

Virtual simulations to help develop Macan

Digital models are able to replicate the properties, systems and power units of the vehicle to a high degree of accuracy.
 Read this article



Porsche Macan S 3.0A PDK **\$159,800** \$34,540 /yr 02-Sep-2014 2,997 cc 128,000 km SUV **Available**
 Free Extension Of Stuttgart Warranty To Sept 2023. Stuttgart Warranty 7 Years Till Sept 2021. Pristine Condition. Strictly Well Maintained From Day 1 By Agent. Sporty, Stylish, Modern In Design And Elegant For Single Or Family. Trade In, Loan Quantum Can Be Discussed....
 Sing Thai Hin Car
 Posted: 21-May-2021 Tags: 2014 Porsche Macan, Porsche Macan, Porsche, Macan



Porsche Macan Diesel S 3.0A PDK **\$158,888** \$36,150 /yr 24-Jul-2014 2,967 cc 121,914 km SUV **Available**
Fuel Type: Diesel (Euro 5 Engine and Above)
 Immediate Delivery! Newly Changed Fog Light, Head Lamp, Damper, Gasket & Transfer Box (Repair Just Done W 2Years Stuttgart Warranty From 24/05/21), Car Warranty Till 07/21 Or 200,000km, SMS For Exact Car Interior & Exterior Video. Attractive Trade-In & Fle...
 Posted: 20-May-2021 Tags: 2014 Porsche Macan, Porsche Macan, Porsche, Macan

PREMIUM AD

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	839D
Vehicle Details	
Vehicle No.:	SMA8148X
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Jul 2021
Vehicle Make:	PORSCHE
Vehicle Model:	MACAN S 3.0 A/T ABS D/AIRBAG 4WD
Primary Colour:	Black
Manufacturing Year:	2014
Engine No.:	011955
Chassis No.:	WP1ZZZ95ZFLB60694
Maximum Power Output:	250.0 kW (335 bhp)
Open Market Value:	\$74,137.00
Original Registration Date:	11 Nov 2014
First Registration Date:	11 Nov 2014
Transfer Count:	1
Actual ARF Paid:	\$105,447.00 <i>2723</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2024
PARF Rebate Amount:	\$68,540.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2024
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,889.00
COE Rebate Amount:	\$21,647.00
Total Rebate Amount:	\$90,187.00

The information contained herein is correct as at 09 Jul 2021

OK