

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate - 2

Denise.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0529/2021/TF

7-Jul-21

CHANG

1 of 1


SDA 7242 U

AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	A-PILLAR BRACKET - LH LOWER <i>disturbed</i>	\$ 44.00	34.88
GRAND TOTAL		\$ 44.00	

For Premium Automobiles Pte Ltd

Adrian Ling
07/07/21



Authorised Signature

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0529/2021/TF
3-Jul-21
CHANG
1 of 1
SDA 7242 U
AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL CENTER CONSOLE AND DASHBOARD ASSY TO FACILITATE RENEWAL OF LHS A PILLAR WITH SILL PANEL.	S/N \$ 3,200.00	✓
2	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, A/B PILLAR TRIMS, SILL TRIMS, CARPET, ELECTRICAL COMPONENTS AND FUSE TRAYS	S/N \$ 1,800.00	✓
3	TO RENEW FRONT WINDSCREEN TO FACILITATE RENEWAL OF A PILLAR WITH SILL PANEL.	S/N \$ 500.00	X
4	TO REMOVE AND REPLACE RAIN SENSOR FOIL TO RESET SYSTEM.	S/N \$ 300.00	X
5	TO CARRY OUT WATER SEEPAGE TEST FOR FRONT WINDSCREEN.	S/N \$ 200.00	X
6	TO CUT OUT AND WELD LHS A-PILLAR.	\$ 2,400.00	? 750.
7	TO RESPRAY LHS A-PILLAR.	\$ 1,000.00	550
Parts			
1	A/B PILLAR FRAME - LH	\$ 3,361.00	?
2	FRONT WINDSCREEN	\$ 1,461.00	?
3	RAIN SENSOR GEL FOIL	\$ 137.00	?
4	GLASS PRIMER	\$ 20.00	?

GRAND TOTAL \$ 14,379.00

Adrian Ling
05/07/21
88/5

For Premium Auto
Authorised Sign

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

Tel: 6366 2323 FAX: 6841 1183

EMAIL: JORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDA 7242 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVIVOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S.N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S.N \$ 400.00	250
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. TO CUT LHS FRONT FENDER TOP SUPPORT AND LHS A-PILLAR BRACKET, RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	1500 1000
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, BONNET, LHS FRONT DOOR, DOOR COVER, LHS UPPER A-PILLAR, LHS A-PILLAR BRACKET, LHS WING MIRROR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 8,400.00	3700
SUB TOTAL LABOUR CHARGES		\$ 15,960.00	

Bumper 550
 Lower Spoiler 275
 Fender 550
 Fender Top Support 275
 Bonnet 550
 Door 550
 A pillar - Upper : 550
 Wheel Arch x 2 = 400
 3700

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 5366 2323 FAX : 6841 1183

EMAIL : NURA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDA 7242 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
01	A/SEALANT	S/N \$	180.00	✓
02	C/WAX	S/N \$	140.00	✓
03	METAL FILLER POWER	S/N \$	290.00	✓
04	STONE CHIP	S/N \$	180.00	✓
05	SUNDRIES	\$	400.00	✓
TOTAL SPARE PARTS		:	\$ 24,857.00	
TOTAL LABOUR CHARGES		:	\$ 16,864.00	
GRAND TOTAL		:	\$ 41,721.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.