

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0529/2021/TF
DATE : 26-Jun-21
WIP : 32941

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/06/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. LONG SEY HAI
ADDRESS : 20 UPPER CIRCULAR ROAD
#09-01
SINGAPORE 058416
TELEPHONE : HP +65 96866534
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100462895-05
VEHICLE NO : **SDA 7242 U**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 27/4/2016
ENGINE NO : CZD 226388
CHASSIS NO : WAUZZZ8U7GR068212
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Jun-21
PLACE OF ACCIDENT : NOVENA SQUARE CARPARK RAMP

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDA 7242 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE , CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S.N \$ 360.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S.N \$ 400.00	250
3	TO REMOVE AND TRANSFER LHS FRONT DOOR 'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
4	TO DISMANTLE AND RENEW FRONT BUMPER , LHS FRONT FENDER , LHS FRONT DOOR AND LHS HEADLIGHT. TO CUT LHS FRONT FENDER TOP SUPPORT AND LHS A-PILLAR BRACKET.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 6,400.00	1500
5	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER, LHS FRONT FENDER TOP SUPPORT, BONNET, LHS FRONT DOOR , DOOR COVER, LHS UPPER A-PILLAR, LHS A-PILLAR BRACKET, LHS WING MIRROR COVER AND BOTH FRONT WHEEL ARCH TRIMS.	\$ 8,400.00	3700
SUB TOTAL LABOUR CHARGES		\$ 15,960.00	

Bumper 550
Lower Spoiler 275
Fender 550
Fender Top Support 275
Bonnet 550
Door 550
A pillar upper = 550
Wheel Arc x 2 = 400
3700

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDA 7242 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	320
7	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ <u>16,864.00</u>	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDA 7242 U

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1	\$	2,125.00	✓
2	FRONT BUMPER FIXING PARTS <i>Ne m</i>	1	\$	109.00	+
3	FRONT BUMPER AIR GUIDE GRILLE - LH <i>Ne m</i>	1	\$	153.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>men</i>	1	\$	176.00	+
5	FRONT BUMPER SPOILER <i>cut</i>	1	\$	581.00	✓
6	FRONT FENDER - LH <i>Distorted</i>	1	\$	902.00	✓
7	FRONT FENDER ATTACHMENT PARTS <i>Ne m</i>	1	\$	70.00	+
8	FRONT FENDER BRACKET - LH <i>Distorted</i>	1	\$	83.00	✓
9	FRONT FENDER RIVET <i>Ne</i>	6	\$	20.00	✓
10	FRONT FENDER BRACE - LH <i>Bent.</i>	1	\$	105.00	✓
11	FRONT FENDER CLOSING ELEMENT - LH ?	1	\$	33.00	?
12	FRONT WHEEL HOUSING SEAL ?	1	\$	18.00	?
13	FRONT WHEEL HOUSING LINER <i>torn</i>	1	\$	240.00	✓
14	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>Ne m</i>	1	\$	153.00	+
15	FRONT WHEEL SPOILER - LH <i>Ne m</i>	1	\$	73.00	+
16	FRONT WHEEL COVER - LH / RH <i>LH cut, RH Ne m</i>	2	\$	1,056.00	✓
17	FRONT FENDER UPPER BRACKET - LH <i>Distorted</i>	1	\$	65.00	✓
18	FRONT SIDE MEMBER <i>Rein</i>	1	\$	431.00	+
19	SIDE MEMBER RIVETTED CAP <i>Ne</i>	2	\$	6.00	✓
20	HEADLIGHT MOUNTING - LH ?	1	\$	118.00	?
SUB TOTAL SPARE PARTS		:	\$	6,517.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDA 7242 U

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	S/NETT	REMARKS
21	HEADLIGHT RETAINING PLATE - LH ?	1	\$	87.00 ?	
22	HEADLIGHT - LH <i>cracked</i>	1	\$	7,781.00 ✓	
23	HEADLIGHT LED MODULE <i>new</i>	1	\$	781.00 +	
24	HEADLIGHT FAN <i>new</i>	1	\$	398.00 x	
25	HEADLIGHT POWER MODULE - DAY LIGHT <i>3 AP</i>	1	\$	553.00 +	
26	HEADLIGHT POWER MODULE - MAIN LIGHT <i>AP</i>	1	\$	686.00 +	
27	HEADLIGHT POWER MODULE - CORNERING LIGHT <i>AP</i>	1	\$	557.00 +.	
28	HEADLIGHT HOSE <i>new</i>	1	\$	36.00 +.	
29	WINDSHIELD MOLDING - LH <i>done</i>	1	\$	67.00 ✓	
30	FRONT COWL-SIDE SEAL - LH ?	1	\$	41.00 ?	
31	FRONT DOOR - LH <i>Regis</i>	1	\$	2,909.00 +	
32	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$	166.00 +	
33	GROMMET <i>new</i>	5	\$	13.00 +.	
34	FRONT PROTECRIVE FILM ?	1	\$	26.00 ?	
35	FRONT DOOR ATTACHMENT PART <i>new</i>	1	\$	107.00 +.	
36	FRONT DOOR CATCH - LH <i>new</i>	1	\$	120.00 +	
37	FRONT DOOR COVER - LH <i>new</i>	1	\$	446.00 x	
38	FRONT MIRROR MOUNTING - LH <i>new</i>	1	\$	1,024.00 x	
39	FRONT TURNING SIGNAL INDICATOR <i>new</i>	1	\$	100.00 x	
40	FRONT ALUMINIUM RIM - LH <i>let</i>	1	\$	1,262.00 ✓	
TOTAL SPARE PARTS			:	\$ 17,160.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDA 7242 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	A/SEALANT	S/N	\$ 180.00	✓
42	C/WAX	S/N	\$ 140.00	✓
43	METAL FILLER POWER	S/N	\$ 280.00	✓
44	STONE CHIP	S/N	\$ 180.00	✗
45	SUNDRIES		\$ 400.00	✓
TOTAL SPARE PARTS		:	\$ 24,857.00	
TOTAL LABOUR CHARGES		:	\$ 16,864.00	
GRAND TOTAL		:	\$ 41,721.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *28/06/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorized, 08 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT