

Not Authoised
Repair B4 paint

Trans-cab Auto Services Pte Ltd

AAD2106-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5242U

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

28 JUN 2021

SHD5242U

JTDKB3FU003078534

TOYOTA

PRIUS

24/06/2021

To Kio.

19/12/2018

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$ 1,300.70 ✓
1 WEATHERSTRIP, FRONT DOOR, LH	\$ 231.30 X
1 HINGE ASSY, FRONT DOOR, LOWER LH	\$ 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER LH	\$ 97.50 X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$ 13.30 —
1 TAPE, BLACK OUT, NO.2 FRT LH	\$ 43.50 —
1 TAPE, BLACK OUT, NO.3 FRT LH	\$ 26.30 —
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$ 193.50 X
1 HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$ 390.60 X
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$ 926.00 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$ 238.30 X
1 MIRROR ASSY, OUTER REAR VIEW, LH	\$ 1,339.30 ✓
1 COVER, FRONT BUMPER	\$ 516.00 —
1 FENDER SUB-ASSY, FRONT LH	\$ 977.80 ✓
1 LINER, FRONT FENDER, LH	\$ 202.50 —
TOTAL	\$ 6,607.20
25%	\$ 1,651.80
(PART-BY-PART) Repair Cost	\$ 4,955.40

Special Nett

1 FENDER CLIP	\$ 130.00 X
1 FENDER LINER CLIP	\$ 65.00 —
2SET DOOR WEATHERSTRIP CLIP	\$ 130.00 X
1 FRONT BUMPER SIDE CLIP	\$ 60.00 50% off
1 FRONT BUMPER CLIP	\$ 65.00 X
1 DOOR STICKER TRANSCAB	\$ 100.00 50% off

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2106-

SHD5242U

- 1 DOOR STICKER TEL NO.
- 1 TYRE
- 1 RIM

\$	100.00	X
\$	350.00	80%a
\$	1,879.40	X
TOTAL	\$ 2,879.40	
TOTAL PARTS	\$ 7,834.80	

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,400.00 500

Putty And Spray Painting Of The Affected Portion.

\$ 1,400.00 700

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 240.00 60

To Check Electrical Lighting Concerned.

\$ 170.00 20

TOTAL \$ 3,590.00

Over All Total \$ 11,424.80

(PART-BY-PART) Repair Days

20 days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: