

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5242U*Not Notified*
*Repair B4 paint***84913.55****AAD2106-**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

28 JUN 2021**SHD5242U**

JTDKB3FU003078534

TOYOTA

PRIUS

24/06/2021

Tb Kio.

19/12/2018

PART**LIST**

1	PANEL SUB-ASSY, FRONT DOOR, LH	\$	Bn	1,300.70	✓
1	WEATHERSTRIP, FRONT DOOR, LH	\$	Bn	231.30	X
1	HINGE ASSY, FRONT DOOR, LOWER LH	\$	R	110.60	X
1	HINGE ASSY, FRONT DOOR, UPPER LH	\$	R	97.50	X
1	TAPE, BLACK OUT, NO.1 FRT LH	\$	R	13.30	—
1	TAPE, BLACK OUT, NO.2 FRT LH	\$	R	43.50	—
1	TAPE, BLACK OUT, NO.3 FRT LH	\$	Me	26.30	—
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, LH	\$	R	193.50	X
1	HANDLE ASSY, FRONT DOOR OUTSIDE, LH	\$	Bn	390.60	X
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT LH	\$	Bn	926.00	X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, LH	\$	Bn	238.30	X
1	MIRROR ASSY, OUTER REAR VIEW, LH	\$	CM	1,339.30	✓
1	COVER, FRONT BUMPER	\$	Bn	516.00	—
1	FENDER SUB-ASSY, FRONT LH	\$	R	977.80	✓
1	LINER, FRONT FENDER, LH	\$	Di	202.50	—
TOTAL		\$		6,607.20	
25%		\$		1,651.80	
		\$		4,955.40	

Special Nett

1	FENDER CLIP	\$	na Me	130.00	X
1	FENDER LINER CLIP	\$	na	65.00	✓
2SET	DOOR WEATHERSTRIP CLIP	\$	na	130.00	X
1	FRONT BUMPER SIDE CLIP	\$	na	60.00	50% na
1	FRONT BUMPER CLIP	\$	na	65.00	X
1	DOOR STICKER TRANSCAB	\$	na	100.00	50% na

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2106-

SHD5242U

- 1 DOOR STICKER TEL NO.
- 1 TYRE
- 1 RIM

1485N	\$	100.00	X
	\$	350.00	809a
	\$	1,879.40	X
TOTAL	\$	2,879.40	

TOTAL PARTS	\$	7,834.80
--------------------	-----------	-----------------

LABOUR

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$	380.00	X
----	--------	---

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$	1,400.00	500l
----	----------	------

Putty And Spray Painting Of The Affected Portion.

\$	1,400.00	700l
----	----------	------

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$	240.00	60l
----	--------	-----

To Check Electrical Lighting Concerned.

\$	170.00	20l
----	--------	-----

TOTAL	\$	3,590.00
--------------	-----------	-----------------

Over All Total	\$	11,424.80
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days

20 days

3 days

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: