#### Note: This document has not been finalised.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.

Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Abu Kassim, Noor Mariesa Date: 16 Jul 2021

# **Preliminary Advice**

Vehicle No : SGR1166X Accident Date : 25/06/2021 : AUDI A5 Policy No. : 1800067648-Make

01

: 6

: S\$800.00

Assignment

Date

Date of

: 29/06/2021

: 28/06/2021 Est. Duration of

Excess

Inspection Repair

Inspection At: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

(ESTIMATE

\$37,584.00 + 37,620.00 Repairer's Estimate (Gross) :S\$

SUPPLEMENTARY

\$36.00)

**Revised Amount** 20,468.00 :S\$ :S\$ 3,162.00 Check Items (Estimated) Total :S\$ 23,630.00

:S\$ Lump Sum Repair

**Total Loss Consideration** 

New for Old Value :S\$

Pre-Accident Value :S\$ 138,000.00 COE / PARF Rebate :S\$ 61,309.00

Salvage Value :S\$

Margin for Repair :S\$ 76,691.00

#### **Remarks**

( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: KINDLY APPROVE ON SUPPLEMENTARY.