

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NOPA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0532/2021/TF
DATE : 4-May-21
WIP : 25560

Xiao Chun.
\$18525.12

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/06/2021

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR RAFEEL AHMED S/O ABDUL MAJEED
ADDRESS : 73 PASIR RIS GROVE LIVIA
#06-23
SINGAPORE 518206
TELEPHONE : HP +65 91005327
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800067648-01
VEHICLE NO : SGR 1166 X
MODEL CODE : A5 SPORTBACK 2.0 TFSI S TRONIC
MODEL YEAR : 19/6/2018
ENGINE NO : CVK 062064
CHASSIS NO : WAUZZZF51JA101867
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jun-21
PLACE OF ACCIDENT : BEDOK FOOD CENTER CARPARK

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGR 1166 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00	250 ✓ 480
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE	S/N \$ 400.00	250 ✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, ADDITIONAL RADIATOR, RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	S/N \$ 1,700.00	+
4	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR	S/N \$ 280.00	+
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, RHS FRONT FENDER AND RHS HEADLIGHT. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 5,600.00	1500 ✓
SUB TOTAL LABOUR CHARGES		\$ 8,460.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGR 1166 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES AND RHS FRONT DOOR.	\$ 4,400.00	1650 ✓
7	TO REAPPLY STICKER ON AFFECTED PANELS.	S/N TBC	?? 350
8	TO REAPPLY PAINT PROTECTION ON FRONT BONNET, HEADLIGHT AND FRONT BUMPER (BY OWNER)	S/N \$ 1,500.00	?? 1150
9	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 14,552.00	

[Handwritten signature]

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: TJOA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGR 1166 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	1 S	2,251.00	✓ 1800.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	1 S	407.00	+
3	FRONT BUMPER SECURING STRIP <i>new</i>	2 S	71.00	+
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1 S	196.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>new</i>	1 S	228.00	+
6	FRONT BUMPER AIR GUIDE - RH <i>new Deformed</i>	1 S	63.00	+ 50.08 ✓
7	FRONT BUMPER AIR GUIDE GRILLE - RH <i>cut</i>	1 S	474.00	✓ 378.80
8	FRONT BUMPER CARRIER <i>new</i>	1 S	845.00	? X
9	FRONT BUMPER CARRIER FORM <i>new</i>	1 S	124.00	? X
10	FRONT BUMPER TOP COVER <i>new</i>	1 S	127.00	+
11	FRONT BUMPER GUIDE SECTION - RH <i>Deformed</i>	1 S	36.00	✓ 28.72
12	FRONT BUMPER BRACKET - RH <i>Deformed</i> NN	1 S	214.00	✓ X
13	CAUTION STICKER <i>new</i>	1 S	14.00	+
14	A/C STICKER <i>new</i>	1 S	8.00	+
15	FRONT LOCK CARRIER BRACKET <i>new</i>	1 S	137.00	+
16	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2 S	58.00	? X
17	FRONT BUMPER PARKING AID SENSOR <i>new</i>	2	TBC	+
18	FRONT BUMPER PARKING AID SENSOR SEAL RING <i>new</i>	4 S	9.00	+
19	FRONT BUMPER WIRING SET <i>new</i>	1 S	510.00	+
20	HORN - LOW TONE <i>new</i>	1 S	126.00	? X
SUB TOTAL SPARE PARTS		:	\$ 5,898.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55, UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6341 1183
EMAIL: NURA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGR 1166 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	HORN BRACKET <i>Neu</i>	1	\$ 29.00	X
22	FRONT FENDER - RH <i>Dented</i>	1	\$ 1,060.00	✓ 848
23	FRONT FENDER ATTACHMENT PARTS <i>Neu</i>	1	\$ 53.00	+
24	FRONT FENDER CLOSING ELEMENT - RH <i>Neu</i>	1	\$ 74.00	? X
25	FRONT FENDER BRACKET - RH <i>Distorted</i>	1	\$ 35.00	— 27.92
26	FRONT FENDER RIVET <i>Neu</i>	5	\$ 17.00	✓ 13.20
27	FRONT FENDER DEFORMATION BRACKET - RH <i>Dented</i>	1	\$ 49.00	✓ 39.20
28	FRONT FENDER BRACKET - RH FRONT <i>Dented</i>	1	\$ 35.00	— 27.92
29	FRONT FENDER BRACE - RH <i>Bent</i>	1	\$ 118.00	✓ 94.40 ✓
30	FRONT FENDER CHROME TRIM - RH <i>Neu</i>	1	\$ 164.00	✓ 130.80
31	FRONT WHEEL HOUSING LINER - RH <i>Deformed</i>	1	\$ 275.00	✓ 219.60
32	FRONT WHEEL HOUSING LINER ATTACHMENT <i>Neu</i>	1	\$ 169.00	+
33	FRONT WHEEL SPOILER - RH <i>Cracked</i>	1	\$ 73.00	X 58.40 ✓
34	FRONT WHEEL SPOILER TRIM - RH <i>Neu</i>	1	\$ 51.00	+
35	FRONT WHEEL SPOILER TRIM BRACKET - RH <i>Neu</i>	1	\$ 24.00	+
36	FRONT FENDER TOP COVER <i>Neu</i>	2	\$ 16.00	— X
37	FRONT BONNET <i>Dented</i>	1	\$ 3,312.00	✓ 2649.60
38	FRONT BONNET RETAINING CLIP <i>Neu</i>	3	\$ 4.00	? X
39	FRONT BONNET ATTACHMENT PARTS <i>Neu</i>	1	\$ 126.00	+
40	FRONT BONNET HINGE <i>Neu</i>	2	\$ 838.00	X
SUB TOTAL SPARE PARTS			\$ 6,522.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGR 1166 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT BONNET IMPACT PROTECTION <i>Neu</i>	3	\$ 84.00	✓ 65.68
42	FRONT BONNET SOUND ABSORBER <i>Neu</i>	1	\$ 343.00	+
43	FRONT BONNET STRIKER <i>? Neu</i>	1	\$ 50.00	+
44	FRONT BONNET LOCK	1	\$ 214.00	+
45	FRONT HEADLIGHT - RH <i>Cracked</i>	1	\$ 7,902.00	✓ 6321.60
46	FRONT HEADLIGHT LIFT CYLINDER - RH <i>Damaged</i>	1	\$ 198.00	✓ 158.40 ✓
47	FRONT HEADLIGHT LIFT CYLINDER BRACKET - RH <i>Neu</i>	1	\$ 15.00	? X
48	FRONT HEADLIGHT LIFT CYLINDER HOSE - RH <i>Neu</i>	1	\$ 86.00	X
49	FRONT LOCK CARRIER <i>Neu</i>	1	\$ 1,016.00	+
50	FRONT SENSOR BRACKET <i>Neu</i>	1	\$ 19.00	+
51	COOLANT <i>Neu</i>	6	\$ 142.00	+
52	FRONT RADIATOR AIR GUIDE <i>? Neu</i>	3	\$ 63.00	+
53	FRONT RADIATOR GRILLE		TBC	+
54	FRONT NO. PLATE <i>Neu</i>	S/N	\$ 80.00	+
55	SUNDRIES <i>Neu</i>		\$ 400.00	? 40 ✓
TOTAL SPARE PARTS		:	\$ 23,032.00	
TOTAL LABOUR CHARGES		:	\$ 14,552.00	
GRAND TOTAL		:	\$ 37,584.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

VEHICLE DAMAGE INSPECTION REPORT

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :

SURVEYED DATE :

AUTHORISED DATE :

EXCESS COST :

LIABILITY :

REMARKS :

Adrian Lj
28/06/21

Not Authorized, 06 Days.

H. S.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

