

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Xiao Chan .

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0532/2021/KS
1-Jul-21
KEE SIANG
1 of 1
SGR 1166 X
A5 SPORTBACK 2.0 TFSI S TRONIC

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	FRONT FENDER TOP LEDGE COVER RH 26.00	\$ 36.00	XNN
GRAND TOTAL		\$ 36.00	

For Premium Automobiles Pte Ltd

Adrian L
07/07/21
H.S.



Authorised Signature

Cor-in 1/9/24

wp= 25560

LQ/keong

AG-Adnan

- 6 days



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGR 1166 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1 S	2,251.00	✓
2	FRONT BUMPER FIXING PARTS xle m	1 S	407.00	x
3	FRONT BUMPER SECURING STRIP xle m	2 S	71.00	x
4	FRONT BUMPER GRILLE - CENTER xle m	1 S	196.00	x
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER xle m	1 S	228.00	x
6	FRONT BUMPER AIR GUIDE - RH new behind	1 S	63.00	✓
7	FRONT BUMPER AIR GUIDE GRILLE - RH cut	1 S	474.00	✓
8	FRONT BUMPER CARRIER ?	1 S	845.00	?
9	FRONT BUMPER CARRIER FORM ?	1 S	124.00	?
10	FRONT BUMPER TOP COVER xle m	1 S	127.00	x
11	FRONT BUMPER GUIDE SECTION - RH Dented	1 S	36.00	✓
12	FRONT BUMPER BRACKET - RH Dashed	1 S	214.00	✓
13	CAUTION STICKER } xle m	1 S	14.00	x
14	A/C STICKER } xle m	1 S	8.00	x
15	FRONT LOCK CARRIER BRACKET xle m	1 S	137.00	x
16	FRONT BUMPER SUPPORT - LH / RH ?	2 S	58.00	?
17	FRONT BUMPER PARKING AID SENSOR xle m	2	TBC	x.
18	FRONT BUMPER PARKING AID SENSOR SEAL RING xle m	4 S	9.00	x
19	FRONT BUMPER WIRING SET xle m	1 S	510.00	x
20	HORN- LOW TONE Abbr ?	1 S	126.00	?
SUB TOTAL SPARE PARTS		:	\$	5,898.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

Add

N 06 185 7 X 5

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGR 1166 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	HORN BRACKET <i>Not New</i>	1	S	29.00	+
22	FRONT FENDER - RH <i>Dented</i>	1	S	1,060.00	✓
23	FRONT FENDER ATTACHMENT PARTS <i>Not New</i>	1	S	53.00	+
24	FRONT FENDER CLOSING ELEMENT - RH ?	1	S	74.00	?
25	FRONT FENDER BRACKET - RH <i>Distorted</i>	1	S	35.00	—
26	FRONT FENDER RIVET <i>New</i>	5	S	17.00	✓
27	FRONT FENDER DEFORMATION BRACKET - RH <i>Dented</i>	1	S	49.00	✓
28	FRONT FENDER BRACKET - RH FRONT <i>Dented</i>	1	S	35.00	✓
29	FRONT FENDER BRACE - RH <i>Brace</i>	1	S	118.00	✓
30	FRONT FENDER CHROME TRIM - RH <i>New</i>	1	S	164.00	✓
31	FRONT WHEEL HOUSING LINER - RH <i>Dented</i>	1	S	275.00	✓
32	FRONT WHEEL HOUSING LINER ATTACHMENT <i>Not New</i>	1	S	169.00	+
33	FRONT WHEEL SPOILER - RH <i>Cracked</i>	1	S	73.00	✓
34	FRONT WHEEL SPOILER TRIM - RH <i>Not New</i>	1	S	51.00	+
35	FRONT WHEEL SPOILER TRIM BRACKET - RH <i>Not New</i>	1	S	24.00	+
36	FRONT FENDER TOP COVER ?	2	S	16.00	?
37	FRONT BONNET <i>Dented</i>	1	S	3,312.00	✓
38	FRONT BONNET RETAINING CLIP ?	3	S	4.00	?
39	FRONT BONNET ATTACHMENT PARTS <i>Not New</i>	1	S	126.00	+
40	FRONT BONNET HINGE <i>Not New</i>	2	S	838.00	+
SUB TOTAL SPARE PARTS		:	\$	6,522.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGR 1166 X

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT BONNET IMPACT PROTECTION <i>Neu</i>	3	\$	84.00	✓
42	FRONT BONNET SOUND ABSORBER <i>Neu</i>	1	\$	343.00	+
43	FRONT BONNET STRIKER <i>} Neu</i>	1	\$	50.00	+
44	FRONT BONNET LOCK	1	\$	214.00	+
45	FRONT HEADLIGHT - RH <i>Caused</i>	1	\$	7,902.00	✓
46	FRONT HEADLIGHT LIFT CYLINDER - RH <i>Damaged.</i>	1	\$	198.00	✓
47	FRONT HEADLIGHT LIFT CYLINDER BRACKET - RH	1	\$	15.00	?
48	FRONT HEADLIGHT LIFT CYLINDER HOSE - RH <i>Neu</i>	1	\$	86.00	+
49	FRONT LOCK CARRIER <i>Neu</i>	1	\$	1,016.00	+
50	FRONT SENSOR BRACKET <i>Neu</i>	1	\$	19.00	+
51	COOLANT <i>Neu</i>	6	\$	142.00	+
52	FRONT RADIATOR AIR GUIDE <i>} Neu</i>	3	\$	63.00	+
53	FRONT RADIATOR GRILLE			TBC	+
54	FRONT NO. PLATE <i>Neu</i>	S/N	\$	80.00	+
55	SUNDRIES		\$	400.00	?
TOTAL SPARE PARTS		:	\$	23,032.00	
TOTAL LABOUR CHARGES		:	\$	14,552.00	
GRAND TOTAL		:	\$	37,584.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.