

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 456 9830 • FAX: 455 3986
Business Regn No : 269436/00J

28, Jun 2021

EQ Insurance Company Ltd
5 Maxwell Road #17-00 Tower Block MNO Complex
S069110

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no:GBD8501Z
Accident involving vehicle no: SMK896U/GBD8501Z
DOA: 25/06/2021 AT CTE (city) before Braddell Lane 2

Dear sir,

Re: Estimate cost of repair for vehicle no: SMK896U

To supply:

Description	Qty	Amount
Tailgate	1	1,472.00
Rear door board	1	136.00
Tailgate absorber @ 129.80	2	259.60
Tailgate lock	1	174.90
Tailgate reflector @296.40	2	592.80
End panel	1	474.10
End panel top garnish	1	84.90
Rear bumper	1	508.80
Rear bumper side @118.50	2	237.00
End panel top garnish aluminium cover	1	75.00
Taillamp @462.60	2	925.20
Boot weather strip	1	165.30
Tailgate auto lock motor	1	
Tailgate bezel emblem	1	52.50
EH logo	1	45.10
Description	Qty	Amount
Tailgate	1	1,472.00
Rear door board	1	136.00
Tailgate absorber	2	259.60
Tailgate lock	1	174.90
Tailgate reflector	2	592.80
End panel	1	474.10
End panel top garnish	1	84.90
Rear bumper	1	508.80
Rear bumper side	2	237.00
End panel top garnish	1	75.00
Taillamp	2	925.20
Boot weather strip	1	165.30
Tailgate auto lock motor	1	
Tailgate bezel emblem	1	52.50
EH logo	1	45.10

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: [Signature]

Date:

