

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: 455 3986
Business Regn No : 269436/00J

28, Jun 2021

EQ Insurance Company Ltd
5 Maxwell Road #17-00 Tower Block MNO Complex
S069110

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no:GBD8501Z
Accident involving vehicle no: SMK896U/GBD8501Z
DOA: 25/06/2021 AT CTE (city) before Braddell Lane 2

Dear sir,

Re: Estimate cost of repair for vehicle no: SMK896U

To supply:

Description	Qty	Amount
Tailgate <i>953</i>	1	1,472.00 ✓
Rear door board	1	136.00 X
Tailgate absorber @ 129.80	2	259.60 ✓
Tailgate lock	1	174.90 ✓
Tailgate reflector @296.40	2	592.80 ✓
End panel	1	474.10 ✓
End panel top garnish	1	84.90 ✓
Rear bumper	1	508.80 ✓
Rear bumper side @118.50	2	237.00 ✓
End panel top garnish aluminium cover	1	75.00 ✓
Taillamp @462.60	2	925.20 ✓
Boot weather strip	1	165.30 X
Tailgate auto lock motor	1	nn
Tailgate vezel emblem	1	52.50 ✓
H logo	1	45.10 X
<i>Reverse</i>	<i>2 of</i>	<i>86.60</i> ✓
Tailgate		1,472.00
Rear door board		136.00
Tailgate absorber		259.60
Tailgate lock		174.90
Tailgate reflector		592.80
End panel		474.10
End panel top garnish		84.90
Rear bumper		508.80
Rear bumper side		237.00
End panel top garnish		75.00
Taillamp		925.20
Boot weather strip		165.30
Tailgate auto lock motor		
Tailgate vezel emblem		52.50
H logo		45.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

0.00

Vehicle no: SMK896U
 Test no: 1071 AT City of

Reverse sensor
 To remove/transfer rear windscreen glass to New door
 To remove damaged parts and attachments
 Repair/reshape all dented areas
 Repair/straighten rear chassis
 Replace/align all parts into position
 To spray paint

Vehicle no: SMK896U
 Test no: 1071 AT City of

Reverse sensor
 To remove/transfer rear windscreen
 To remove damaged parts and attach
 Repair/reshape all dented areas
 Repair/straighten rear chassis
 Replace/align all parts into position
 To spray paint

Vehicle no: SMK896U
 Test no: 1071 AT City of

Reverse sensor
 To remove/transfer rear windscreen
 To remove damaged parts and attach
 Repair/reshape all dented areas
 Repair/straighten rear chassis
 Replace/align all parts into position
 To spray paint

Vehicle no: SMK896U
 Test no: 1071 AT City of

45.00

Amount

1,172.00

174.00

253.80

174.00

592.80

474.10

84.90

508.80

237.00

75.00

925.20

Shen 220.00 2005m

160.00

1201

52.50

45.10

Amount

950.00

7001

900.00

7001

249.50

174.00

592.80

474.10

84.90

508.80

237.00

75.00

925.20

1230.00

160.00

52.50

45.10

Amount

1,490.00

1,908.00

249.50

174.00

45.10

474.10

84.90

508.80

237.00

75.00

925.20

1,230.00

160.00

52.50

45.10

Amount

1,950.00

1,908.00

249.50

174.00

45.10

474.10

84.90

508.80

237.00

75.00

925.20

1,230.00

1,908.00