

Attn Kenneth

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 26/06/2021

TP Veh Reg No: SMA1967U

Estimate No: ES2190595/AMK

Date: 29 Jun 2021

Policy No: 5118707551

Veh Reg No: GBK5275J

Make/Model: TOYOTA HIACE

Chassis No: JTFHT02PX09990310

Engine No: 1KDB046010

Reg. Date: 31/08/2020

Estimate Repair Cost to Vehicle No :GBK5275J

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	454.30	1 PC	71 454.30	✓
2 REAR BUMPER RH SIDE RETAINER	23.40	1 PC	CD 23.40	✓
3 REAR BUMPER CLIP	2.95	6 PC	M 17.70	✓
4 REAR BUMPER MUDFLAP	127.85	1 PC	DIT 127.85	✓
5 REAR TAILGATE	2,162.70	1 PC	B 2,162.70	✓
6 TAILGATE INNER RUBBER	408.40	1 PC	S 408.40	X
7 TAILGATE LOGO	67.80	1 PC	M 67.80	✓
8 TAILGATE EMBLEM 'HIACE'	48.60	1 PC	M 48.60	✓
9 RH TAILLAMP	367.60	1 PC	B 367.60	✓
10 RH TAILLAMP PANEL	570.30	1 PC	B 570.30	✓
11 RH TAILLAMP CLIP	3.50	1 PC	M 3.50	✓
12 RH TAILLAMP LOWER GARNISH	93.90	1 PC	CM 93.90	✓
13 REAR END PANEL OUTER	342.50	1 PC	B 342.50	✓
14 REAR END PANEL INNER	1,104.70	1 PC	B 1,104.70	✓
15 REAR RH SIDE PANEL	1,546.90	1 PC	B 1,546.90	✓
16 REAR RH SIDE INNER PANEL	1,281.10	1 PC	R 1,281.10	X
17 REAR RH SIDE PANEL INNER AIR SCOPE GRILLE	43.80	1 PC	CM 43.80	✓
18 REAR RH SIDE PANEL INNER TRIM BOARD	137.40	1 PC	DIT 137.40	✓
19 RH SLIDING DOOR	1,916.10	1 PC	B 1,916.10	✓
20 REAR RH WHEEL HOUSE COVER	212.20	1 PC	D 212.20	✓
			9241.25	10,930.75
Less 25%			2,732.69	8,198.06
			2310.31	
Special Net				
21 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	M 40.00	✓
22 TAILGATE STICKER 70KM/HR	10.00	1 PC	M 10.00	✓
23 REVERSE SENSOR	200.00	1 SET	win 200.00	✓
			250.00	250.00
Labour				
24 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
25 REMOVE & REFIX CARPET, TOP ROOF LINING, WOODEN FLOORBOARD GARNISH TO FACILITATE REPAIR	250.00	1 LA	250.00	1801
26 REMOVE & REFIX REAR EXHAUST & REALIGN THE SAME	80.00	1 LA	80.00	601

11 days

Not authorized
Recovery B4 pain

6930.94

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 26/06/2021

TP Veh Reg No: SMA1967U

Estimate No: ES2190595/AMK

Date: 29 Jun 2021

Policy No: 5118707551

Veh Reg No: GBK5275J

Make/Model: TOYOTA HIACE

Chassis No: JTFHT02PX09990310

Engine No: 1KDB046010

Reg. Date: 31/08/2020

Estimate Repair Cost to Vehicle No :GBK5275J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
27 R & R REAR BUMPER & ATTACHMENTS, TAILLAMPS, TAILGATE & ATTACHMENTS, RH SLIDING DOOR & ATTACHMENTS, CUT, WELD & RENEW REAR END PANEL OUTER & INNER, REAR RH SIDE PANEL & INNER PANEL, K & R REAR FLOORBOARD PANEL, RH CHASSIS FRAME, RH WHEEL HOUSING & REALIGN THE SAME	2,000.00	1 LA	2,000.00	1600
28 PUTTY & RESPRAY RR BUMPER & PARKING SENSORS, TAILGATE, RR END PANEL OUTER & INNER, RH SIDE PANEL & INNER PANEL, TAILLAMP PANEL & LOWER GARNISH, REAR FLOORBOARD PANEL, RH CHASSIS FRAME, RH WHEEL HOUSING, RH SLIDING DOOR, FRT RH DOOR PILLAR REAR & ALL AFFECTED AREAS	1,400.00	1 LA	1,400.00	1300
29 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
30 RUSTPROOFING	150.00	1 LA	150.00	120
			4,060.00	3440
			<u>4,060.00</u>	
Total			S\$ 12,508.06	
Add GST @ 7%			875.56	
Total Amount Payable			S\$ 13,383.62	

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

PARTS: 6930.94

SUPP: 216.83

SN: 250

L: 3440

10837.77

PLP: 10837.77

PLS CHECK & CONFIRM.

Dorlyn

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 26/06/2021
TP Veh Reg No: SMA1967U

Estimate No: ES2190595/AMK
Date: 06 Jul 2021
Policy No: 5118707551
Veh Reg No: GBK5275J
Make/Model: TOYOTA HIACE
Chassis No: JTFHT02PX09990310
Engine No: 1KDB046010
Reg. Date: 31/08/2020

Estimate Repair Cost to Vehicle No :GBK5275J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
List Price				
1 RH TAILLAMP INNER PANEL	289.10	1 PC	289.10	
			289.10	
		Less 25%	72.28	216.83
Total				S\$ 216.83
GST Amount				S\$ 15.18
Total Amount Payable				S\$ 232.00

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE