



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD  
8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:CYNTHIA

Ref: CC4/ASM21007139/Ugs3q2  
Date: 14/10/2021  
Code: ASM

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SCN 3097S	<b>Veh. Inspected</b>	SJD 6774X
<b>Policy No.</b>	GA524877	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	S1M03CKA	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	29/06/2021

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA VIOS (A)	<b>c.c</b>	1497
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2008
<b>Chassis No.</b>	MR053HY9305045515	<b>Colour</b>	GOLD
<b>Odometer</b>	385809 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	185/60 R15	PREMIO	6 mm
<b>L/H Front Tyre</b>	185/60 R15	PREMIO	6 mm
<b>R/H Rear Tyre</b>	185/60 R15	PREMIO	6 mm
<b>L/H Rear Tyre</b>	185/60 R15	PREMIO	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	25/06/2021	<b>Inspection Date</b>	29/06/2021
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**