

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SW WERKZ PTE LTD

25 KAKI BUKIT ROAD4 # 03-65 SYNERGY @KB Singapore 417800

Acknowledged by Repairer

Signature:

Date:

30th JUNE 2021

BENJAMIN CHEW TING ERN
25 KAKI BUKIT ROAD4
03-65 SYNERGY @KB
Singapore 417800

TP AXA.
Xiao Tony.

Accident date: 25th JUNE 2021

Estimated repair cost for vehicle no: SMH5396D SKODA OCTAVIA 2019

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Dented.</i>		\$1,552.00 ✓
2	2	Rear Boot Lid OCTAVIA logo <i>2</i>		\$55.00 ✓
3	1	Rear boot lid emble logo <i>1 New</i>		\$85.00 ✓
4	1	Rear boot lid SKODA logo		\$45.00 ✓
5	1	Rear boot lid inner rubber <i>new</i>		\$237.00 ✓
6	1	Rear Boot Lid Inner Lock <i>Dmg</i>		\$355.20 ✓
7	1	Rear Boot Lid Number Plate <i>Dented</i>		\$50.00 ✓
8	2	Rear Boot Lid Number Plate Lamp <i>1 New 1 Old</i>	\$81.20	\$162.40 ✓
9	1	Rear Boot Lid center moulding <i>new</i>		\$0.00 ✓
10	10	Rear Boot Lid Inner Trim board clips <i>2 New</i>	\$5.00	\$50.00 ✓
11	1	Rear Boot Lid Inner Trim board <i>1 New</i>		\$512.20 ✓
12	2	Rear tail lamp <i>new</i>	\$752.10	\$1,504.20 ✓
13	2	Rear Bumper towing cover <i>new</i>		\$68.00 ✓
14	1	Rear end panel <i>Repair</i>		\$512.20 ✓
15	1	Rear End Panel Top Garnish <i>2 New</i>		\$215.20 ✓
16	1	Rear Bumper <i>Debond</i>		\$1,120.00 ✓
17	2	Rear Bumper Side Bracket <i>1 New 1 Old</i>	\$155.20	\$310.40 ✓
18	1	Rear Bumper reverse sensor <i>Damaged</i>		\$450.00 ✓
19	8	Rear bumper clips <i>new</i>	\$5.00	\$40.00 ✓
20	1	Rear Bumper lower cover <i>Debond</i>		\$385.20 ✓
21	2	rear bumper side retainer <i>new</i>	\$125.00	\$250.00 ✓
22	1	Rear Bumper reinforcement <i>Dented</i>		\$562.00 ✓
23	1	Rear spare tire panel lower cover <i>2 New</i>		\$452.00 ✓
24	1	Rear spare tire panel sealant <i>1 New</i>		\$200.00 ✓

Subtotal :- \$9,173.00

Labour charges

To remove & re-fix cushion	\$120.00 <i>40</i>
To remove & re-fix rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To remove & re-fix rear reverse sensor	\$120.00 <i>50</i>
To Check Wiring System	\$80.00 <i>30</i>
Tuff Kote	\$120.00 <i>50</i>
Panel beating	\$1,000.00 <i>600</i>
Spray painting	\$1,000.00 <i>600</i>

Subtotal :- \$2,610.00
Total :- \$11,783.00

Total: 5963.14
H/s: A.7K-
050m/s.