

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Hyundai

i45

Vehicle Number : SMZ3064E (DOA 24.06.2021)

Quantity	Description	Repairer's Estimate
FRONT		
1	Front Number Plate	\$50 X nn
1	Front bumper Tow Cover	\$30 X nn
1	Headlight bracket	\$20 X nn
1	Front number plate base garnish	\$200 X nn
1	Fog light Cover	\$170 X nn
1	Engine undercover	\$110 X nn
1	Front bumper Grill BR	\$350 105 ✓
1	Front Driving Sensor	\$250 X nn
1	LH Headlamp Bracket	\$450 X nn
1	LH Chasis Garnish	\$500 X nn
1	LH Headlight CVT	\$750 ✓
1	Front bumper bracket BR	\$35 ✓
1	Front Bumper Retainer	\$500 X nn
1	Front LH Fender DD	\$850 566 ✓
1	Front Support	\$300 X nn
1	Front Reinforcement Bar	\$600 X nn
1	Front Bumper BR	\$1,100 538 ✓
1	BONNET	\$1,300 X nn
SIDE		
1	Bumper Strip	\$200 X nn
1	Under Tray Cover	\$350 X nn
1	Rim tyre	\$360 X nn
1	Condenser	\$450 X nn
1	Radiator	\$450 X nn
1	Reinforcement Bar Sponge	\$450 X nn
LABOUR & MISC		
1	Checking of wiring, lighting and resetting	\$300 30
1	Remove and refit rear undercarriage	\$500 X NN
1	Wheel alignment	\$100 X NN
1	Remove and replace damaged parts	\$800 X NN
1	Apply undercoating on repaired and replaced panel	\$800 X NN

1994
-20%
1595.20

1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,500 400
1	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	X \$1,000 NN 400
	Total Repair Cost :	\$14,825

430

= 2025.20

L/S - 1620.16

= 1600

limit \$1500

Steve (LKK)

30/6/11

w/p

L/S

Respray After Spray

4 days