

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 1 July 2021 12:42 pm
To: tlauto
Cc: SUR
Subject: AIG-OD SKW 5517S DOA: 01/06/2021

Dear Candy,

As instructed by our client, please proceed to repair the insured vehicle **SKW 5517S** (Excess \$1,700/-).

Please take note that "TO PUTTY & SPRAY PAINT ON AFFECTED AREAS: revise to \$450/- instead of \$650/- due to front bumper not consistent.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Note: Kindly arrange our surveyor to conduct resurvey of before paint for all panels and parts.

Thank you.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)