



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

*Not Authenitw
Presumy B4 paint*

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

5 days

YOUR REF NO :

30/6/2021

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 01/06/2021

5/7/2021

ESTIMATE

NO : QUOT202106-000042(00)

DATE : 29/06/2021

POLICY NO : 999995580

VEH REG NO : SKW5517S

MAKE/MODEL : MERCEDES BENZ E250 SEDAN
EDITION E (R18 LED)

CHASSIS NO : WDD2120362B212079

ENGINE NO : 27492030443394

REG. DATE : 2015

Estimate Repair Cost to Vehicle No : SKW5517S

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Front door -- RH	1	1,280.00	1,280.00 ✓
2 Front door weatherstrip -- RH	1	198.00	198.00 ✓
3 Side mirror assy -- RH	1	1,850.00	1,850.00 ✓
4 Front fender - RH <i>(Aluminium)</i>	1	590.00	590.00 ✓
5 Front door 'EDITION' emblem - RH	1	68.00	68.00 ✓
6 Front sport rim - RH	1	1,150.00	1,150.00 X
			5,136.00
		Add 10%	513.60
			5,649.60
LABOUR			
7 To transfer RH front door interior mechanism to new door	1	150.00	150.00 60d
8 To check and rectify wiring system	1	100.00	100.00 20d
9 To panel beat RH front door pillar, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00 400d 650d
10 To putty & spray paint on affected areas	1	1,200.00	1,200.00 650d
11 To computerise check wheel alignment	1	120.00	120.00 X
			2,370.00
		TOTAL	S\$ 8,019.60
		ADD GST @ 7%	561.37
		GRAND TOTAL	S\$ 8,580.97

SINGAPORE DOLLAR EIGHT THOUSAND FIVE HUNDRED EIGHTY AND CENTS NINETY-SEVEN ONLY

\$ 5,514.60
XS
1,700.00

\$ 3,814.60
7%
267.02

\$ 4,081.62

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE