

ASS. REC. BY:

62

CTI

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Indeco

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Sm D236317 Reg: 08 Aug 2018

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Blue car

Colour

white

Sp. Reading

64850

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175 / 65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28-06-21

Survey held at

w/s

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

5pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirmed COR \$4459.2 @ 4 days
RED: 2131.40;32%

6590.6

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

1)

Date/Time, File Return to?

2)

Report Filled:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Survey Fee:

Transportation:

3 + RS \$1

Photos

Other:

Indeco

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES & EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

ACCIDENT REPAIR ESTIMATES

Our Ref: OD / SMD2363P

Type of Claim : TP

Vehicle No. : SMD2363P

Make & Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RJT003274

Ins Company : CHINA TAIPING
INSURANCE (S) PTE LTD

Engine No. :

Excess :

Policy No. : SD21V00611/PZ/R01

Date of Accident : 26/06/2021

Time of Accident :

Suggested Days of Repair : 6

Case Owner : BLUECAR EAST ASIA PTE LTD

Repair Estimates

TP Vehicle No. : SJR8985S

Parts (a) Cost / List Price Items \$ 3,583.00

Plus/Less— 20.0% \$ 716.60

Total of Cost / List \$ 4,299.60

(b) Nett Price Items \$ -

Less \$ -

Total of Nett Item \$ -

(c) Special Nett Items \$ 265.00

Total Parts Cost (Appendix A) \$ 4,564.60

Labour (Appendix B) \$ 1,900.00

Total Repair Cost \$ 6,464.60 4459.2

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Que Qiamp - 82880282

Company : LKK

Survey conducted on : 29/6/2021

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : Date:

part by part.
before paint photos.



VEHICLES & EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

FINALIZATION REPAIR COST DETAILS

Vehicle No : SMD2363P Case Owner : BLUECAR EAST ASIA PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RJT003274 Engine No : 0

Date & Time : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price		List Price	Nett Price	S/N
			Unit	Sub-Total			
1	BOOT LID GLASS / <i>BR.</i>	1	\$ 966.00	\$ 966.00			
2	HATCH PININFARINA LOGO / <i>mis.</i>	1	\$ 32.00	\$ 32.00			
3	HATCH PININFARINA EMBLEM / <i>mis.</i>	1	\$ 62.00	\$ 62.00			
4	BOOT LID GLASS SCREW COVER / <i>COVER X</i>	4	\$ 18.00	\$ 72.00			
5	BOOT LID GLASS SCREW COVER / <i>X</i>	4	\$ 2.00	\$ 8.00			
6	BOOT LID GLASS HINGE ASSY <i>X</i>	1	\$ 154.00	\$ 154.00			
7	BOOT LID GLASS DAMPER RH <i>X</i>	1	\$ 36.00	\$ 36.00			
8	BOOT LID GLASS DAMPER LH <i>X</i>	1	\$ 36.00	\$ 36.00			
9	BOOT LID GLASS LOCK <i>X</i>	1	\$ 132.00	\$ 132.00			
10	BOOT LID GLASS LOCK CATCH <i>X</i>	1	\$ 55.00	\$ 55.00			
11	BOOT LID GLASS CATCH COVER <i>X</i>	1	\$ 35.00	\$ 35.00			
12	REAR BOOT LID STICKER / <i>mis.</i>	1		\$ -			\$ 40.00
13	REAR WEATHER STRIP / <i>mis.</i>	1	\$ 84.00	\$ 84.00			
14	REAR TRIM / <i>mis.</i>	1	\$ 128.00	\$ 128.00			
15	REAR BUMPER / <i>deformed</i>	1	\$ 1,405.00	\$ 1,405.00			
16	REAR BUMPER REINFORCEMENT <i>X NN</i>	1	\$ 82.00	\$ 82.00			
17	REAR BUMPER REINFORCEMENT BRACKET <i>X NN</i>	2	\$ 43.00	\$ 86.00			
18	REAR BUMPER NUMBER PLATE LIGHT <i>APC</i>	2	\$ 105.00	\$ 210.00	105		
19	REAR BUMPER MARKETING DECAL <i>APC</i>	1	NEC				\$ 180.00
20	REAR NUMBER PLATE / <i>mis</i>	1					\$ 45.00
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

TOTAL

\$ 3,375.00 \$ 3,583.00 \$ - \$ - \$265.00

2782

15%: 3199.3

Labour

Vehicle No. :	<u>SMD2363P</u>
Make & Model :	BLUECAR

Case Owner
Year of Manufacture

**BLUECAR
EAST ASIA
PTE LTD**
2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary