

ASS. REC. BY:

62

VET.

CTI

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

Indeco

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Sm D236317 Regd: 08 Aug 2018

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Blue car

Colour

white

Sp. Reading

64850

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

175 / 65 R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28-06-21

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

1)

Date/Time, File Return to?

2)

Report Form:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Survey Fee:

Transportation:

3 + RS \$1

Photos

Other:

**Indeco**

No. 39 DEFU LANE 12, SINGAPORE 539139

VEHICLES &amp; EQUIPMENT DIVISION Tel: (65) 382 2736 FAX: (65) 6382 2817

**ACCIDENT REPAIR ESTIMATES**

Our Ref: OD / SMD2363P

Type of Claim : TP

Vehicle No. : SMD2363P

Make &amp; Model : BLUECAR

Year of Manufacture : 2017

Chassis No. : VL4BCEB4RJT003274

Ins Company : CHINA TAIPING  
INSURANCE (S) PTE LTD

Engine No. :

Excess :

Policy No. : SD21V00611/PZ/R01

Date of Accident : 26/06/2021

Time of Accident :

Suggested Days of Repair : 6

Case Owner : BLUECAR EAST ASIA PTE LTD

**Repair Estimates**

TP Vehicle No. : SJR8985S

|                                   |             |
|-----------------------------------|-------------|
| Parts (a) Cost / List Price Items | \$ 3,583.00 |
| Plus/Less— 20.0%                  | \$ 716.60   |
| Total of Cost / List              | \$ 4,299.60 |
| (b) Nett Price Items              | \$ -        |
| Less                              | \$ -        |
| Total of Nett Item                | \$ -        |
| (c) Special Nett Items            | \$ 265.00   |
| Total Parts Cost (Appendix A)     | \$ 4,564.60 |
| Labour (Appendix B)               | \$ 1,900.00 |
| Total Repair Cost                 | \$ 6,464.60 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

|                                                                                        |                           |
|----------------------------------------------------------------------------------------|---------------------------|
| Name of Surveyor                                                                       | : Que Qiamp - 82880282    |
| Company                                                                                | : LKK                     |
| Survey conducted on                                                                    | : 29/6/2021               |
| Remarks By Surveyor                                                                    |                           |
| (a) The repair of this vehicle is authorized / is not authorized until further notice. |                           |
| (b) Recommended Days of Repair                                                         | : 4 day(s)                |
| (c) Resurvey                                                                           | : Required / Not Required |
| (d) Excess                                                                             | : \$                      |
| (e) Signature of surveyor                                                              | : Date:                   |

part by part.  
before paint photos.



VEHICLES &amp; EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

**FINALIZATION REPAIR COST DETAILS**

Vehicle No : SMD2363P Case Owner : BLUECAR EAST ASIA PTE LTD

Make & Model : BLUECAR Year Manufacture : 2017

Chassis No : VL4BCEB4RJT003274 Engine No : 0

Date & Time : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description                            | QTY | Cost Price  |             | List Price | Nett Price | S/N       |
|------|---------------------------------------------|-----|-------------|-------------|------------|------------|-----------|
|      |                                             |     | Unit        | Sub-Total   |            |            |           |
| 1    | BOOT LID GLASS / <i>BR.</i>                 | 1   | \$ 966.00   | \$ 966.00   |            |            |           |
| 2    | HATCH PININFARINA LOGO / <i>mis.</i>        | 1   | \$ 32.00    | \$ 32.00    |            |            |           |
| 3    | HATCH PININFARINA EMBLEM / <i>mis.</i>      | 1   | \$ 62.00    | \$ 62.00    |            |            |           |
| 4    | BOOT LID GLASS SCREW COVER / <i>COVER X</i> | 4   | \$ 18.00    | \$ 72.00    |            |            |           |
| 5    | BOOT LID GLASS SCREW COVER / <i>X</i>       | 4   | \$ 2.00     | \$ 8.00     |            |            |           |
| 6    | BOOT LID GLASS HINGE ASSY <i>X</i>          | 1   | \$ 154.00   | \$ 154.00   |            |            |           |
| 7    | BOOT LID GLASS DAMPER RH <i>X</i>           | 1   | \$ 36.00    | \$ 36.00    |            |            |           |
| 8    | BOOT LID GLASS DAMPER LH <i>X</i>           | 1   | \$ 36.00    | \$ 36.00    |            |            |           |
| 9    | BOOT LID GLASS LOCK <i>X</i>                | 1   | \$ 132.00   | \$ 132.00   |            |            |           |
| 10   | BOOT LID GLASS LOCK CATCH <i>X</i>          | 1   | \$ 55.00    | \$ 55.00    |            |            |           |
| 11   | BOOT LID GLASS CATCH COVER <i>X</i>         | 1   | \$ 35.00    | \$ 35.00    |            |            |           |
| 12   | REAR BOOT LID STICKER / <i>mis.</i>         | 1   |             | \$ -        |            |            | \$ 40.00  |
| 13   | REAR WEATHER STRIP / <i>cat.</i>            | 1   | \$ 84.00    | \$ 84.00    |            |            |           |
| 14   | REAR TRIM / <i>car.</i>                     | 1   | \$ 128.00   | \$ 128.00   |            |            |           |
| 15   | REAR BUMPER                                 | 1   | \$ 1,405.00 | \$ 1,405.00 |            |            |           |
| 16   | REAR BUMPER REINFORCEMENT ?                 | 1   | \$ 82.00    | \$ 82.00    |            |            |           |
| 17   | REAR BUMPER REINFORCEMENT BRACKET ?         | 2   | \$ 43.00    | \$ 86.00    |            |            |           |
| 18   | REAR BUMPER NUMBER PLATE LIGHT <i>APC</i>   | 2   | \$ 105.00   | \$ 210.00   |            |            |           |
| 19   | REAR BUMPER MARKETING DECAL <i>APC</i>      | 1   |             |             |            |            | \$ 180.00 |
| 20   | REAR NUMBER PLATE / <i>mis. APC</i>         | 1   |             |             |            |            | \$ 45.00  |
| 21   |                                             |     |             |             |            |            |           |
| 22   |                                             |     |             |             |            |            |           |
| 23   |                                             |     |             |             |            |            |           |
| 24   |                                             |     |             |             |            |            |           |
| 25   |                                             |     |             |             |            |            |           |
| 26   |                                             |     |             |             |            |            |           |
| 27   |                                             |     |             |             |            |            |           |
| 28   |                                             |     |             |             |            |            |           |
| 29   |                                             |     |             |             |            |            |           |
| 30   |                                             |     |             |             |            |            |           |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**

\$ 3,375.00 \$ 3,583.00 \$ - \$ - \$265.00



## Labour

|                |                 |
|----------------|-----------------|
| Vehicle No. :  | <u>SMD2363P</u> |
| Make & Model : | BLUECAR         |

Case Owner  
Year of Manufacture

**BLUECAR  
EAST ASIA  
PTE LTD**  
**2017**

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary