

Steve (LKK)  
30/6/21  
W/P . 4 days  
L/S , Respray After Spray

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Suzuki

SX4

Vehicle Number : SJP9294G (DOA 27.06.2021)

| Quantity                   | Description  | Repairer's Estimate   |
|----------------------------|--|-----------------------|
| <b>BACK</b>                |  |                       |
| 1                          | REVERSE SENSOR <b>7^</b>   | \$200 <b>-</b>        |
| 1                          | END PANEL GARNISH  | \$230 <b>x nn</b>     |
| 1                          | TAIL LAMP LOWER BRACKET  | \$120 <b>x nn</b>     |
| 1                          | REAR LEFT TAILLIGHT BRACKET  | \$120 <b>x nn</b>     |
| 1                          | REAR LEFT WHEEL BEARING  | \$150 <b>x nn</b>     |
| 1                          | SPARE TYRE BOARD   | \$80 <b>x nn</b>      |
| 1                          | BOOTLID WEATHERSTRIP   | \$350 <b>x nn</b>     |
| 1                          | BUMPER BRACKET <b>BR</b>   | \$150 <b>90 -</b>     |
| 1                          | REAR LEFT ABSORBER   | \$230 <b>x nn</b>     |
| 1                          | REAR LEFT MUDGUARD   | \$80 <b>x nn</b>      |
| 1                          | LEFT BOOTLID LAMP  | \$200 <b>x nn</b>     |
| 1                          | LEFT TAIL LIGHT  | \$200 <b>x nn</b>     |
| 1                          | REAR UNDERCARRIAGE <b>(lower Spoiler)</b>  | \$900 <b>300 - BR</b> |
| 1                          | BOOT CHROME GARNISH  | \$250 <b>x nn</b>     |
| 1                          | REAR BUMPER <b>DD</b>  | \$650 <b>546 ✓</b>    |
| 1                          | END PANEL <b>R</b>   | \$800 <b>x nn</b>     |
| <b>LABOUR &amp; MISC</b>   |  |                       |
| 1                          | Checking of wiring, lighting and resetting   | \$300 <b>30</b>       |
| 1                          | Remove and refit rear undercarriage  | \$500 <b>x nn</b>     |
| 1                          | Wheel alignment  | \$100 <b>x nn</b>     |
| 1                          | Remove and replace damaged parts   | \$800 <b>x nn</b>     |
| 1                          | Apply undercoating on repaired and replaced panel  | \$800 <b>30 -</b>     |
| 1                          | Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure                 | \$1,500 <b>300 -</b>  |
| 1                          | Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident | \$1,000 <b>400 ✓</b>  |
| <b>Total Repair Cost :</b> |  | <b>\$9,710</b>        |

1136  
-15%  
965.60

760  
= 1725.60

L/S - 1380.48  
= 1400 ✓