

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI21007159/Etf3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	С	Date:	01/09/2021	
			C	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLF 8833L	Veh. Inspected		SJP 9294G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10010694/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		29/06/2021	
2.						
	Make & Model	SUZUKI SX4	c.c		1586	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	JSAGYC21S00203721	Colour		RED	
	Odometer	296157 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/65 R15	DUNLOP		4 mm	
	L/H Front Tyre	175/65 R15	DUNLOP		4 mm	
	R/H Rear Tyre	175/65 R15	DUNLOP		4 mm	
	L/H Rear Tyre	175/65 R15	DUNLOP		4 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	27/06/2021	Inspection Date		30/06/2021	
	Survey held at AUBURN AUTO PTE LTD					
		176 SIN MING DRIVE #04-18 SIN MING AUTOCARE SINGAPORE 575721				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: