

Steve (LKK)
30/6/21
W/P . 4 days
L/S , Resurvey After Spray

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Suzuki

SX4

Vehicle Number : SJP9294G (DOA 27.06.2021)

Quantity	Description	Repairer's Estimate
BACK		
1	REVERSE SENSOR 7^	\$200 -
1	END PANEL GARNISH	\$230 X
1	TAIL LAMP LOWER BRACKET	\$120 X
1	REAR LEFT TAILLIGHT BRACKET	\$120 X
1	REAR LEFT WHEEL BEARING	\$150 X
1	SPARE TYRE BOARD	\$80 X
1	BOOTLID WEATHERSTRIP	\$350 X
1	BUMPER BRACKET BR	\$150 90 -
1	REAR LEFT ABSORBER	\$230 X
1	REAR LEFT MUDGUARD	\$80 X
1	LEFT BOOTLID LAMP	\$200 X
1	LEFT TAIL LIGHT	\$200 X
1	REAR UNDERCARRIAGE (lower Spoiler)	\$900 300 - BR
1	BOOT CHROME GARNISH	\$250 X
1	REAR BUMPER DD	\$650 546 ✓
1	END PANEL R	\$800 X
LABOUR & MISC		
1	Checking of wiring, lighting and resetting	\$300 30
1	Remove and refit rear undercarriage	\$500 X
1	Wheel alignment	\$100 X
1	Remove and replace damaged parts	\$800 X
1	Apply undercoating on repaired and replaced panel	\$800 30 -
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,500 300 -
1	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000 400 ✓
Total Repair Cost :		\$9,710

1136
-15%
965.60

760
= 1725.60

L/S - 1380.48
= 1400 -

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: