

Steve (LKK)  
30/6/21  
W/P . 4 days  
L/S , Respray After Spray

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Make & Model : Suzuki

SX4

Vehicle Number : SJP9294G (DOA 27.06.2021)

Quantity	Description	Repairer's Estimate
<b>BACK</b>		
1	REVERSE SENSOR <b>7^</b>	\$200 <b>✓</b>
1	END PANEL GARNISH	\$230 <b>X</b>
1	TAIL LAMP LOWER BRACKET	\$120 <b>X</b>
1	REAR LEFT TAILLIGHT BRACKET	\$120 <b>X</b>
1	REAR LEFT WHEEL BEARING	\$150 <b>X</b>
1	SPARE TYRE BOARD	\$80 <b>X</b>
1	BOOTLID WEATHERSTRIP	\$350 <b>X</b>
1	BUMPER BRACKET <b>BR</b>	\$150 <b>90 ✓</b>
1	REAR LEFT ABSORBER	\$230 <b>X</b>
1	REAR LEFT MUDGUARD	\$80 <b>X</b>
1	LEFT BOOTLID LAMP	\$200 <b>X</b>
1	LEFT TAIL LIGHT	\$200 <b>X</b>
1	REAR UNDERCARRIAGE <b>(lower Spoiler)</b>	\$900 <b>300 ✓ BR</b>
1	BOOT CHROME GARNISH	\$250 <b>X</b>
1	REAR BUMPER <b>DD</b>	\$650 <b>546 ✓</b>
1	END PANEL <b>R</b>	\$800 <b>X</b>
<b>LABOUR &amp; MISC</b>		
1	Checking of wiring, lighting and resetting	\$300 <b>30</b>
1	Remove and refit rear undercarriage	\$500 <b>X</b>
1	Wheel alignment	\$100 <b>X</b>
1	Remove and replace damaged parts	\$800 <b>X</b>
1	Apply undercoating on repaired and replaced panel	\$800 <b>30 ✓</b>
1	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,500 <b>300 ✓</b>
1	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000 <b>400 ✓</b>
<b>Total Repair Cost :</b>		<b>\$9,710</b>

1136  
-15%  
965.60

760  
= 1725.60

L/S - 1380.48  
= 1400 ✓