

RICO60 AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -%20	
SN	
Labour	
Total	
Lump Sum	
ERV	44K

TO: AXA

Vehicle No : SLT 2289 L

Make & Model : HONDA ODYSSEY

DATE: 28/6/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	HEAD LAMP LH <i>cracked</i>	1	\$ 2,257.90	\$ 2,257.90
2	HEAD LAMP LOWER BRACKET LH <i>cracked</i>	1	\$ 214.00	\$ 214.00
3	FRONT BUMPER <i>Distorted</i>	1	\$ 845.00	\$ 845.00
4	FRONT BUMPER SIDE RETAINER LH <i>Damaged</i>	2	\$ 125.00	\$ 250.00
5	FRONT BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 589.00	\$ 589.00
6	FRONT BUMPER FOG LAMP LH <i>cracked</i>	1	\$ 452.00	\$ 452.00
7	FRONT BUMPER FOG LAMP BRACKET LH <i>cracked</i>	1	\$ 155.00	\$ 155.00
8	FRONT BUMPER FOG LAMP COVER LH <i>cracked</i>	1	\$ 161.00	\$ 161.00
9	FRONT BUMPER LOWER GRILLE <i>cracked</i>	1	\$ 123.00	\$ 123.00
10	FRONT BUMPER LOWER SIDE DIFFUSER LH <i>cracked</i>	1	\$ 199.50	\$ 199.50
11	FRONT BUMPER LOWER DIFFUSER MLD <i>cracked</i>	1	\$ 102.00	\$ 102.00
12	FRONT BUMPER UNDER COVER <i>Deformed</i>	1	\$ 320.00	\$ 320.00
13	BATTERY GARNISH BRACKET <i>new</i>	1	\$ 125.00	\$ 125.00
14	FRONT AIR DUCT <i>cracked</i>	1	\$ 186.00	\$ 186.00
15	FRONT GRILLE BADGE <i>new</i>	1	\$ 185.00	\$ 185.00
16	FRONT GRILLE CHROME <i>new</i>	1	\$ 658.00	\$ 658.00
17	FRONT GRILLE BASE <i>cracked</i>	1	\$ 665.00	\$ 665.00
18	SUPPORT PANEL TOP GARINSH <i>cracked</i>	1	\$ 156.00	\$ 156.00
19	AIR CLEANER <i>new</i>	1	\$ 625.00	\$ 625.00
20	AIR RESULATOR BOX <i>cracked</i>	1	\$ 662.00	\$ 662.00
21	FRONT FENDER LH <i>Dented</i>	1	\$ 875.00	\$ 875.00
22	FRONT FENDER BOTTOM PROTECTOR LH <i>cracked</i>	1	\$ 120.00	\$ 120.00
23	FRONT FENDER TOP INNER GARNISH LH <i>new</i>	1	\$ 225.30	\$ 225.30
24	FRONT FENDER TOP CHROME LH <i>new</i>	1	\$ 276.30	\$ 276.30
25	FRONT FENDER INNER SHIELD LH <i>new</i>	1	\$ 215.00	\$ 215.00
26	FRONT EXTENTION PANEL OUTE LH <i>new</i>	1	\$ 337.50	\$ 337.50

LKK

27	FRONT EXTENTION PANEL INNER LH <i>Regr</i>	1	\$ 349.00	\$ 349.00	+
28	FRONT DOOR LH <i>Nbe m</i>	1	\$ 1,542.00	\$ 1,542.00	+
29	FRONT DOOR PROTECTOR <i>Delnd</i>	1	\$ 265.00	\$ 265.00	✓
30	FRONT DOOR SIDE MIRROR WITH CAMERA LH <i>Nbe m</i>	1	\$ 1,452.00	\$ 1,452.00	x.
31	FRONT ABSORBER LH <i>Nbe m</i>	1	\$ 444.60	\$ 444.60	+
32	FRONT LOWER ARM LH <i>But</i>	1	\$ 672.30	\$ 672.30	332
33	FRONT KNUCKLE ARM LH <i>Nbe m</i>	1	\$ 658.00	\$ 658.00	X
34	FRONT WHEEL BEARING LH <i>Regrd</i>	1	\$ 289.00	\$ 289.00	165
35	FRONT ANTI ROLL BAR LINK LH <i>3 NH</i>	1	\$ 269.80	\$ 269.80	+
36	FRONT STEERING RICK <i>Nbe m</i>	1	\$ 2,144.00	\$ 2,144.00	+

7402.40
5921.92

Subtotal : \$ 19,065.20

Less 20% \$ 3,813.04

Parts Total : \$ 15,252.16

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	FRONT BUMPER CLIP SET <i>Nbe m</i>	1	\$ 50.00	\$ 50.00	30
2	FRONT BUMPER UNDER CLIP <i>Nbe m</i>	1	\$ 40.00	\$ 40.00	30
3	FRONT GRILLE CLIP SET <i>Nbe m</i>	1	\$ 50.00	\$ 50.00	20
4	FRONT GRILLE 360 CAMERA <i>Nbe m</i>	1	\$ 650.00	\$ 650.00	x.
5	FRONT FENDER INNER SHIELD CLIP SET <i>Nbe m</i>	1	\$ 40.00	\$ 40.00	+
6	FRONT FENDER BOTTOM PROTECTOR CLIP <i>Nbe m</i>	1	\$ 30.00	\$ 30.00	10
7	FRONT EXTENTION PANEL INNER SEALANT <i>3 NH</i>	1	\$ 80.00	\$ 80.00	x
8	FRONT EXTENTION PANEL OUTER SEALANT <i>Nbe m</i>	1	\$ 80.00	\$ 80.00	x
9	HEAD LAMP BULK SET <i>Nbe m</i>	1	\$ 80.00	\$ 80.00	x.
10	FRONT DOOR PROTECTOR CLIPS <i>Nbe m</i>	1	\$ 50.00	\$ 50.00	20.
11	FRONT RIM BBS <i>ut</i>	1	\$ 4,800.00	\$ 4,800.00	760.
12	FRONT TYRE LH <i>Nbe m</i>	1	\$ 600.00	\$ 600.00	x
13	HORN <i>Nbe m</i>	1	\$ 200.00	\$ 200.00	x
				\$ 6,750.00	

LABOUR

PRICE

PANEL BEATING, REMOVAL AND REPLACING PARTS

\$ ~~1,500.00~~

TO SPRAY PAINT AFFECTED AREA

\$ ~~1,400.00~~

TO PERFORM LIGHTING & WIRING CHECK

\$ ~~100.00~~

TO APPLY ANTI-RUST & TUFF KOTE

\$ ~~200.00~~

REMOVE AND INSTALL FRONT DOOR PART

\$ ~~180.00~~

REMOVE AND INSTALL FRONT UNDER CARRIAGE

\$ ~~650.00~~

TO CHECK FOUR WHEEL ALIGMENT

\$ ~~100.00~~

REMOVE AND INSTALL CARPET, SEAT AND INTERIOR

\$ 350.00

LABOUR TOTAL \$ 4,480.00

	Total Parts Cost	\$ 22,002.16
	Total Labour Cost	\$ 4,480.00
	Total Repair Cost	\$ 26,482.16

APPROVED DETAILS

NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

Adrian King.
 L/S 30/06/21.

06 Days.

total: 8521.92

L/S: 6.8k ✓

**LKK Auto Consultants hence notify
 the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: