

SMRT Accident Vehicle Repair Estimates

| |
|---|
| SMRT Automotive Services Pte Ltd |
| 60 Woodlands Industrial Park E4, Singapore 75 |
| FAX Number : 63685592 |
| Estimator Telephone Number : 68662623 |
| Accident Reporting Number : 68662672 |

Date Generated : 28/06/2021


User ID : GohKK2

Section A - Accident Details

| | |
|------------------------------------|---|
| Registration Number | SMB184M |
| Case Reference Number | BUS/06/21/7007 |
| Registration Date | 18/11/2011 |
| Company Type | SMRT Buses Ltd |
| Make | MERCEDES |
| Model | CITARO O530 |
| Name of Driver | Mokhtar Morris Bin Musa |
| Type of Accident | Head to Rear |
| Accident Date and Time | 5/6/2021 8:19 AM |
| Accident Reported Date and Time | 5/6/2021 10:15 AM |
| Is Surveyor Required? | No |
| Survey by | |
| Vehicle is Towed Back? | No |
| Towed Back Date and Time | |
| Replacement Vehicle issued? | No |
| Job Card Number | |
| Special Instruction to ARC, if any | SMB184M - REAR PORTON GBK1112Y (TP) - INSURED WITH AIG |
| Prepared Date and Time | 28/6/2021 11:09 AM |
| Chassis Number | WEB62808323122712 |
| Mileage | |
| Work Shop | |
| Repair Completion Date and Time | |

Section B - Summary of Repair Estimates

Summary of Repair Estimates

| | Quotation from ARC | Adjusted by Surveyor, if applicable |
|------------------------------|---|-------------------------------------|
| Total Labour Cost | \$2,650.00 | \$0.00 |
| Total Spray Cost | \$956.00 | \$0.00 |
| Total Spare Part Cost | \$11,080.35 | \$0.00 |
| Total Other Cost | \$200.00 | \$0.00 |
| TOTAL COST | \$14,886.35 | \$0.00 |
| Lump Sum Total | \$14,900.00 | \$0.00 |
| Number of Repair Days | 7.0 | |
| Prepared / Adjusted By | ARC Manager Team | |
| ARC / Surveyor Sign Off Date | 28/06/2021 11:43 AM | |
| Signature |  | <input checked="" type="checkbox"/> |
| Remarks | | |

Section C - Quotation and Accident Invoice Details

| | | | |
|------------------|--|----------------|--|
| Quotation Number | | Invoice Number | |
| Quotation Date | | Invoice Date | |
| Invoice Amount | | Prepared Date | |

SMRT Accident Vehicle Repair Estimates

| |
|---|
| SMRT Automotive Services Pte Ltd |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592 |
| Estimator Telephone Number : 68662623 |
| Accident Reporting Number : 68662672 |

Date Generated : 28/06/2021

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

| Job Scope | Quotation from AR | Adjusted by Surveyor, if applicable |
|---|-------------------|-------------------------------------|
| TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. | \$2,650.00 | 2120 |
| Total Labour | \$2,650.00 | |

Part 2 - Spray Painting & Panel Beating Related Works

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|---|--------------------|-------------------------------------|
| PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS | \$956.00 | 694 |
| Total Spray Painting & Panel Beating | \$956.00 | |

Part 3 - Other Costs - Accident and Accident Repair Related Expense

| Job Scope | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------|--------------------|-------------------------------------|
| TOWING CHARGE | \$200.00 | receipt |
| Total Other Costs | \$200.00 | |

Part 4 - Spare Parts / Material Usage

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|---------------|---|----------|-----------------|--------------|------------------|--------------------|-------------------|
| 6010113 | Body | 6287502974 | FLAP:REAR END, FOR MB CITARO BUS | 1.00 | \$5,573.10 | 10.00 | \$5,015.79 | Replace | bt |
| | | | STICKER SMRT | 1.00 | \$75.00 | 0.00 | \$75.00 | Replace | rm |
| | | | STICKER 60KM/H | 1.00 | \$5.00 | 0.00 | \$5.00 | Replace | rm |
| 6009879 | VE | 0008206864 | LAMP, TAIL: REAR LH, FOR MB CITARO O530 | 1.00 | \$1,261.71 | 10.00 | \$1,135.54 | Replace | 50 |
| 6009893 | VM | 6288208314 | BRACKET: LH, FOR MB CITARO O530 | 1.00 | \$219.09 | 10.00 | \$197.18 | Replace | ? |
| 6010012 | VE | 0005446911 | LAMP, SIDE MARKER: FOR MB CITARO O530 BUS | 1.00 | \$94.50 | 10.00 | \$85.05 | Replace | sc |
| 6010965 | | 906 200 60 01 | WATER PUMP | 1.00 | \$1,480.00 | 10.00 | \$1,332.00 | Replace | sc |
| | | | OIL FILTER HOUSING | 1.00 | \$800.00 | 10.00 | \$720.00 | Replace | con |
| 6012247 | | | COOLANT: ANTIFREEZE (60L/DR) - MB OC500 | 1.00 | \$871.25 | 0.00 | \$871.25 | Replace | rm |
| 6010559 | | | belt for water pump, md 0530 citaro bus | 1.00 | \$103.15 | 10.00 | \$92.84 | Replace | aut |
| 6009907 | Body | | BUMPER: REAR, CENTR E, FOR MB CITARO O530 | 1.00 | \$1,791.33 | 10.00 | \$1,612.20 | Replace | con |
| 6009908 | BODY LH | 6288850005 | BUMPER: REAR, LH, FOR MB CITARO O530 | 1.00 | \$837.84 | 10.00 | \$754.06 | Replace | con |
| | | 5120647012 | REAR MEMBER SUB-ASSY, RR | 1.00 | \$2,171.70 | 10.00 | \$1,954.53 | Replace | bt |
| Total | | | | | \$15,283.67 | | \$13,850.44 | | |

Added Spare Parts / Material Usage After Surveyor Signed off

| Part Number | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|-------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| Total | | | | | | | | | |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pam
Hf 9000068

6 days

45

28/06/21 @ 1450

Reg after repair