

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBJ5830L

MAKE & MODEL : NISSAN / NV350 PANEL VAN 2.5 SMT 5DR

CHASSIS NO : JN1MC2E26Z0031157

DATE : 29 JUN 2021

CLAIM TYPE : OD CLAIM

D.O.A : 25 JUN 2021

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	COST PRICE	TOTAL PRICE
1	1	FRONT BUMPER		\$ 280.00	\$ 280.00
2	2	FRONT BUMPER SIDE RETAINER LH/RH		\$ 75.00	\$ 150.00
3	1	FRONT BUMPER TOWING COVER		\$ 20.00	\$ 20.00
4	2	FRONT FOG LAMP GARNISH LH/RH		\$ 65.00	\$ 130.00
5	1	FRONT BUMPER CENTRE BEAM		\$ 95.00	\$ 95.00
6	1	FRONT BUMPER REINFORCEMENT		\$ 350.00	\$ 350.00
7	1	FRONT BUMPER LOWER GRILLE		\$ 380.00	\$ 380.00
8	1	FRONT GRILLE		\$ 350.00	\$ 350.00
9	1	FRONT GRILLE EMBLEM		\$ 55.00	\$ 55.00
10	2	HEADLAMP ASSY LH/RH		\$ 280.00	\$ 560.00
11	1	FRONT PANEL		\$ 650.00	\$ 650.00
12	1	FRONT CORNER PANEL LH/RH		\$ 195.00	\$ 195.00
13	1	STEP GARNISH LH/RH		\$ 95.00	\$ 95.00
14	1	AIR GUIDE LOWER		\$ 48.00	\$ 48.00
15	1	INTERCOOLER		\$ 1,600.00	\$ 1,600.00
16	1	INTERCOOLER AIR GUIDE		\$ 130.00	\$ 130.00
				\$ 4,668.00	\$ 5,088.00

LKK Auto Consultants hence notify

the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONDITION /
REMARKS

TOTAL PRICE	\$ 3985	\$ 5,088.00
PLUS 10%	\$ 4383.50	\$ 508.80
SUB TOTAL PRICE	\$	\$ 5,596.80

S/No.	QTY	DESCRIPTION	UNIT S/NETT	TOTAL S/NETT
1	1	FRONT BUMPER CLIPS SET	\$ 50.00	\$ 50.00
2	1	FRONT GRILLE CLIPS SET	\$ 50.00	\$ 50.00
3	1	FRONT NO. PLATE	\$ 45.00	\$ 45.00
4	1	RADIATOR COOLANT	\$ 50.00	\$ 50.00
5	1	TOWING FEE	\$ 70.00	\$ 70.00

TOTAL S/NETT \$ 265.00 \$ 145 265.00

Labour Charges

1	To knock and panel beat damaged panels & replace damaged parts.	\$ 1,000.00	\$ 600
2	To check and rectify lighting & wiring harness	\$ 50.00	\$ 30
3	To Spray painting Front Portions & other affected areas.	\$ 800.00	\$ 600.
4	To remove and intercooler, hoses and other components.	\$ 150.00	\$ 100.
5	To do artwork company sticker.	\$ 350.00	\$ 200

TOTAL LABOUR

Total Cost of Repairs

(Total parts + Total S/Nett + Total Labour Cost)

\$ 1530	\$ 2,350.00
\$	\$ 8,211.80

Taufik 97495749
 up: 30/6/21 @ 420 pm
 Not Authorised, Revert.
 Ex: to be advise.
 05 days
 4/5 Resurvey after repair
 Taufik @ lkk auto.com