

ASS. REC. BY:

Steve

REF

CS/CTI 21007169/EC

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP/WS/TP RES/OD-RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. DMCVSNW00011352100

Claims No. SNM21D203585/C01

Sum Insured:


Excess:

1500

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.:

Yes or No

Cum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

XE 4617J

Yr Regn:

24/1/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

☒ Truck / Trailer or

Make:

Mitsubishi Fuso FV700

Colour:

White

A/C: Insured / Std / NI / N

Sp. Reading

N/A

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

FV700/ETA 990 74

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

P:

295/80R225

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ALL ROUND

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

24/6/21

D.O.A.

30/6/21

Survey held at

Gold Bell

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-105K

30/06/21 @ 4.31pm revert to Irene Tay via Merimen.

01/07/21 @ 9.36am So Chow informed C/A via Merimen.

01/07/21 @ 10.22am Informed Catherine C/A & ex: \$1500 by email.

23/07/21 @ 4.19pm confirmed with Catherine final fig \$22929.25, 5 days. (Red \$3957.75, 15%)

Date/Time, File, Pass to:



: Prel. Report

23/07 Typist



: Final Report

Date/Time, File Return to:

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

\$ + RS, SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (%)



: Weekend (%)

Special Notes:

MER-OD

Total Amount / L.P. / C.P.

22929.25

6/30/2021

Repairer Estimates


GOLDBELL
ENGINEERING

 Industrial Vehicles.
 20,000 Served. And Counting.
GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6881 0007 Fax: +65 6881 3876 (Sales)

Fax: +65 6883 0425 (Service) +65 6882 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg No. 198003963G

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	XE4617J
Policy No:	DMCVSNW00011352100	Date of Loss:	24/06/2021
Vehicle Reg. No.:	XE4617J	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SAT.S PTE. LTD.		
Driver:	KARUPPIAH PERIYAKARUPPAN		

Make/Model:	mitsubishi fuso super great FV, 12.9 D FV51JKM4RDEA (M)	Vehicle Reg. Date:	24/01/2019
Vehicle Colour:	WHITE	Chassis No:	FV70HJA00074
Engine No:	470912C0357814		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		

Present Location: **GOLDBELL ENGINEERING PTE LTD (TUAS)**

COST OF CLAIMS	Amount
Parts	12,756.85
Miscellaneous Items	375.00
Labour	5,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	18,931.85
+ GST 7.00% (\$\$)	1,325.23
Nett Amount (\$\$)	20,257.08

This claim is handled by: CHONG KAI LING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 28 Jun 2021)
Parts: N/A MITSUBISHI FUSO SUPER GREAT FV 12.9 D FV51JKM4RDEA (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FORNT PANEL / <i>DD</i>	0.00	0.00	*2,440.13 F
2	1		*MARK, FUSO / <i>DD</i>	0.00	0.00	*319.10 F
3	1		*MARK, 3-DIA / <i>DD</i>	0.00	0.00	*145.54 F
4	1		*EMBLEM, SUPER GREAT / <i>DD</i>	0.00	0.00	*51.00 F
5	1		*GRILLE ASSY, RADIATOR / <i>DD</i>	0.00	0.00	*575.39 F
6	1		*GRILLE ASSY, FRT UNDER / <i>DD</i>	0.00	0.00	*182.40 F
7	1		*PANEL, CAB FR CORNER, RH / <i>DD</i>	0.00	0.00	*564.77 F
8	1		*SEAL, DOOR OPENING RH / <i>DD</i>	0.00	0.00	*65.70 F
9	1		*SHIELD, C/PNL LOWER LH (BEZEL) / <i>DD</i>	0.00	0.00	*30.91 F
10	1		*SHIELD, C/PNL LOWER RH (BEZEL) / <i>DD</i>	0.00	0.00	*52.55 F
11	1		*BUMPER, FRT / <i>DD</i>	0.00	0.00	*2,645.41 F
12	1		*BEZEL, HEADLAMP -RH / <i>DD</i>	0.00	0.00	*316.98 F
13	1		*BEZEL, HEADLAMP -LH / <i>DD</i>	0.00	0.00	*316.98 F
14	1		*COVER, FR BUMPER -RH / <i>DD</i>	0.00	0.00	*125.28 F
15	1		*COVER, FR BUMPER -LH / <i>DD</i>	0.00	0.00	*125.28 F
16	1		*COVER, FR BUMPER CTR / <i>DD</i>	0.00	0.00	*359.47 F
17	1		*PROTECTOR, STEP LWR LH / <i>DD</i>	0.00	0.00	*122.08 F
18	1		*PROTECTOR, STEP LWR RH / <i>DD</i>	0.00	0.00	*117.91 F
19	2	1	*BRACKET, FR FOG LAMP / <i>DD</i>	0.00	0.00	*15.08 F
20	1		*STAY, HEADLAMP -LH / <i>DD</i>	0.00	0.00	*340.22 F
21	1		*STAY, HEADLAMP -RH / <i>DD</i>	0.00	0.00	*340.22 F
22	1		*PROTECTOR, STEP UPPER / <i>DD</i>	0.00	0.00	*144.43 F
23	1		*HEADLAMP ASSY LH / <i>DD</i>	0.00	0.00	*1,004.36 F
24	1		*HEADLAMP ASSY RH / <i>DD</i>	0.00	0.00	*1,004.36 F
25	1		*LAMP ASSY, FOG, FR LH / <i>DD</i>	0.00	0.00	*346.40 F
26	1		*LAMP ASSY, FOG, FR RH / <i>DD</i>	0.00	0.00	*346.40 F
27	1		*OIL COOLER / <i>DD</i>	0.00	0.00	*658.50 F

F=Franchise part.

Total Parts (S\$)

12,756.85

Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

6/30/2021

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 COMPANY STICKER ✓ M
2 1 FRONT NUMBER PLATE ✓ OT

222 350.00
25.00 ✓

Sub Total (S\$) 375.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC 600 X 5
2 TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK
3 TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC 350 X 3

New 3000 3,600.00

New 150 200.00

New 1050 2,000.00

Gross Labour Cost (S\$) 5,800.00

Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve CLKK)

30/6/21, 12:00pm



OD - M AL

EXPERI - \$1500

5 dgs

P/P

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before and after repairing
- To display damage and repair survey
- Parts prices are on a competitive basis
- Third party survey is on a competitive basis
- No illegal modification
- Supplemental insurance is subject to final approval from insurance company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	317W

Vehicle Details

Vehicle No.:	XE4617J
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2021
Vehicle Make:	MITSUBISHI
Vehicle Model:	FUSO FV70HJD2VDEA
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	470912C0357814
Chassis No.:	FV70HJA00074
Maximum Power Output:	-
Open Market Value:	\$105,948.00
Original Registration Date:	24 Jan 2019
First Registration Date:	24 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$5,298.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	23 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$29,501.00
COE Rebate Amount:	\$22,331.00
Total Rebate Amount:	\$22,331.00

The information contained herein is correct as at 28 Jun 2021

OK