



Industrial Vehicles.  
20,000 Served. And Counting.

Repairer Estimates

**GOLDBELL ENGINEERING PTE LTD**

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: [www.goldbell.com.sg](http://www.goldbell.com.sg)

Co Reg No. 198003963G

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

#### PARTICULARS OF CLAIM

Claim Type: OD (OWN DAMAGE)  
Policy No: DMCVSNW00011352100  
Vehicle Reg. No.: **XE4617J**  
Driver Age/Info: / MALE  
Is Injury Involved? NO  
Insured/Claimant: SAT.S PTE. LTD.  
Driver: KARUPPIAH PERIYAKARUPPAN

Ref. No: XE4617J  
Date of Loss: 24/06/2021  
Driveable?  
Party At Fault: UNKNOWN  
Third Party Involved? YES

Make/Model: MITSUBISHI FUSO SUPER GREAT  
FV, 12.9 D FV51JKM4RDEA (M)  
Vehicle Colour: WHITE  
Engine No: 470912C0357814  
Odometer: 0 KM

Vehicle Reg. Date: 24/01/2019  
Chassis No: FV70HJA00074

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair  
(day) 10

Present Location: **GOLDBELL ENGINEERING PTE LTD (TUAS)**

| <b>COST OF CLAIMS</b>     | <b>Amount</b>    |
|---------------------------|------------------|
| Parts                     | 12,756.85        |
| Miscellaneous Items       | 375.00           |
| Labour                    | 5,800.00         |
| Paintwork Labour          | 0.00             |
| Towing                    | 0.00             |
| <b>Gross Total (\$\$)</b> | <b>18,931.85</b> |
| <b>+ GST 7.00% (\$\$)</b> | <b>1,325.23</b>  |
| <b>Nett Amount (\$\$)</b> | <b>20,257.08</b> |

**This claim is handled by: CHONG KAI LING**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**Source:** (Last Synchronised: 28 Jun 2021)

|       |     |                                                                                          |
|-------|-----|------------------------------------------------------------------------------------------|
| arts: | N/A | MITSUBISHI FUSO SUPER GREAT FV 12.9 D FV51JKM4RDEA (M) (Model not available in database) |
|-------|-----|------------------------------------------------------------------------------------------|

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

| Estimates on Parts |     |                                       | %Disc | %Depr | Amount      |
|--------------------|-----|---------------------------------------|-------|-------|-------------|
| No.                | Qty | Part No. Particulars                  |       |       |             |
| 1                  | 1   | *FORNT PANEL / DD                     | 0.00  | 0.00  | *2,440.13 F |
| 2                  | 1   | *MARK, FUSO / APC                     | 0.00  | 0.00  | *319.10 F   |
| 3                  | 1   | *MARK, 3-DIA / APC                    | 0.00  | 0.00  | *145.54 F   |
| 4                  | 1   | *EMBLEM, SUPER GREAT / APC            | 0.00  | 0.00  | *51.00 F    |
| 5                  | 1   | *GRILLE ASSY, RADIATOR / BR           | 0.00  | 0.00  | *575.39 F   |
| 6                  | 1   | *GRILLE ASSY, FRT UNDER / DD          | 0.00  | 0.00  | *182.40 F   |
| 7                  | 1   | *PANEL, CAB FR CORNER, RH / BR        | 0.00  | 0.00  | *564.77 F   |
| 8                  | 1   | *SEAL, DOOR OPENING RH / ?            | 0.00  | 0.00  | *65.70 F    |
| 9                  | 1   | *SHIELD, C/PNL LOWER LH (BEZEL) / X   | 0.00  | 0.00  | *30.91 F    |
| 10                 | 1   | *SHIELD, C/PNL LOWER RH (BEZEL) / TAI | 0.00  | 0.00  | *52.55 F    |
| 11                 | 1   | *BUMPER, FRT / BT                     | 0.00  | 0.00  | *2,645.41 F |
| 12                 | 1   | *BEZEL, HEADLAMP -RH / BR             | 0.00  | 0.00  | *316.98 F   |
| 13                 | 1   | *BEZEL, HEADLAMP -LH / X              | 0.00  | 0.00  | *316.98 F   |
| 14                 | 1   | *COVER, FR BUMPER -RH / BR            | 0.00  | 0.00  | *125.28 F   |
| 15                 | 1   | *COVER, FR BUMPER -LH / BR            | 0.00  | 0.00  | *125.28 F   |
| 16                 | 1   | *COVER, FR BUMPER CTR / MIS           | 0.00  | 0.00  | *359.47 F   |
| 17                 | 1   | *PROTECTOR, STEP LWR LH / CR6         | 0.00  | 0.00  | *122.08 F   |
| 18                 | 1   | *PROTECTOR, STEP LWR RH / CR6         | 0.00  | 0.00  | *117.91 F   |
| 19                 | 2   | *BRACKET, FR FOG LAMP / (R4) BT       | 0.00  | 0.00  | *15.08 F    |
| 20                 | 1   | *STAY, HEADLAMP -LH / X               | 0.00  | 0.00  | *340.22 F   |
| 21                 | 1   | *STAY, HEADLAMP -RH / BT              | 0.00  | 0.00  | *340.22 F   |
| 22                 | 1   | *PROTECTOR, STEP UPPER / CAT          | 0.00  | 0.00  | *144.43 F   |
| 23                 | 1   | *HEADLAMP ASSY LH / ?                 | 0.00  | 0.00  | *1,004.36 F |
| 24                 | 1   | *HEADLAMP ASSY RH / BR                | 0.00  | 0.00  | *1,004.36 F |
| 25                 | 1   | *LAMP ASSY, FOG, FR LH / X            | 0.00  | 0.00  | *346.40 F   |
| 26                 | 1   | *LAMP ASSY, FOG, FR RH / BR           | 0.00  | 0.00  | *346.40 F   |
| 27                 | 1   | *OIL COOLER / DD                      | 0.00  | 0.00  | *658.50 F   |

**F=Franchise part.**

**Total Parts (S\$)**

**12,756.85**

Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Repairer Estimates

## Estimates on Miscellaneous Items

| No                         | Particulars        | Amount |
|----------------------------|--------------------|--------|
| <u>Miscellaneous Items</u> |                    |        |
| 1                          | COMPANY STICKER    | 350.00 |
| 2                          | FRONT NUMBER PLATE | 25.00  |
| Sub Total (S\$)            |                    | 375.00 |

## Estimates on Labour

| No                      | Particulars                                                                         | Lab.Type | Amount   |
|-------------------------|-------------------------------------------------------------------------------------|----------|----------|
| <u>Labour Items</u>     |                                                                                     |          |          |
| 1                       | TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC | New      | 3,600.00 |
| 2                       | TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK                | New      | 200.00   |
| 3                       | TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC                                        | New      | 2,000.00 |
| Gross Labour Cost (S\$) |                                                                                     |          | 5,800.00 |

Goldbell Engineering Pte Ltd/XE4617J/28/06/2021 18:21. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve CLKK)  
30/6/21, 12:00pm



LKK Auto Co. should hence notify the Repairer of the following:

- To resurvey the vehicle and provide a written report.
- To display the vehicle in a safe and secure place.
- Parts prices to be agreed in writing.
- Third party's liability to be agreed in writing.
- No illegal modifications.
- Supplemental insurance is subject to first approval by the insurer.

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

00- M AL  
EXPERI - \$1500  
5 dgs  
PIP