

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508989
Fax: 6548 8156

Our Job Ref No : 305475206

Date : 29/06/21

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr NAZ

Vehicle Reg No : SH 7251D CTPL

23.06.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC SMQ9739A
- The finalized amount shall be:
 - Spare Parts after List discount
 - Labour Charges
 - Total for Part-By-Part Repair Cost
 - Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost \$1,450.00

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : MS. LOKE YY

Tel : 62148355

Fax : 65468156

Signature : 

Name : NAZ LKK

Date : 9/7/2021

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH 7251D

Make : HYUNDAI

Model : I40

Date: 24/06/2021

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Part Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
1	REAR BUMPER CLIPS			\$22.00
	REAR BUMPER LOWER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT			\$428.40
	REAR BUMPER SPONGE			\$119.50
1	RR BUMPER REINFORCEMENT BRACKET LH RH		\$160.60	\$321.20
1	REAR PANEL			\$526.70
1	REAR PANEL GARNISH			\$57.70
1	BOOTLID			\$2,174.90
1	BOOTLID 'H' EMBLEM			\$63.10
1	BOOTLID CRDI PLATE			\$52.40
1	BOOTLID MOULDING			\$85.00
1	BOOTLID I40 EMBLEM			\$67.90
1	BOOTLID LOCK UPPER			\$114.90
	SUB TOTAL		1,475.50	\$5,252.80
	LESS 25%			\$1,050.56
	DISCOUNTED TOTAL		1,180.40	\$4,202.24
1	BOOTLID COMFORT LOGO & TEL NO. STICKER		-10%	\$30.00
1	BOOTLID ADVERTISEMENT LOGO			\$100.00
1	REAR NUMBER PLATE		-10%	\$25.00
1	REAR BUMPER ADVERTISEMENT LOGO			\$50.00
1	REAR BUMPER REVERSE SENSOR		-10%	\$135.70
1	REAR BUMPER MAT			\$50.00
				\$390.70
	Labour Charge			
	WIRING CHARGE			\$60.00
	PANEL BEATING			\$600.00
	SPRAY PAINTING CHARGE			\$600.00
	REMOVE/REFIX REVERSE SENSOR			\$60.00
	TOTAL LABOUR			\$1,320.00
	ESTIMATE TOTAL		1,790.40	\$5,912.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

NAZ LKK
25/6/2021 12:17 PM
L13
2 PAGES
CHECK ITEM PHOTO
AFTER REPAIR PHOTO