

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

Estimate Repair List

30 June 2021

HHTPClaims21-45

Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Attn: Motor Claims Department

ACCIDENT INVOLVING SMH 2866 J, SJV 7910 T & YM 3847 P ON 24/06/2021 ALONG CTE TOWARDS PIE AT ABOUT 1440 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SMH 2866 J
Vehicle Make : HONDA
Vehicle Model : FREED HYBRID 1.5G AUTO
Vehicle Chassis No : GB71083049
Policy No : 5109921641-02-000206
Date of Accident : 16/06/2021

				Type of Claim: Third Party	
S/N	Quantity	Description	Unit Price S\$	Amount S\$	
1	1	Rear Bumper	828.90	2,100.00	de
2	10	Rear Bumper Clips	5.00	50.00	re
3	2	Rear Bumper Side Retainer (LH/RH)	49.80	99.60	RH re
4	1	Rear Tailgate	1207.90	2,200.00	bf
5	1	Rear Tailgate Lock	187.50	375.00	bf
6	1	Rear Tailgate Logo (Freed)	48.20	110.00	re
7	1	Rear Tailgate Logo (Hybrid)	65.10	150.00	re
8	1	Rear Tailgate Chrome Garnish		640.80	Xnn
9	1	Rear Tailgate Emblem		54.80	re
10	1	Rear Tailgate Weather Strip	194	336.00	fab
11	1	Rear Tailgate Pull Holder		42.00	Xnn
12	1	Rear Tailgate Trimboard		576.00	Xnn
13	1	Rear Tailgate Catch		54.00	Xnn
14	1	Rear Tailgate Glass Moulding	132.20	277.60	re
15	1	Rear End Panel		1,247.40	bf XR
16	2	Rear End Panel (LH/RH)		380.00	Xnn
17	1	Rear End Panel Top Garnish		230.00	re
18	2	Rear End Panel Bracket (LH/RH)		342.40	Xnn
19	1	Rear Floor Panel		9,265.60	
				Less 20%	
					\$ (1,853.12)
					\$ 7,412.48
20	1	PHV Decal		20.00	re
21	1	Sealant		40.00	Xnn
					\$ 1,200.00
					\$ 8,672.48

To dismantle, cut & weld rear end panel & rear floor panel. To change rear bumper, rear tailgate. Knocking all area affected by accident

43090.40

20.

NETT

NETT

8000

OOHRAY RENTAL PTE. LTD.

8 Kaki Bukit Avenue 4, Premier@Kaki Bukit #06-31 Singapore 415875
Tel: (65) 6661 9687 Fax: (65) 6241 6697

ACCIDENT INVOLVING SMH 2866 J, SJV 7910 T & YM 3847 P ON 24/06/2021 ALONG CTE TOWARDS PIE AT ABOUT 1440 HOURS

Estimate Repair List for vehicle SMA 3120 H - Toyota CHR

	Balance B/F	\$ 8,672.48
To perform wire checking	\$	50.00 <i>30</i>
To transfer rear tailgate mechanism to new tailgate	\$	80.00 <i>60.</i>
To dismantle & refit rear windscreen	\$	120.00 ✓
To dismantle & transfer rear tail gate mechanism fitting to new tail gate	\$	<i>Replaced</i> 60.00 <i>Km.</i>
To spray rear end panel, rear floor panel, rear tailgate, rear bumper & all affected area	\$	1,200.00 <i>800</i>
	<i>1810</i>	
		\$ 10,182.48
	7% GST	\$ 712.77
	Total	\$ 10,895.25


Authorised by Claims Dept

Taufik 9741 5749 / 62563561

Supp

- LH tail lamp area ✓ \$1041.613 - WP 30/6/21 @ 1415

- Floor Cushion de ✓ \$184.20 P/P Resurvey before paint

\$422.50

1035.50 *taufik @ 1415.00*

5-6 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3090.40
1035.50
4125.90
20% - 3300.72.

20
1810
\$5130.72 *# 06 days*