

* Able call



NINETEEN AUTOWERKS PTE LTD

436 Tampines Street 43
#07-97 Singapore 520436
Tel: (65) 9674 1991

Email: nineteenautowerks@gmail.com

Date : 29-Jun-21

Registration no. : SLS5162R / Nissan X-Trail 2.0 CVT

DOA : 20-Jun-21

Estimate No. : 19A071_SLS5162R_X-TRAIL

not attached
30/6/21
1/5 \$26,000 / 30 days

S/N	Qty	Item	Amount
-----	-----	------	--------

NETT ITEMS

1	1	Tailgate <i>waged/cra</i>	4380	4820.00	✓
2	1	Tailgate logo <i>neu</i>	59.70	101.20	✓
3	1	Tailgate emblem X-TRAIL <i>neu</i>	101.30	133.70	✓
4	2	Tailgate reflector @ \$316.20 <i>11</i>		632.40	X
5	1	Tailgate inner lock assy <i>11</i>		589.45	X
6	1	Tailgate weatherstrip <i>neu</i>	182.50	391.40	✓
7	2	Tailgate hydraulic damper @ \$212.00 <i>11</i>		424.00	X
8	1	Tailgate trimboard <i>cra</i>	442	374.50	✓
9	1	Tailgate lock sensor <i>11</i>		221.00	X
10	1	Tailgate windscreen moulding <i>neu</i>	101.20	181.00	✓
11	1set	Tailgate windscreen clips <i>neu</i>		45.00	✓
12	1	Rear bumper <i>dis</i>	632.60	1083.00	✓
13	2	Rear bumper side retainer @ \$102.60 <i>n/s cra</i>	45.00	205.20	1pc
14	2	Rear bumper reflector @ \$132.40 <i>n/s cra</i>	63.50	264.80	1pc
15	1	Rear bumper top garnish <i>11</i>		247.00	X
16	1	Rear bumper reinforcement <i>dis</i>	533.00	497.00	✓
17	2	Rear bumper reinforcement bracket @ \$125.70 <i>n/s cra</i>		251.40	1pc
18	1	Rear bumper defuser <i>dis</i>		412.00	✓
19	1	Rear end panel <i>body</i>	501.60	881.50	✓
20	1	Rear end panel top garnish <i>neu</i>	250.00	361.00	✓
21	1	Rear well panel <i>R</i>		1075.00	X
22	1	Exhaust pipe assy <i>Body/neu</i>	177.30	1985.00	✓
23	5	Exhaust mounting @ \$87.70 <i>neu</i>	45x2590	438.50	2pc
24	1	Fuel tank heat shield <i>Body</i>		164.00	✓
25	2	Taillamp @ \$483.00 <i>n/s cra</i>		966.00	1pc
26	2	Taillamp base panel @ \$267.00 <i>n/s cra</i>		534.00	1pc
27	1	Rear fender LH <i>dis</i>	1215.00	1256.00	✓
28	1	Rear fender arch garnish LH <i>dis</i>	541.00	552.20	✓
29	1	Rear fender inner shield LH <i>neu</i>	262.00	266.00	✓
30	1	Rear fender inner trim LH <i>dis</i>	455.20	488.20	✓
31	1	Rear fender glass moulding LH <i>neu</i>		94.00	✓
32	1	Rear fender air vent LH <i>cra</i>	92.50	102.20	✓

126528



NINETEEN AUTOWERKS PTE LTD

436 Tampines Street 43
#07-97 Singapore 520436
Tel: (65) 9674 1991
Email: nineteenautowerks@gmail.com

Date : 29-Jun-21

Registration no. : SLS5162R / Nissan X-Trail 2,0 CVT

DOA : 20-Jun-21

Estimate No. : 19A071_SLS5162R_X-TRAIL

S/N	Qty	Item	Amount
33	1	Rear wheel housing pannel outer LH <i>body</i>	987.00 ✓
34	1	Rear wheel housing pannel inner <i>Side H</i>	1021.00 ✓
35	2	Rear shock absorber @ \$312.00 <i>MS TWI</i>	624.00 <i>1PC</i>
36	2	Rear shock absorber mounting @ \$95.00 <i>11</i>	190.00 X
37	2	Rear lower arm @ \$447.00 <i>NLS surf</i>	894.00 <i>1PC</i>
38	2	Rear upper arm @ \$486.00 <i>NLS surf</i>	972.00 <i>1PC</i>
39	2	Rear knuckle arm @ \$612.00 <i>NLS surf</i>	1224.00 <i>1PC</i>
40	2	Rear knuckle arm bearing @ \$284.00 <i>MS Dged</i>	568.00 <i>1PC</i>
41	1	Rear anti-roll bar <i>Surf</i>	283.00 ✓
42	2	Rear anti-roll bar link @ \$102.00 <i>NLS TWI</i>	204.00 <i>1PC</i>
43	2	Rear driveshaft @ \$1080.00 <i>NLS TWI</i>	2160.00 <i>1PC</i>
44	1	Rear subframe <i>Surf / TWI</i>	1220.00 ✓
45	1	Rear door LH <i>Surf / TWI</i>	1619.00 ✓
46	1	Rear door outer moulding LH <i>11</i>	157.30 X
47	1	Rear door inner lock LH <i>11</i>	387.00 X
48	1	Rear door weatherstrip LH <i>11</i>	213.70 X
49	1	Rear door ouetr garnish lower LH <i>gross</i>	248.00 ✓
50	1	Rocker panel LH <i>2.5</i>	775.00 ✓
51	1	Rocker panel garnish LH <i>2.5</i>	712.00 ✓
52	1	Rear brake caliper LH <i>Damped / TWI</i>	985.00 ✓
53	1	Step panel top plate LH X-TRAIL <i>2.5</i>	447.00 ✓
54	1	Side curtain airbag front LH <i>Actual</i>	1420.00 ✓
55	1	Side curtain airbag front sensor LH <i>Actual</i>	215.00 ✓
56	1	Passenger seat Airbag LH <i>Actual</i>	1420.00 ✓
57	1	Side curtain airbag rear sensor LH <i>Repel</i>	215.00 X
58	1	Side curtain airbag repair kit LH <i>11</i>	286.00 X
59	1	Roof lining <i>wopet</i>	1195.00 ✓
60	1	3rd row safety belt LH <i>Actual / TWI</i>	712.00 ✓
61	1	Front passenger safety belt <i>Actual / TWI</i>	845.00 ✓
62	1	Driver safety belt <i>11</i>	845.00 X
			43081.65

Less 10%

4308.17

38773.49



NINETEEN AUTOWERKS PTE LTD

436 Tampines Street 43
#07-97 Singapore 520436
Tel: (65) 9674 1991
Email: nineteenautowerks@gmail.com

Date : 29-Jun-21

Registration no. : SLS5162R / Nissan X-Trail 2,0 CVT

DOA : 20-Jun-21

Estimate No. : 19A071_SLS5162R_X-TRAIL

S/N	Qty	Item	Amount
-----	-----	------	--------

SPECIAL NETT ITEMS

1	1	Sundries	11	60.00	X
2	1set	Tailgate trimboard clips	11	45.00	X
3	1	Tailgate windscreen primer and cleaner	11	100.00	X
4	1	Tailgate windscreen sealant	11	100.00	40
5	1	Tailgate windscreen inner seal	11	80.00	40
6	1set	Rear bumper clips	11	80.00	35
7	1	Reverse sensor with module	11	300.00	200
8	1set	Rear end panel top garnish clips	11	45.00	X
9	1	Rear end panel sealant	11	100.00	50
10	1set	Rear fender inner shield clips LH	11	45.00	30
11	1set	Rear fender inner garnish clips LH	11	55.00	X
12	1set	Rear fender arch garnish clips LH	11	50.00	X
13	1	Rear fender glass primer and cleaner LH	11	80.00	X
14	1	Rear fender glass sealant LH	11	80.00	40
15	1	Rear rim LH 19 inch	11	1050.00	700
16	1	Rear tyre LH 19 inch	11	280.00	602 = 168
17	1set	Rear door trimboard clips LH	11	45.00	X
18	1	Rear door sealant LH	11	100.00	X
19	1set	Rocker panel garnish clips	11	55.00	50
				2750.00	
Parts Total				41523.49	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudices" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



NINETEEN AUTOWERKS PTE LTD

436 Tampines Street 43
#07-97 Singapore 520436
Tel: (65) 9674 1991
Email: nineteenautowerks@gmail.com

Date : 29-Jun-21

Registration no. : SLS5162R / Nissan X-Trail 2,0 CVT

DOA : 20-Jun-21

Estmate No. : 19A071_SLS5162R_X-TRAIL

S/N	Qty	Item	Amount
-----	-----	------	--------

LABOUR & MISC CHARGES

1	1	Panel beating and strenghten parts on rear accident area.	3800.00	2600
2	1	Check wiring system after disconnect and connect.	80.00	30
3	1	R&R interior upholstery.	100.00	✓
4	1	R&R tailgate component.	100.00	60
5	1	R&R fuel tank.	180.00	60
6	1	R&R LH rear fender glass.	150.00	100
7	1	R&R LH rear tyre and balancing	80.00	X
8	1	R&R rear undercarriage.	300.00	✓
9	1	R&R LH rear door component.	100.00	60
10	1	R&R airbags.	350.00	250
11	1	R&R safety belts.	350.00	
12	1	To diagnos and reset ECU.	300.00	200
13	1	To conduct wheel alignment.	150.00	80
14	1	To apply undercoating for rust roofing.	200.00	100
15	1	Spray painting on accident area.	2800.00	1400
Labour Total			9040.00	

Total Parts and Labour Cost of Repair

50563.49

7-28690.1
104
7-28821.09
S.N-1353.00
h-5340.00
32894.09
202
Page 4 of 4
26011.

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment
Work Order: SLS 5162 R
Date 1.7.21 12:00

Factory Japan 2019.0.1 Copyright (c) 2018 Hunter Engineering : Nissan : X-Trail : T32 Series : T32 2seat

Front : Left

Actual	Before	Specified Range
14'		-1°15' 0°15'
5°05'		4°50' 6°20'
-0°38'		0°00' 0°05'
14°08'		11°00' 12°30'
12°54'		9°45' 12°45'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°33'		-1°15' 0°15'
5°01'		4°50' 6°20'
0°33'		0°00' 0°05'
14°50'		11°00' 12°30'
14°18'		9°45' 12°45'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°41'		
0°04'		
-0°42'		
-0°05'		0°00' 0°09'

Rear : Left

Actual	Before	Specified Range
-3°34'		-1°20' 0°10'
0°58'		0°00' 0°09'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°56'		-1°20' 0°10'
0°02'		0°00' 0°09'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
-2°38'		
1°00'		0°00' 0°19'
0°28'		
0mm		

TECHNEAT PTE LTD
8 Kaki Bukit Avenue 4
(Enter by Gate 2)
#03-38/39/40
Premier@Kaki Bukit
Singapore 415875

Tel : (65) 6384 1996
Fax : (65) 6384 1996
Hotline : (65) 9691 0887
Email: techneatcarcare@yahoo.com.sg
Business Hour : 9am to 7pm(Mon to Sat)

Service - Repair - Rim - Tyres - Battery - Balancing & Alignment
Work Order: SLS5162R
Date: 12.8.21 18:33

Nissan/Datsun : X-Trail : 2013- (T32) : Rest of World : All Wheel Drive Right-hand Drive (5-Passenger)

Front : Left		
Actual	Before	Specified Range
-1°13'	-1°24'	-1°15' 0°15'
5°09'	5°09'	4°55' 6°25'
0°07'	-0°07'	-0°01' 0°08'
13°58'	14°09'	10°50' 12°20'
12°45'	12°46'	9°35' 12°35'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right		
Actual	Before	Specified Range
-0°31'	-0°29'	-1°15' 0°15'
5°04'	5°04'	4°55' 6°25'
0°07'	0°00'	-0°01' 0°08'
15°09'	15°08'	10°50' 12°20'
14°39'	14°39'	9°35' 12°35'

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Front		
Actual	Before	Specified Range
-0°43'	-0°54'	-0°35' 0°35'
0°06'	0°06'	-0°35' 0°35'
-1°11'	-0°59'	
0°14'	-0°07'	-0°02' 0°17'

Rear : Left		
Actual	Before	Specified Range
-0°38'	-0°55'	-1°20' 0°10'
0°09'	0°11'	0°00' 0°09'

Camber
Toe

Rear : Right		
Actual	Before	Specified Range
-1°35'	-1°07'	-1°20' 0°10'
0°05'	-0°02'	0°00' 0°09'

Cross Camber
Total Toe
Thrust Angle

Rear		
Actual	Before	Specified Range
0°57'	0°11'	
0°14'	0°09'	0°00' 0°19'
0°02'	0°06'	