

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG19007570/R1TF3E2-1

Date: 02/08/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28625376MKC

Claimant Vehicle No : WXA312

Insured Vehicle No : YN6514A

Date of Loss: 18/04/2019

Nature of Claim: TP

Claim No: 591779

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WXA312**

Make & Model: BAJAJ PULSAR 200 NS, 200cc

Engine No: JLYCJE53732

Reg. Date: 31/03/2019 (Man. Year: 2018)

Chassis No: PMNNS200NJML03913

Colour: Black

Odometer: 548 km

Engine Capacity: 200 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100/80-17

Rear Tyre Size: 130/70-17

Front Left Side: Nylogrip Zapper 6 mm

Rear Left Side: Nylogrip Zapper 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,695.08	3,060.16	2,634.92	46.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	740.00	1,100.00	59.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,535.08	3,800.16	3,734.92	49.57
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	7,535.08	3,050.00	4,485.08	59.52

INSPECTION

Date of Assignment: 29/04/2019

Date Inspected: 30/04/2019 Inspected At:

38 Woodland #05-16

Repairer: Sincere Lead Automotive

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Aug 2021)	
Parts:	N/A	BAJAJ PULSAR 200 NS 200cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for WXA312)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT MUDGUARD	Damaged	102.00 FL	*102.00 FL
2	1		*FRONT WHEEL RIM LH	Serviceable	575.50 FL	*- FL
3	1		*FRONT FORK ASSY	Damaged	952.00 FL	*510.00 FL
4	2		*FRONT SIDE MIRROR ASSY	Damaged	280.00 FL	*90.00 FL
5	1		*HANDLE BAR	Serviceable	166.00 FL	*- FL
6	1		*SET HANDLE BALANCER	Damaged	170.00 FL	*170.00 FL
7	1		*HANDLE BAR RUBBER RH	Not Necessary	25.00 FL	*- FL
8	1		*SET HANDLE GRIP	Serviceable	100.00 FL	*- FL
9	1		*FRONT METER ASSY	Damaged	599.00 FL	*599.00 FL
10	1		*HEADLAMP	Damaged	385.60 FL	*385.60 FL
11	1		*HEADLAMP BRACKET	Damaged	145.80 FL	*145.80 FL
12	2		*FRONT SIGNAL LAMP	Damaged	150.00 FL	*150.00 FL
13	1		*FRONT BODY COVER ASSY	Damaged	650.00 FL	*650.00 FL
14	1		*FOOT REST RH	Damaged	102.00 FL	*102.00 FL
15	1		*FOOT REST BRACKET RH	Damaged	85.00 FL	*85.00 FL
16	1		*GEAR SHIFT LH	Damaged	135.00 FL	*135.00 FL
17	2		*ENGINE GUARD	Damaged	150.00 FL	*150.00 FL
18	1		*REAR FENDER ASSY	Serviceable	485.00 FL	*- FL
19	1		*REAR WHEEL SHAFT	Damaged	332.00 FL	*98.00 FL
20	2		*REAR SIGNAL LAMP	Serviceable	130.00 FL	*- FL
21	1		*REAR SEAT BAR	Serviceable	241.30 FL	*- FL
22	1		*FRONT NUMBER PLATE	Damaged	40.00 FS	*10.00 FS
23	1		*REAR NUMBER PLATE	Damaged	40.00 FS	*15.00 FS
24	1		*FRONT TYRE	Serviceable	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,291.20	3,397.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	596.12	337.24
Total Parts (\$\$)	5,695.08	3,060.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	750.00	350.00
2	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	20.00	10.00
3	FRONT WHEEL ALIGNMENT CHARGES / BODY CHASSIS ALIGNMENT CHARGES	New	450.00	60.00
4	WIRING AND BULB CHECKING	New	20.00	20.00
5	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	600.00	300.00
Gross Labour Cost (\$)			1,840.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >