

Section A - Accident Details

Registration Number	SHB5533R
Case Reference Number	TAX/06/21/2062
Registration Date	30/11/2020
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4FL
Name of Driver	WONG WAN WAH
Type of Accident	Head To Side
Accident Date and Time	29/6/2021 1:15 PM
Accident Reported Date and Time	29/6/2021 4:25 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24111423
Special Instruction to ARC, if any	TOWED \$40 / LEFT FRONT PORTION /SOMPO
Prepared Date and Time	30/6/2021 10:50 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$600.00
Total Spray Cost	\$2,772.00	\$1,090.00
Total Spare Part Cost	\$32,073.94	\$9,290.21
Total Other Cost	\$776.00	\$130.00
TOTAL COST	\$36,466.94	\$11,110.21 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	7.0	5.0
Prepared / Adjusted By	Tuck Foo Kok	Kenneth Kong (LKK) / Somp
ARC / Surveyor Sign Off Date	06/07/2021 9:51 AM	05/07/2021 4:47 PM
Signature		
Remarks	Total number of repair days = 5 days. SUP = 0 day. part by part repair / before paint photo / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com / for SUP part TP surveyor given 50% only for BATTERY	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2107-0225	Invoice Number	
Quotation Date	19.07.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$845.00	\$600.00
Total Labour	\$845.00	\$600.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$80.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT FENDER LH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY FRONT PILLAR LH	\$180.00	\$80.00
TO RESPRAY APRON PANEL LH	\$180.00	\$80.00
RESPRAY MIRROR COVER LH	\$180.00	\$50.00
TO RESPRAY FRONT DOOR LH	\$378.00	\$200.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$2,772.00	\$1,090.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
TOWING CHARGE	\$56.00	\$50.00
Total Other Costs	\$776.00	\$130.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		87945-47060-A1	COVER, OUTER MIRROR, LH	1.00	\$108.60	100.00	\$0.00	Replace	Repair
		87940-47440	MIRROR ASSY, OUTER REAR VIEW , LH	0.00	\$1,339.30	0.00	\$0.00	Replace	Not Given
		43550-47020	HUB & BEARING ASSY, RH & LH	0.00	\$668.90	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,879.40	0.00	\$0.00	Replace	Not Given

R
X
X
X
X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/07/2021

User ID : PohSuan

	61014-47020	PILLAR, FRONT BODY, LH	1.00	\$350.00	100.00	\$0.00	Replace	Repair	R
	53702-47101	APRON SUB-ASSY, FRONT FENDER, LH	1.00	\$979.40	100.00	\$0.00	Replace	Repair	R
	53852-47041	PAD, FR WHEEL LH	0.00	\$59.60	0.00	\$0.00	Replace	Not Given	X
	53828-47070	PROTECTOR, FR FENDER LH	0.00	\$93.90	0.00	\$0.00	Replace	Check	X
	53876-47060	LINER, FR FENDER, LH	1.00	\$210.30	25.00	\$157.73	Replace	Replace	✓
	75374-47140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$54.60	25.00	\$40.95	Replace	Replace	✓
	53802-47100	FENDER SUB-ASSY, FR, LH	1.00	\$977.80	25.00	\$733.35	Replace	Replace	✓
	55754-47070	WIPER GARNISH SHIELD, COWL WATER, LH	1.00	\$19.60	25.00	\$14.70	Replace	Replace	✓
	55708-47260	WIPER GARNISH LOUVER SUB-ASSY	0.00	\$686.80	0.00	\$0.00	Replace	Check	X
	82123-47060	WIRE, ENGINE, NO.3	0.00	\$310.30	0.00	\$0.00	Replace	Not Given	X
	28800-37130	BATTERY	0.00	\$1,584.90	0.00	\$0.00	Replace	Not Given	X
	53214-47050	SUPPORT, RADIATOR UPPER LH	1.00	\$78.90	25.00	\$59.18	Replace	Replace	✓
	53213-47050	SUPPORT, RADIATOR UPPER RH	0.00	\$78.90	0.00	\$0.00	Replace	Not Given	X
	53028-12050	SUPPORT SUB-ASSY LOWER	0.00	\$409.90	0.00	\$0.00	Replace	Not Given	X
	53203-47901	SUPPORT S/A LH	0.00	\$245.10	0.00	\$0.00	Replace	Not Given	X
	53202-47901	SUPPORT S/A RH	0.00	\$245.10	0.00	\$0.00	Replace	Not Given	X
	53205-47900	SUPPORT S/A UPPER,	0.00	\$377.10	0.00	\$0.00	Replace	Not Given	X
	75536-47020	MOULDING LH	0.00	\$85.50	0.00	\$0.00	Replace	Check	X
	53420-47130	HINGE ASSY, HOOD, LH	0.00	\$58.90	0.00	\$0.00	Replace	Check	X
	53410-47130	HINGE ASSY, HOOD, RH	0.00	\$58.90	0.00	\$0.00	Replace	Not Given	X
	53301-47110	HOOD SUB-ASSY	1.00	\$983.10	100.00	\$0.00	Replace	Repair	R
	51410-47021	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$472.40	0.00	\$0.00	Replace	Not Given	X
	81220-12240	LAMP ASSY, FOG, LH	0.00	\$237.10	0.00	\$0.00	Replace	Not Given	X
	81210-12240	LAMP ASSY, FOG, RH	0.00	\$237.10	0.00	\$0.00	Replace	Not Given	X
	81016-47860	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$3,772.50	0.00	\$0.00	Replace	Not Given	X
	81056-47860	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	0.00	\$3,772.50	0.00	\$0.00	Replace	Check	X
	81145-47890	UNIT, HEADLAMP, RH	0.00	\$2,637.60	0.00	\$0.00	Replace	Not Given	X
	81185-47890	UNIT, HEADLAMP, LH	1.00	\$2,637.60	10.00	\$2,373.84	Replace	Replace	✓
	52021-47110	REINFORCEMENT FRONT UPPER	0.00	\$716.60	0.00	\$0.00	Replace	Not Given	X
	52132-47010	REINFORCEMENT FRONT LOWER	0.00	\$246.10	0.00	\$0.00	Replace	Not Given	X
	52103-47010	EXTENSION SUB-ASSY, LH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given	X
	52102-47020	EXTENSION SUB-ASSY, RH	0.00	\$120.10	0.00	\$0.00	Replace	Not Given	X
	52611-47210	ABSORBER, FR BUMPER	0.00	\$80.20	0.00	\$0.00	Replace	Not Given	X
	52618-47130	ABSORBER, FR BUMPER LOWER	0.00	\$132.70	0.00	\$0.00	Replace	Not Given	X
	52713-47040	MOULDING, FRONT BUMPER SIDE, LH	1.00	\$95.60	25.00	\$71.70	Replace	Replace	✓
	52421-47040	PAD, FRONT BUMPER (NO.2)	2.00	\$36.00	25.00	\$54.00	Replace	Replace	✓
	52421-47030	PAD, FRONT BUMPER (NO.1)	0.00	\$40.70	0.00	\$0.00	Replace	Check	X
	52161-16010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.50	25.00	\$33.75	Replace	Replace	✓
	51451-12120	COVER ASSY, ENGINE	0.00	\$241.90	0.00	\$0.00	Replace	Not Given	X
	53111-47140	GRILLE, SUB -ASSY, 2	0.00	\$160.50	0.00	\$0.00	Replace	Not Given	X
	53101-47100	GRILLE SUB-ASSY	0.00	\$422.50	0.00	\$0.00	Replace	Not Given	X
	53112-47310	GRILLE, RADIATOR	0.00	\$178.60	0.00	\$0.00	Replace	Not Given	X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/07/2021

User ID PohSuan

		53395-47060	SEAL, HOOD TO FR END	0.00	\$85.50	0.00	\$0.00	Replace	Not Given	X
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace	√
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace	√
		45047-49195	END SET, TIE ROD, LH	0.00	\$186.70	0.00	\$0.00	Replace	Not Given	X
		43212-47040	KNUCKLE, STEERING, LH	0.00	\$663.40	0.00	\$0.00	Replace	Not Given	X
		69210-47051-A1	DOOR OUTER HANDLE FRONT, LH	1.00	\$390.60	100.00	\$0.00	Replace	Repair	R
		60118-47020	COVER SUB-ASSY, FRONT PILLAR, UPR LH	1.00	\$100.40	25.00	\$75.30	Replace	Replace	√
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
		68740-12120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$110.60	0.00	\$0.00	Replace	Check	X
		68720-12151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$97.50	0.00	\$0.00	Replace	Check	X
		68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$183.80	0.00	\$0.00	Replace	Not Given	X
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,300.70	25.00	\$975.53	Replace	Replace	√
		75860-47900	MOULDING ASSY, BODY ROCKER PANEL, LH	0.00	\$594.80	0.00	\$0.00	Replace	Not Given	X
Total					\$32,891.84		\$5,102.51			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		28800-37130	BATTERY	1.00	\$1,584.90	50.00	\$792.45	Replace	Replace
		81056-47860	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$3,772.50	10.00	\$3,395.25	Replace	Replace
Total					5,357.40		4,187.70		

√ dented
√ cracked

9,290.20
+ 600.00
+ 1220.00

11,110.20