

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/07/2021

User ID PohSuan

		53395-47060	SEAL, HOOD TO FR END	0.00	\$85.50	0.00	\$0.00	Replace	Not Given	X
		52116-47050	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace	√
		52115-47050	SUPPORT, FR BUMPER RH	0.00	\$80.10	0.00	\$0.00	Replace	Not Given	X
		52119-47980	COVER, FR BUMPER	1.00	\$521.00	25.00	\$390.75	Replace	Replace	√
		45047-49195	END SET, TIE ROD, LH	0.00	\$186.70	0.00	\$0.00	Replace	Not Given	X
		43212-47040	KNUCKLE, STEERING, LH	0.00	\$663.40	0.00	\$0.00	Replace	Not Given	X
		69210-47051-A1	DOOR OUTER HANDLE FRONT, LH	1.00	\$390.60	100.00	\$0.00	Replace	Repair	R
		60118-47020	COVER SUB-ASSY, FRONT PILLAR, UPR LH	1.00	\$100.40	25.00	\$75.30	Replace	Replace	√
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace	√
		68740-12120	HINGE ASSY, FRONT DOOR, LOWER LH	0.00	\$110.60	0.00	\$0.00	Replace	Check	X
		68720-12151	HINGE ASSY, FRONT DOOR, UPPER LH	0.00	\$97.50	0.00	\$0.00	Replace	Check	X
		68610-47040	CHECK ASSY, FRONT DOOR	0.00	\$183.80	0.00	\$0.00	Replace	Not Given	X
		67002-47163	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,300.70	25.00	\$975.53	Replace	Replace	√
		75860-47900	MOULDING ASSY, BODY ROCKER PANEL, LH	0.00	\$594.80	0.00	\$0.00	Replace	Not Given	X
Total					\$32,891.84		\$5,102.51			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		28800-37130	BATTERY	1.00	\$1,584.90	50.00	\$792.45	Replace	Replace
		81056-47860	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	1.00	\$3,772.50	10.00	\$3,395.25	Replace	Replace
Total					5,357.40		4,187.70		

√ dented
√ cracked

9,290.20
+ 600.00
+ 1220.00

11,110.20