



Rico 60 Auto Services Pte Ltd

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: claims@rico60.com

Tel: 6286 6060 Fax : 6286 7060

Xiao Chen,

JM6BN22A8H0137791

RICO Office Use Only

Parts -%20	
SN	
Labour	
Total	
Lump Sum	
ERV	20K

TO: China Taiping Insurance

Vehicle No : SLK 5616 R

Make & Model : MAZDA 3

DATE: 29/6/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER <i>Del d</i>	1	\$ 1,089.00	\$ ✓ 1,089.00
2	FRONT BUMPER TOP PAD	1	\$ 458.00	\$ ✕ 458.00
3	FRONT BUMPER TOP PAD BASE <i>new</i>	1	\$ 286.00	\$ ✕ 286.00
4	FRONT BUMPER TOWING COVER	1	\$ 45.60	\$ ✕ 45.60
5	FRONT BUMPER SIDE RETAINER <i>RH Del d</i>	2	\$ 98.50	\$ 98.50 197.00
6	FRONT BUMPER LOWER ABSORBER <i>new Del d</i>	1	\$ 308.50	\$ ✓ 308.50
7	FRONT BUMPER LOWER SUPPORT BEAN RH <i>new</i>	1	\$ 215.00	\$ ✕ 215.00
8	FRONT BUMPER LOWER SIDE SUPPORT RH <i>new</i>	1	\$ 192.30	\$ ✕ 192.30
9	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 750.10	\$ ✕ 750.10
10	FRONT BUMPER REINFORCEMENT GARNISH <i>new</i>	1	\$ 285.60	\$ ✕ 285.60
11	FRONT BUMPER UNDER COVER <i>new torn</i>	1	\$ 189.20	\$ ✓ 189.20
12	FRONT FOG LAMP RH <i>crack d</i>	1	\$ 321.00	\$ ✓ 321.00
13	FRONT FOG LAMP GARNISH RH <i>Del d</i>	1	\$ 277.80	\$ (277.80) 68
14	WIPER WASHER TANK <i>new Del d</i>	1	\$ 169.30	\$ ✕ 169.30
15	WIPER WASHER TANK MOTOR <i>new</i>	1	\$ 277.40	\$ ✕ 277.40
16	HEAD LAMP RH <i>at</i>	1	\$ 3,289.00	\$ (3,289.00) ✓
17	HEAD LAMP LOWER BRACKET RH <i>new</i>	1	\$ 157.60	\$ ✕ 157.60
18	FRONT GRILLE <i>new crack d</i>	1	\$ 970.10	\$ ✕ 970.10 450
19	FRONT GRILLE CHROME MOULDING RH <i>crack d</i>	1	\$ 276.40	\$ (276.40) 198
20	FRONT GRILLE EMBLEM <i>new</i>	1	\$ 104.90	\$ ✕ 104.90
21	FRONT GRILLE TOP GARNISH	1	\$ 320.50	\$ ✕ 320.50
22	FRONT GRILLE SUPPORT BRACKET RH <i>new</i>	1	\$ 154.00	\$ ✓ 154.00
23	FRONT GRILLE SUPPORT BRACKET PIN <i>new</i>	2	\$ 89.00	\$ 178.00 89
24	FRONT SUPPORT TOP PANEL RH <i>new</i>	1	\$ 448.00	\$ ✕ 448.00
25	FRONT SUPPORT PANEL <i>new</i>	1	\$ 886.90	\$ ✕ 886.90
26	RADIATOR AIR GUIDE	1	\$ 135.30	\$ ✕ 135.30

27	A/C CONDENSER	<i>Not</i>	1	\$	976.30	\$ X 976.30
28	RADIATOR	<i>Not</i>	1	\$	1,527.50	\$ X 1,527.50
29	FRONT FENDER RH	<i>Dented</i>	1	\$	665.00	\$ ✓ 665.00
30	FRONT FENDER TOP GARNISH RH	<i>Not</i>	1	\$	154.00	\$ X 154.00
31	FRONT FENDER INNER SHIELD RH	<i>Not</i> Not <i>torn</i>	1	\$	221.10	\$ X 221.10
32	FRONT ABSORBER RH	<i>Not</i>	1	\$	556.70	\$ X 556.70
33	FRONT LOWER ARM RH	<i>Not</i>	1	\$	457.60	\$ X 457.60
34	FRONT KNUCKLE ARM RH	<i>Not</i>	1	\$	650.90	\$ X 650.90
35	FRONT WHEEL BEARING RH	<i>Not</i>	1	\$	415.90	\$ X 415.90

6752.70

5402.16

Subtotal : \$ 17,607.50

Less 20% \$ 3,521.50

Parts Total : \$ 14,086.00

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT BUMPER CLIPS SET <i>Not</i>	1	\$ 50.00	\$ 30 50.00
2	FRONT BUMPER TOP PAD RIVET <i>Not</i>	1	\$ 70.00	\$ + 70.00
3	FRONT BUMPER UNDER COVER CLIP <i>Not</i>	1	\$ 50.00	\$ X 50.00
4	FRONT GRILLE CLIP <i>Not</i>	1	\$ 50.00	\$ 20 50.00
5	FRONT FENDER TOP GARNISH CLIP <i>Not</i>	1	\$ 40.00	\$ X 40.00
6	FRONT FENDER INNER SHIELD CLIP SET <i>Not</i>	1	\$ 40.00	\$ 30 40.00
7	FRONT SUPPORT PANEL SEALANT <i>Not</i>	1	\$ 80.00	\$ + 80.00
8	RADIATOR COOLANT <i>Not</i>	1	\$ 70.00	\$ X 70.00
9	FRONT TYRE LH <i>Not</i>	1	\$ 400.00	\$ X 400.00
10	WHEEL RIM <i>Not</i>	1	\$ 400.00	\$ 150 400.00
				\$ 850.00

LABOUR

PRICE

PANEL BEATING, REMOVAL AND REPLACING PARTS	500	\$ 1,300.00
TO SPRAY PAINT AFFECTED AREA	400	\$ 1,500.00
TO PERFORM LIGHTING & WIRING CHECK	30	\$ 60 0.00
TO APPLY ANTI-RUST & TUFF KOTE		\$ X 250.00
REMOVE AND INSTALL FRONT UNDER CARRIAGE		\$ X 600.00
TO CHECK FOUR WHEEL ALIGMENT	1110	\$ 80 100.00
REMOVE AND INSTALL RADIATOR ASSY. PERFORMED RADIATOR PRESSURE TEST		\$ X 150.00
REMOVE AND INSTALL CONDENSER AND REFILL AIRCON GAS		\$ X 180.00

LABOUR TOTAL \$ 4,140.00

Total Parts Cost \$ 14,936.00

Total Labour Cost \$ 4,140.00

Total Repair Cost \$ 19,076.00

APPROVED DETAILS

NO. OF WORKING DAYS

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY

SURVEYED BY

CONTACT NUMBER

FAX NUMBER

Adrian Lj

1/s 30/06/21.

65 Days.

total: 6742.16.

1/s: 53K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: