

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: EP3028/06/21 Your Ref: _____ Date: 18th JUNE 2021

MR SEET TEE MENG, AUGUSTINE
Blk 688C, #17-122
Choa Chu Kang Crescent
Singapore 683688

Estimate cost of repair to HONDA FREED 1.5L (A) CVD 8/Wgn - SME 9099 B

1 pc tail gate door	DD	1204-30	\$ 1,358.00	
1 set rear windscreen inner seal	ner		74.10	
1 pc rear windscreen inner dam rubber	ner		54.00	
1 pc rear windscreen sealant	ner		60.00	40 S/N
1 pc tail gate door 'FREED' emblems	ner		69.30	
1 pc tail gate door 'i-VTEC' emblems	ner		36.60	
1 pc tail gate door 'M' logo	ner		38.20	
1 pc tail gate door n/s reflector (Hybrid Tyre)	11		429.50	X
1 pc tail gate door weatherstrip	11		183.30	X
20 pcs tail gate door trim board clips	ner	59	118.00	
1 pc n/s tail lamp assy	great		750.80	
2 pcs n/s tail lamp clips stopper	ner		11.80	
1 pc rear bumper	D/S	778-40	809.80	
10 pcs rear bumper clips	ner		39.00	
1 pc rear bumper n/s side retainer	ner		28.60	
1 pc rear bumper n/s top retainer	ner		31.20	
1 pc rear bumper n/s side bracket clips	ner		6.80	
1 pc rear bumper damper	11		68.30	X
1 set rear bumper reflector	320		136.60	
1 set rear bumper side spoiler	Dyed		86.00	
1 pc n/s tail lamp panel	R		158.30	X
1 pc rear n/s fender	R		1,209.10	X
10 pcs rear n/s fender inner garnish clips	ner		59.00	
1 set reverse sensor	8u		287.90	X
			\$ 6,405.80	
Less 20%			\$ 1,221.16	
			\$ 4,884.64	

To wiring check up for affected wiring system.	50.00	30
To remove & refix rear windscreen glass & necessary parts.	150.00	120
To remove & refix tail gate door top spoiler & repump sealant.	150.00	50
To transfer tail gate door inner lock, trim board, wiper motor, garnish, shock absorber, hinge, third brake light, garnish & necessary parts into new tail gate door.	200.00	120
To remove & refix carpet, floor mat, garnish, floor board cover, tool set, spare tyre & necessary parts.	120.00	60
To respray Tuff-Kote on all affected accident parts.	90.00	X
		\$ 5,644.64

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3028/06/21

Your Ref: _____

Date: 18th June 2021

MR SEET TZE MENG, AUGUSTINE.,

Balance B/F..... \$ 5,644.64

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s fender, tail lamp panel, rear end panel & necessary parts, to weld, renew & align above parts.

1,300.00 600

No putty & respray Pearl White colour on all affected accident parts.

1,630.00 850

\$ 8,594.64

Dollars : Eight Thousand Five Hundred Ninety Four And Cents
Sixty Four Only.

1830

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: