# Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Jenny Lew Date: 16 Jul 2021

# **Preliminary Advice**

Insured Vehicle No : YP2003Z

 TP Vehicle No
 : GBC2881X
 Accident Date
 : 28/06/2021

 Make
 : NISSAN NV200
 Assignment Date
 : 30/06/2021

Date of Inspection : 01/07/2021 Est. Duration of Repair : 10

Inspection At : ETHOZ GROUP LTD - TAMPINES (HQ)

22 TAMPINES STREET 92 SINGAPORE 528876

## Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,166.64
Revised Amount	:S\$	7,692.17
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,692.17
Lump Sum Repair	:S\$	4,500.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
		let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : Please note that the preliminary advice amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.