

**Automotive Repair Centre Pte Ltd**CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C**Estimate**

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2106-128

DATE : 30-Jun-2021

POLICY NO. : AVIVA 10875339

VEHICLE REG. NO. : SLT7310L

VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 480.00	\$ 480.00
2	Rear Bumper Lower Cover	1	\$ 280.00	\$ 280.00
3	Rear Bumper Clips	10	\$ 3.00	\$ 30.00
4	Rear Bumper Retainer RH	1	\$ 50.00	\$ 50.00
5	Rear Bumper Guard RH	1	\$ 20.00	\$ 20.00
6	Rear Bumper Reflector RH	1	\$ 50.00	\$ 50.00
7	Rear Fender RH	1	\$ 1,980.00	\$ 1,980.00
8	Rear Fender Front Shield RH	1	\$ 70.00	\$ 70.00
9	Rear Fender Rear Shield RH	1	\$ 60.00	\$ 60.00
10	Rear Fender Clip	10	\$ 3.00	\$ 30.00
11	Rear Tail lamp Panel Assy	1	\$ 200.00	\$ 200.00
12	Tail lamp RH	1	\$ 400.00	\$ 400.00
13	Tail lamp RH Special Clip	1	\$ 10.00	\$ 10.00
14	Boot lamp RH	1	\$ 300.00	\$ 300.00
15	Front Door Outer Chrome Handle RH	1	\$ 180.00	\$ 180.00
16	Rear Windscreen	1	\$ 550.00	\$ 550.00
17	Rear Windscreen Molding	1	\$ 100.00	\$ 100.00
18	Rear Door RH	1	\$ 1,950.00	\$ 1,950.00
19	Rear Door Outer Chrome Handle RH	1	\$ 70.00	\$ 70.00
20	Rear Door Outer Chrome Handle Small Cover RH	1	\$ 40.00	\$ 40.00
21	Rear Door Chrome Handle Pad RH	1	\$ 10.00	\$ 10.00
22	Rear Door Chrome Handle Small Cover Pad RH	1	\$ 10.00	\$ 10.00
23	Rear Door Window Regulator RH	1	\$ 250.00	\$ 250.00
24	Rear Door Window Regulator Motor RH	1	\$ 200.00	\$ 200.00
25	Rear Door Channel Assy RH	1	\$ 80.00	\$ 80.00
26	Rear Door Lock	1	\$ 200.00	\$ 200.00
27	Rear Door Lock Latch	1	\$ 30.00	\$ 30.00
28	Rear Door Out Chrome Weatherstrip RH	1	\$ 90.00	\$ 90.00
29	Rear Door Inner Weatherstrip RH	1	\$ 110.00	\$ 110.00
30	Rear Door Inner Trim Assy RH	1	\$ 500.00	\$ 500.00
31	Rear Upper Door Moulding (Black Sticker) RH	1	\$ 20.00	\$ 20.00
32	Rear Front Door Moulding (Black Sticker) RH	1	\$ 20.00	\$ 20.00

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2106-128

DATE : 30-Jun-2021

POLICY NO. : AVIVA 10875339

VEHICLE REG. NO. : SLT7310L

VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
 3 Anson Road, #15-00 Springleaf Tower
 Singapore 079909
 Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
33	Side Mirror with Signal Assy RH	1	\$ 680.00	\$ 680.00
34	Hyundai Rim 15R	1	\$ 680.00	\$ 680.00
35	Rear Absorber RH	1	\$ 250.00	\$ 250.00
36	Rear Wheel Bearing RH	1	\$ 480.00	\$ 480.00
Total Spare Parts				\$ 10,460.00
	<u>SPECIAL NETT</u>			
37	Rear Windscreen Sealant	1	\$ 40.00	\$ 40.00
38	Rear Windscreen Solar Film	1	\$ 200.00	\$ 200.00
39	Rear Tyre R15	1	\$ 200.00	\$ 200.00
Total Special Nett				\$ 440.00
	<u>LABOUR</u>			
40	Spray Painting Whole Right Side, Front and Rear Bumpers	1	\$ 1,200.00	\$ 1,200.00
41	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,000.00	\$ 1,000.00
42	Remove & Refit Rear Undercarriage	1	\$ 250.00	\$ 250.00
43	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 80.00
44	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
45	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 50.00	\$ 50.00
46	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 100.00
47	Computerized Wheel Alignment	1	\$ 70.00	\$ 70.00
48	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Total Labour	\$ 2,900.00
Amount Before Excess	\$ 13,800.00
Add GST @ 7%	966.00
Total Amount Payable	\$ 14,766.00