

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2106-128
DATE : 30-Jun-2021
POLICY NO. : AVIVA 10875339
VEHICLE REG. NO. : SLT7310L
VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

RASUL - Hp 90010068
9 days / L15 - 02/07/21 @ 1145
Rehy after repair

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	SPARE PARTS			
1	Rear Bumper <i>de /</i>	1	\$ 480.00	\$ 480.00
2	Rear Bumper Lower Cover <i>X</i>	1	\$ 280.00	\$ 280.00
3	Rear Bumper Clips <i>ne /</i>	10	\$ 3.00	\$ 30.00
4	Rear Bumper Retainer RH <i>ca /</i>	1	\$ 50.00	\$ 50.00
5	Rear Bumper Guard RH <i>at /</i>	1	\$ 20.00	\$ 20.00
6	Rear Bumper Reflector RH <i>X</i>	1	\$ 50.00	\$ 50.00
7	Rear Fender RH <i>bu /</i>	1	\$ 1,980.00	\$ 1,980.00
8	Rear Fender Front Shield RH <i>de /</i>	1	\$ 70.00	\$ 70.00
9	Rear Fender Rear Shield RH <i>de /</i>	1	\$ 60.00	\$ 60.00
10	Rear Fender Clip <i>ne /</i>	10	\$ 3.00	\$ 30.00
11	Rear Tail lamp Panel Assy <i>bro /</i>	1	\$ 200.00	\$ 200.00
12	Tail lamp RH <i>bro /</i>	1	\$ 400.00	\$ 400.00
13	Tail lamp RH Special Clip <i>ne /</i>	1	\$ 10.00	\$ 10.00
14	Boot lamp RH <i>ca /</i>	1	\$ 300.00	\$ 300.00
15	Front Door Outer Chrome Handle RH <i>repair</i>	1	\$ 180.00	\$ 180.00
16	Rear Windscreen <i>bro /</i>	1	\$ 550.00	\$ 550.00
17	Rear Windscreen Molding <i>ne /</i>	1	\$ 100.00	\$ 100.00
18	Rear Door RH <i>turn /</i>	1	\$ 1,950.00	\$ 1,950.00
19	Rear Door Outer Chrome Handle RH <i>mis /</i>	1	\$ 70.00	\$ 70.00
20	Rear Door Outer Chrome Handle Small Cover RH <i>ca sca /</i>	1	\$ 40.00	\$ 40.00
21	Rear Door Chrome Handle Pad RH <i>ne /</i>	1	\$ 10.00	\$ 10.00
22	Rear Door Chrome Handle Small Cover Pad RH <i>ne /</i>	1	\$ 10.00	\$ 10.00
23	Rear Door Window Regulator RH <i>?</i>	1	\$ 250.00	\$ 250.00
24	Rear Door Window Regulator Motor RH <i>?</i>	1	\$ 200.00	\$ 200.00
25	Rear Door Channel Assy RH <i>?</i>	1	\$ 80.00	\$ 80.00
26	Rear Door Lock <i>?</i>	1	\$ 200.00	\$ 200.00
27	Rear Door Lock Latch <i>?</i>	1	\$ 30.00	\$ 30.00
28	Rear Door Out Chrome Weatherstrip RH <i>ro de /</i>	1	\$ 90.00	\$ 90.00
29	Rear Door Inner Weatherstrip RH <i>ne /</i>	1	\$ 110.00	\$ 110.00
30	Rear Door Inner Trim Assy RH <i>?</i>	1	\$ 500.00	\$ 500.00
31	Rear Upper Door Moulding (Black Sticker) RH <i>ne /</i>	1	\$ 20.00	\$ 20.00
32	Rear Front Door Moulding (Black Sticker) RH <i>ne /</i>	1	\$ 20.00	\$ 20.00

38 Woodlands Industrial Park E1
#05-18, Singapore 757700
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2106-128
DATE : 30-Jun-2021
POLICY NO. : AVIVA 10875339
VEHICLE REG. NO. : SLT7310L
VEHICLE MAKE : HYUNDAI ELANTRA AD 1.6 GLS AT

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
33	Side Mirror with Signal Assy RH <i>cut</i>	1	\$ 680.00	\$ 680.00
34	Hyundai Rim 15R <i>cut / s/n</i>	1	\$ 680.00	\$ 300 680.00
35	Rear Absorber RH	1	\$ 250.00	\$ 250.00
36	Rear Wheel Bearing RH	1	\$ 480.00	\$ 480.00
Total Spare Parts				\$ 10,460.00
SPECIAL NETT				
37	Rear Windscreen Sealant <i>re</i>	1	\$ 40.00	\$ 40.00
38	Rear Windscreen Solar Film <i>re</i>	1	\$ 200.00	\$ 150 200.00
39	Rear Tyre R15 <i>X</i>	1	\$ 200.00	\$ X 200.00
Total Special Nett				\$ 440.00
LABOUR				
40	Spray Painting Whole Right Side, Front and Rear Bumpers	1	\$ 1,200.00	\$ 900 1,200.00
41	Replace Rear including Fitting, Cut, Weld and Re-align	1	\$ 1,000.00	\$ 800 1,000.00
42	Remove & Refit Rear Undercarriage <i>photo?</i>	1	\$ 250.00	\$ 150 250.00
43	Transfer Door Fitting and Window Mechanism to New Door	1	\$ 80.00	\$ 60 80.00
44	Remove and Refit Rear Windscreen	1	\$ 120.00	\$ 120.00
45	Remove and Refit Rear Bumper Reverse Sensor	1	\$ 50.00	\$ 50.00
46	Apply Rust Proofing on Replaced/Repaired Panel	1	\$ 100.00	\$ 60 100.00
47	Computerized Wheel Alignment <i>(copy)</i>	1	\$ 70.00	\$ 70.00
48	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,900.00
Amount Before Excess				\$ 13,800.00
Add GST @ 7%				966.00
Total Amount Payable				\$ 14,766.00

Estimate prepared by: Raymond Tan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: