

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G

SHB9618D

AAD2106-

*Not Authorised**Running B4 paint**62475.33*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHB9618D

JTDKB3FU503082109

TOYOTA

PRIUS

27/06/2021

29 JUN 2021

27/06/2019

PART**LIST**

1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	R	1,300.70	
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	S	193.50	
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	S	390.60	
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R	110.60	
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R	97.50	
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	R	13.30	
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	R	43.50	
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	R	26.30	
1	MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$	S	926.00	
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	S	238.30	
1	WEATHERSTRIP, FRONT DOOR, RH	\$	S	231.30	
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	R	1,294.90	
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	S	97.40	
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	S	193.50	
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	R	87.10	
1	HINGE ASSY, REAR DOOR, UPPER LH	\$	R	98.90	
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	R	21.90	
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	R	34.90	
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	R	15.40	
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	S	926.00	
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	S	206.70	
1	WEATHERSTRIP, REAR DOOR, RH	\$	S	180.10	
1	PANEL SUB-ASSY, QUARTER, RH	\$	R	871.50	
1	LINER, REAR WHEEL HOUSE, RH	\$	S	139.80	
1	COVER, REAR BUMPER	\$	R	442.60	
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	R	594.80	
TOTAL		\$		8,777.10	
		\$		2,194.28	
					25%

*62475.33**1220**1092.73*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No.: 6287 6666 Fax No.: 6257 1330
CO./GST Reg. No. 201019626G
SHB9618D

AAD2106-

Special Nett			
1	FENDER LINER CLIP	nn	75.00 X
1	FENDER CLIP	nn	75.00 X
1	FRT BUMPER CLIP	nn	65.00 X
1	REAR BUMPER CLIP	nn	65.00 X
1	END PANEL INNER TRIM CLIP	nn	60.00 X
1	CLIP(FOR FRONT DOOR TRIM BOARD)	nn	65.00 X
1	CLIP(FOR REAR DOOR TRIM BOARD)	nn	65.00 X
1	REAR DOOR STICKER "6555-3333"	nn	100.00 6050
1	FRT DOOR STICKER 'TRANSCAB'	nn	100.00 6050
1	TYRE	nn	350.00 X
1	RIM	nn	1,879.40 X
2	WINDSCREEN SEALANT	nn	150.00 X
1	WINDSCREEN MOULDING	nn	200.00 X
1	WINDSCREEN INNER SPONGE SEAL	nn	130.00 X
TOTAL			3,379.40

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	30%
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	88%
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20%
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	400%
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

TOTAL

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111
Tel No. : 6287 6666 Fax No. : 6257 1330
CO./GST Reg. No. 201019626G
SHB9618D

AAD2106-

To transfer of rear fender panel fittings, attachment and perform
water seepage test.

\$	170.00	X
TOTAL	\$	4,790.00

Over All Total	\$	14,752.23
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days 10 Days
3 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: