

Trans-cab Auto Services Pte Ltd

AAD2106-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9618D

Not Withheld
Running B4 paint

Vehicle No.:

SHB9618D

Chassis No.:

JTDKB3FU503082109

Vehicle Make:

TOYOTA

Vehicle Model:

PRIUS

Date of Accident :

27/06/2021

Third Party Insurer :

Date of Registration:

27/06/2019

PART	LIST
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ R 1,300.70
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ S 193.50
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ S 390.60
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ R 110.60
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ R 97.50
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ R 13.30
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ R 43.50
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ R 26.30
1 MOTOR ASSY, POWER WINDOW REGULATOR, FRT RH	\$ S 926.00
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ S 238.30
1 WEATHERSTRIP, FRONT DOOR, RH	\$ S 231.30
1 PANEL SUB-ASSY, REAR DOOR, RH	\$ R 1,294.90
1 HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$ S 97.40
1 FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$ S 193.50
1 HINGE ASSY, REAR DOOR, LOWER RH	\$ R 87.10
1 HINGE ASSY, REAR DOOR, UPPER LH	\$ R 98.90
1 TAPE, BLACK OUT, NO.1 REAR RH	\$ R 21.90
1 TAPE, BLACK OUT, NO.2 REAR RH	\$ R 34.90
1 TAPE, BLACK OUT, NO.3 REAR RH	\$ R 15.40
1 MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$ S 926.00
1 REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$ S 206.70
1 WEATHERSTRIP, REAR DOOR, RH	\$ S 180.10
1 PANEL SUB-ASSY, QUARTER, RH	\$ R 871.50
1 LINER, REAR WHEEL HOUSE, RH	\$ S 139.80
1 COVER, REAR BUMPER	\$ R 442.60
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$ R 594.80
TOTAL	\$ 8,777.10
25%	\$ 2,194.28

Trans-cab Auto Services Pte Ltd**AAD2106-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9618D

\$	6,582.83
----	-----------------

Special Nett

- 1 FENDER LINER CLIP
- 1 FENDER CLIP
- 1 FRT BUMPER CLIP
- 1 REAR BUMPER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 CLIP(FOR FRONT DOOR TRIM BOARD)
- 1 CLIP(FOR REAR DOOR TRIM BOARD)
- 1 REAR DOOR STICKER "6555-3333"
- 1 FRT DOOR STICKER 'TRANSCAB'
- 1 TYRE
- 1 RIM
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

	\$	nn	75.00	X
	\$	nn	75.00	X
	\$	nn	65.00	X
	\$	nn	65.00	X
	\$	nn	60.00	X
	\$	nn	65.00	X
	\$	nn	65.00	X
	\$	nn	100.00	605m
	\$	nn	100.00	605m
	\$	nn	350.00	X
	\$	nn	1,879.40	X
	\$	nn	150.00	X
	\$	nn	200.00	X
	\$	nn	130.00	X
TOTAL	\$		3,379.40	
TOTAL PARTS	\$		9,962.23	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	301
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	8801
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	4001
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHB9618D

AAD2106-

To transfer of rear fender panel fittings, attachment and perform water seepage test.

\$ 170.00 X
TOTAL \$ 4,790.00

Over All Total \$ 14,752.23

(PART-BY-PART) Repair Days

10 Days

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: