

CITYCAB PTE LTD

REPAIR ESTIMATE*

24.06.21

VEHICLE NO SHB3693A

CHIANG/NTUC

MAKE :

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
			\$459.40
1	REAR BUMPER		\$55.80
1	REAR BUMPER SIDE BRACKET LH/RH		\$394.80
1	REAR BUMPER REINFORCEMENT		\$276.20
1	REAR BUMPER STAY LH/RH		\$22.00
10	REAR BUMPER CLIPS		\$451.25
1	REAR BUMPER CENTRE MOULDING		\$170.60
2	REAR NUMBER PLATE LAMP		\$201.10
1	REAR BUMPER FOG LAMP		
	SUB TOTAL		\$2,031.15
	20.00%		\$406.23
	DISCOUNTED TOTAL		\$1,624.92
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$235.00
	Labour Charge		
	Panel Beating		\$600.00
	Spray Painting Charge		\$500.00
	Tuff Kote		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,220.00
	ESTIMATE TOTAL		\$3,079.92
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

NA2 LKK
25/6/2021 1655
P/R
2 DAY)
(CHECK ITEM PHOTO)
AFTER REPAIR PHOTO)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary cost(s) if not surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: